

MX-Sensor_V6.12 Function List For KR Market (Note:For reference only)

NOTES:

● This function is supported. ○ This function is not supported. Mark explaining (Red:New, Yellow: Modify)

Special Declaration:

- 1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.
- 2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Abarth	500C	2010/01-2019/06	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Aston Martin	DB11	2016/01-2020/06	433Mhz	VH500	○	●	○	A	433Mhz	Schrader	●	●
Aston Martin	DBS	2007/09-2012/08	433Mhz	AM803	●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	DBS Superleggera	2018/01-2020/06	433Mhz	VH500	○	●	○	A	433Mhz	Schrader	●	●
Aston Martin	Rapide	2010/01-2020/06	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	Rapide S	2010/01-2019/12	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	Vanquish	2010/01-2019/12	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	Vantage	2010/01-2019/12	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	A4	2012/01-2020/06	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
아우디	A4	2008/08-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A5	2006/12-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A6	2017/07-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A6	2002/01-2017/06	Indirect		○	○	○	S	N/A	N/A	Indirect	●
아우디	A6	2005/01-2012/12	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	A6	2018/01-2019/12	433MHz	4G	●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	A7	2012/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A7	2010/09-2020/06	433MHz 5Q0907275	4G	●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	A8	2010/11-2016/12	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	A8	2017/01-2019/12	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	A8	2009/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	Q5	2008/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	Q5	2018/01-2019/12	433MHz	8R	●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	Q7	2005/09-2014/12	433MHz	4L/AU716	●	●	○	O/A	433Mhz	Huf/Beru	●	●
아우디	Q7	2015/01-2020/06	433MHz	4L/AU726	●	●	○	O/A	433Mhz	Huf/Beru	●	●
아우디	Q7	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	R9	2009/06-2015/03	433MHz	AU714	●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	R9	2015/04-2020/06	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
아우디	R9	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	RS5	2010/01-2016/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	RS5	2017/01-2019/12	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
아우디	S6	2005/01-2012/12	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	S6	2002/01-2017/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
아우디	S6	2018/01-2019/12	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	S7	2012/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	S8	2010/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
아우디	S8	2017/11-2019/12	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	S8	2009/11-2017/10	433MHz	D4	●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	SQ5	2017/01-2019/12	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	SQ5	2012/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	TT	2014/02-2020/06	433MHz	AU334	●	●	○	A	433Mhz	Huf/Beru	●	●
아우디	TTS	2017/01-2019/12	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
BMW	1 Series	2010/07-2020/06	433MHz	F20/F21/F40	●	●	○	A	433Mhz	Continental	●	●
BMW	1 Series	2008/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	2 Series	2014/01-2019/12	433Mhz	F22/F23/F45/F46	●	●	○	A	433Mhz	Continental	●	●
BMW	3 Series	2010/10-2013/11	433MHz	F30	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	3 Series	1999/01-2005/12	433MHz	E46	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	3 Series	2014/01-2019/12	433Mhz	F31/F35	●	●	○	A	433Mhz	Continental	●	●
BMW	3 Series	2005/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	3 Series	2006/01-2009/08	433MHz	E9x	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	3 Series	2018/12-2020/06	433Mhz	G20	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	3 Series	2009/09-2010/09	433MHz	E9x	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	3 Series GT	2014/03-2019/12	433MHz	F34	●	●	○	A	433Mhz	Continental	●	●
BMW	3 Series Sedan	2014/03-2019/12	433MHz	F34	●	●	○	A	433Mhz	Continental	●	●
BMW	4 Series	2014/03-2020/06	F32/F33/F36 433MHz	F32/F33/F36	●	●	○	A	433Mhz	Continental	●	●
BMW	5 Series	2014/03-2017/12	433MHz	F10/F11	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	5 Series	2017/01-2019/12	433Mhz	G30/G31/G38	●	●	○	A	433Mhz	Schrader	●	●
BMW	5 Series	2010/10-2015/02	433MHz	F10/F07/F18	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	5 Series GT	2009/01-2010/12	433MHz	E60/E61	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	5 Series GT	2017/01-2019/12	433Mhz	G32	●	●	○	A	433Mhz	Schrader	●	●
BMW	5 Series GT	2014/04-2018/06	433MHz	F07 LCI	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	5 Series GT	2011/01-2016/12	433MHz	F10/F07	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	6 Series	2011/01-2014/03	433MHz	F06/F12/F13	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	6 Series	2016/09-2020/06	433Mhz G14/G32	G14/G32	●	●	○	A	433Mhz	Schrader	●	●
BMW	6 Series	2014/03-2019/12	433MHz	F12/F13/F06	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	7 Series	2010/10-2014/12	433MHz	F01/F02/F04	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	7 Series	2015/06-2020/06	433Mhz	G11/G12	●	●	○	A	433Mhz	Schrader	●	●
BMW	7 Series	2014/03-2015/05	433MHz	F01/F02/F03/F04	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	M2	2014/11-2019/12	433MHz	F87	●	●	○	A	433Mhz	Continental	●	●
BMW	M3	2014/01-2018/12	433Mhz	F80	●	●	○	A	433Mhz	Continental	●	●
BMW	M4	2015/01-2019/12	433Mhz	F82/F83	●	●	○	A	433Mhz	Continental	●	●
BMW	M5	2014/03-2017/12	433MHz	F10	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	M5	2010/09-2014/03	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	M6	2014/03-2018/12	433MHz	F12	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	모터사이클	2010/01-2019/12	433MHz		○	●	○	C	433Mhz	Schrader	●	●
BMW	X1	2015/08-2019/12	433MHz	F48	●	●	○	A	433Mhz	Continental	●	●
BMW	X1	2014/03-2015/09	433MHz	E84	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	X1	2009/01-2013/12	Indirect	E84	○	○	○	A	N/A	N/A	Indirect	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
BMW	X2	2016/01-2019/12	433MHz		●	●	○	A	433Mhz	Continental	●	●
BMW	X3	2017/01-2020/06	G01/G08 433MHz		●	●	○	A	433Mhz	Schrader	●	●
BMW	X3	2003/01-2010/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	X3	2014/04-2017/12	433MHz	F25	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	X4	2014/01-2019/12	433MHz	F26	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	X4	2017/03-2020/06	433MHz	G02	●	●	○	A	433Mhz	Schrader	●	●
BMW	X5	2013/05-2019/12	433MHz	F15/F85	●	●	○	A	433Mhz	Continental	●	●
BMW	X5	2010/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	X6	2014/08-2019/12	433MHz	F16/F86	●	●	○	A	433Mhz	Continental	●	●
BMW	X6	2008/01-2014/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	Z4	2014/03-2019/02	433MHz	E89	●	●	○	O/A	433Mhz	Huf/Beru	●	●
BMW	Z4	2009/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	i Series	2018/01-2018/12	433MHz		●	●	○	A	433Mhz	Continental	●	●
BMW	i3	2013/01-2019/12	433MHz	I01/I12	●	●	○	A	433Mhz	Continental	●	●
BMW	i8	2013/01-2019/12	433MHz	I01/I12	●	●	○	A	433Mhz	Continental	●	●
벤틀리	벤틀가	2016/01-2020/06	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
벤틀리	플라잉 스피어	2011/01-2019/12	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
벤틀리	물산	2010/01-2020/06	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
캐딜락	ATS	2014/01-2014/12	433MHz	A1SL/A1BL	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	ATS	2015/01-2015/12	433MHz	A1SL/A1BL	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	ATS	2016/01-2019/12	433MHz	A1SL/A1BL	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	ATS	2013/01-2013/12	433MHz	A1SL/A1BL	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	ATS-V	2017/01-2019/12	433MHz		○	●	○	S	433Mhz	Schrader	●	●
캐딜락	ATS-V	2016/01-2016/12	433MHz		○	●	○	S	433Mhz	Schrader	●	●
캐딜락	ATS-V	2015/01-2015/12	433MHz		○	●	○	S	433Mhz	Schrader	●	●
캐딜락	BLS	2006/01-2010/12	433MHz		○	●	○	A	433Mhz	Schrader	●	●
캐딜락	CT7	2016/01-2019/12	433Mhz 13598773		●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	CTS	2013/06-2013/12	433MHz	A1LL	○	●	○	C	433Mhz	Schrader	●	●
캐딜락	CTS	2014/01-2015/12	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	CTS	2016/01-2020/06	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	CTS-V	2016/01-2019/12	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	CTS-V	2010/01-2015/12	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	에스컬레이드	2015/01-2019/12	433MHz	GMT900/ GMTK2XL/ K2UL	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	에스컬레이드	2014/01-2014/12	433MHz	GMT900/ GMTK2XL/ K2UL	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	에스컬레이드	2013/01-2013/12	433MHz	GMT900/ GMTK2XL	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	에스컬레이드	2012/01-2012/12	433MHz	GMT900/ GMTK2XL	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	에스컬레이드	2009/01-2011/12	433MHz	GMT926	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	에스컬레이드	2007/01-2008/12	433MHz	GMT926	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	Orlando	2013/01-2015/12	433MHz	GMT166	●	●	●	O/S	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
캐딜락	SRX	2016/01-2016/12	433MHz	C1UL	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	SRX	2016/01-2016/12	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
캐딜락	SRX	2014/10-2015/12	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
캐딜락	SRX	2014/01-2016/12	433MHz	GMT166	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	SRX	2013/01-2013/12	433MHz	GMT166	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	SRX	2007/01-2008/12	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
캐딜락	SRX	2009/01-2009/12	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
캐딜락	SRX	2009/06-2009/12	433MHz	GMT166	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	SRX	2004/01-2006/12	315MHz		●	●	○	O/S	315Mhz	Schrader	●	●
캐딜락	SRX	2010/01-2011/12	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
캐딜락	SRX	2010/01-2012/12	433MHz	GMT166	●	●	●	O/S	433Mhz	Schrader	●	●
캐딜락	SRX	2012/01-2012/09	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
캐딜락	SRX	2012/10-2013/12	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
캐딜락	SRX	2015/01-2016/12	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
쉐보레	Alpheon	2011/01-2015/12	433Mhz		○	●	○	S	433Mhz	Schrader	●	●
쉐보레	아베오	2013/01-2018/12	433Mhz		●	●	●	O/S	433Mhz	Schrader	●	●
쉐보레	볼트 EV	2017/01-2020/06	433Mhz		●	●	●	O/S	433Mhz	Schrader	●	●
쉐보레	카마로	2017/01-2019/12	433Mhz		●	●	●	O/S	433Mhz	Schrader	●	●
쉐보레	카마로	2016/01-2016/12	Snap in 433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
쉐보레	캡티바	2011/01-2018/12	433Mhz		●	●	●	O/S	433Mhz	Schrader	●	●
쉐보레	콜로라도	2017/01-2018/12	433Mhz		●	●	●	O/S	433Mhz	Schrader	●	●
쉐보레	크루즈	2016/01-2019/12	433Mhz		●	●	●	O/S	433Mhz	Schrader	●	●
쉐보레	크루즈	2013/01-2015/12	433MHz	D1SC/ D1JC/ D1WC/ KL1J	●	●	●	O/S	433Mhz	Schrader	●	●
쉐보레	크루즈	2012/01-2012/12	433MHz	D1SC/ D1JC/ D1WC/ KL1J	●	●	●	O/S	433Mhz	Schrader	●	●
쉐보레	에퀴녹스	2017/06-2019/12	433Mhz		●	●	●	O/S	433Mhz	Schrader	●	●
쉐보레	임팔라	2012/01-2012/12	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
쉐보레	임팔라	2009/01-2011/12	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
쉐보레	임팔라	2008/01-2008/12	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
쉐보레	임팔라	2007/01-2007/12	Snap in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
쉐보레	임팔라	2007/01-2007/12	Clamp in 315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
쉐보레	임팔라	2006/01-2006/12	Clamp in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
쉐보레	임팔라	2016/01-2016/12	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
쉐보레	임팔라	2017/01-2020/06	315MHz 13598772		●	●	●	O/S	315Mhz	Schrader	●	●
쉐보레	임팔라	2016/01-2020/06	433MHz 13598773		●	●	●	O/S	433Mhz	Schrader	●	●
쉐보레	임팔라	2015/01-2016/12	Limited 315Mhz 13598771		●	●	●	O/S	315Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
쉐보레	임팔라	2015/01-2016/12	Limited 315MHz 23445327		●	●	●	0/S	315Mhz	Schrader	●	●
쉐보레	임팔라	2013/10-2014/12	Limited 315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
쉐보레	임팔라	2013/01-2013/09	315MHz 13598771		●	●	●	0/S	315Mhz	Schrader	●	●
쉐보레	말리브	2011/01-2019/12	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
쉐보레	몬테 카를로	2007/01-2007/12	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
쉐보레	올랜도	2016/01-2018/12	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
쉐보레	스파크	2013/01-2019/12	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
쉐보레	트랙스	2015/01-2020/06	433MHz	G1UC	●	●	●	0/S	433Mhz	Schrader	●	●
쉐보레	트랙스	2013/01-2014/12	315MHz		●	●	●	0/S	315Mhz	Schrader	●	●
쉐보레	볼트	2016/01-2019/12	433Mhz		●	●	●	0/S	433Mhz	Schrader	●	●
크라이슬러	200	2014/01-2016/12	433MHz		●	●	●	0/A	433Mhz	Continental	●	●
크라이슬러	300C	2010/06-2019/12	18 inch 433Mhz		●	●	●	0/A	433Mhz	Schrader	●	●
크라이슬러	300C	2010/06-2019/12	20 inch 433Mhz		●	●	●	0/A	433Mhz	Schrader	●	●
크라이슬러	300C	2005/06-2010/05	433Mhz	LE48	●	●	●	0/A	433Mhz	Continental	●	●
크라이슬러	그랜드 보예저	2011/01-2019/12	433Mhz	RT	●	●	●	0/S	433Mhz	Schrader	●	●
크라이슬러	퍼시픽카	2017/01-2020/06	433MHz		●	●	●	0/A	433Mhz	Continental	●	●
크라이슬러	퍼시픽카	2006/01-2008/12	315MHz	CS	●	●	○	A	315Mhz	Continental	●	●
크라이슬러	퍼시픽카	2004/01-2005/12	315MHz		●	●	○	A	315Mhz	Continental	●	●
크라이슬러	퍼시픽카	2004/01-2004/12	433MHz		●	●	○	S	433Mhz	Schrader	●	●
크라이슬러	퍼시픽카	2003/01-2003/12	433MHz		●	●	○	A	433Mhz	Schrader	●	●
Citroen	C4	2013/01-2019/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	DS3	2015/01-2019/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	DS4	2010/12-2014/01	433MHz	B75	●	●	○	0	433Mhz	Schrader	●	●
Citroen	DS4	2014/02-2019/12	433MHz	B81	●	●	○	0/A	433Mhz	Schrader	●	●
Citroen	DS4 Crossback	2016/01-2017/12	433MHz		●	●	○	0	433Mhz	Schrader	●	●
Citroen	DS5	2011/01-2014/01	433MHz	B81	●	●	○	0	433Mhz	Schrader	●	●
Citroen	DS5	2014/02-2019/12	433MHz	X2/50	●	●	○	0	433Mhz	Schrader	●	●
Citroen	Space Tourer	2016/10-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
페라리	458 이탈리아	2014/01-2016/12	433Mhz	F142	●	●	○	0/A	433Mhz	Huf/Beru	●	●
페라리	458 Spider	2009/09-2019/12	433Mhz	F142	●	●	○	0/A	433Mhz	Huf/Beru	●	●
페라리	488	2015/01-2020/06	433Mhz	F142	○	●	○	A	433Mhz	Huf/Beru	●	●
페라리	575M 마라넬로	2002/01-2006/12	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
페라리	595 GTB/GTO	2004/01-2011/12	433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
페라리	812 Superfast	2017/01-2018/12	315MHz		○	●	○	C	315Mhz	Huf/Beru	●	●
페라리	캘리포니아	2008/10-2017/12	433MHz	F149	●	●	○	0/A	433Mhz	Huf/Beru	●	●
페라리	엔조	2003/01-2006/12	433MHz	F140	●	●	○	0/A	433Mhz	Huf/Beru	●	●
페라리	F12 벨리네타	2012/10-2017/12	433Mhz	F151/ F152	●	●	○	0/A	433Mhz	Huf/Beru	●	●
페라리	F12 tdf	2015/01-2018/12	433Mhz	F151/ F152	○	●	○	A	433Mhz	Huf/Beru	●	●
페라리	F430	2004/09-2007/06	433Mhz	F131E	●	●	○	0/A	433Mhz	Huf/Beru	●	●
페라리	F430	2007/07-2009/10	433MHz	F131E	●	●	○	0/A	433Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
페라리	FF	2011/01-2020/01	433MHz	F151	●	●	○	O/A	433Mhz	Huf/Beru	●	●
페라리	FXX	2005/01-2006/12	433MHz	F140	○	●	○	A	433Mhz	Huf/Beru	●	●
페라리	GTC4 루쏘	2016/01-2018/12	433MHz		○	●	○	C	433Mhz	Huf/Beru	●	●
페라리	라 페라리	2013/07-2020/06	433MHz	F150	○	●	○	A	433Mhz	Huf/Beru	●	●
페라리	Portofino	2016/01-2019/12	433MHz		○	●	○	C	433Mhz	Huf/Beru	●	●
Fiat	500	2014/01-2020/06	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	500L	2012/01-2020/06	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	500X	2014/01-2020/06	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	Freemont	2014/07-2018/03	433Mhz		●	●	○	O/A	433Mhz	Schrader	●	●
포드	에스케이프	2012/05-2014/12	433MHz	C520	●	●	●	S	433Mhz	Schrader	●	●
포드	에스케이프	2015/01-2018/12	433MHz	C520	●	●	●	O/S	433Mhz	Schrader	●	●
포드	익스플로러	2011/01-2015/12	315MHz	U502	●	●	●	S	315Mhz	Schrader	●	●
포드	익스플로러	2011/01-2015/12	433MHz	U502	●	●	●	S	433Mhz	Schrader	●	●
포드	익스플로러	2015/06-2019/12	433MHz		●	●	○	O/S	433Mhz	Schrader	●	●
포드	쿠가	2014/01-2019/12	433MHz	C520	●	●	●	O/S/A	433Mhz	Schrader	●	●
포드	몬데오	2015/01-2017/08	Snap in 433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
포드	몬데오	2017/09-2020/12	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
포드	무스탕	2015/01-2018/12	433MHz	S550	●	●	●	O/S	433Mhz	Schrader	●	●
포드	타우러스	2016/01-2018/12	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
혼다	아코드	2015/01-2018/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
혼다	아코드	2013/01-2014/12	Direct 433MHz	2GA/2GB/QE	●	●	○	O	433Mhz	Continental	●	●
혼다	CR-V	2014/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
혼다	씨빅	2013/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
혼다	HR-V	2014/09-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
혼다	오디세이	2017/01-2019/12	433MHz		●	●	○	O	433MHz	Continental	●	●
혼다	오디세이	2014/01-2017/12	315MHz		○	●	○	C	315Mhz	TRW	●	●
혼다	파이롯	2016/01-2017/12	433MHz		●	●	○	O	433Mhz	Continental	●	●
혼다	파이롯	2009/01-2015/12	Alloy 315MHz		●	●	○	O/A	315Mhz	Pacific	●	●
혼다	파이롯	2018/01-2020/12	433MHz		●	●	○	O	433MHz	Continental	●	●
혼다	파이롯	2009/01-2015/12	Steel 315MHz		●	●	○	O	315Mhz	Pacific	●	●
홈머	H2	2009/01-2010/12	315MHz		●	●	●	O/S	315Mhz	Schrader	●	●
홈머	H2	2008/01-2008/12	315MHz 13598771		●	●	●	O/S	315Mhz	Schrader	●	●
홈머	H2	2008/01-2008/12	315MHz 15922396		●	●	●	O/S	315Mhz	Schrader	●	●
홈머	H2	2007/01-2007/12	315MHz		●	●	●	S	315Mhz	Schrader	●	●
홈머	H3	2007/01-2010/12	315MHz		●	●	●	S	315Mhz	Schrader	●	●
홈머	H3	2006/01-2006/12	315MHz		●	●	●	S	315Mhz	Schrader	●	●
홈머	H3T	2006/01-2010/12	315MHz		○	●	○	S	315Mhz	Schrader	●	●
현대	엑센트	2015/01-2018/12	Hi Line 433MHz	RB	●	●	○	O	433Mhz	Continental	●	●
현대	엑센트	2015/01-2018/12	Lo Line 433MHz	RB	●	●	○	O	433Mhz	Continental	●	●
현대	Aslan	2014/01-2017/12	433MHz		●	●	○	O	433Mhz	Continental	●	●
현대	Aslan	2018/01-2018/12	433MHz		●	●	○	O	433Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
현대	Avante	2011/01-2013/12	MD 433MHz		●	●	○	0	433MHz	TRW	●	●
현대	Avante	2016/01-2018/12	AD 433MHz		●	●	○	0	433MHz	Continental	●	●
현대	Avante	2014/01-2016/12	MD 433MHz		●	●	○	0	433MHz	TRW	●	●
현대	Avante	2012/01-2016/12	JK 433MHz		●	●	○	0	433MHz	TRW	●	●
현대	엘란트라	2013/10-2019/12	Lo Line 315MHz		●	●	○	0/A	315MHz	TRW	●	●
현대	Elantra GT	2017/06-2019/12	PD 433MHz	PD	●	●	○	0	433MHz	Continental	●	●
현대	에쿠스	2013/01-2016/12	433MHz	VI New	●	●	○	0/A	433MHz	Continental	●	●
현대	에쿠스	2008/01-2013/12	433MHz	VI Old	●	●	○	0	433MHz	TRW	●	●
현대	제네시스	2007/01-2007/12	BH 315MHz	BH	●	●	○	0	315MHz	TRW	●	●
현대	제네시스	2007/01-2014/12	BH 433MHz	BH	●	●	○	0	433MHz	TRW	●	●
현대	제네시스	2013/01-2016/12	DH 433MHz	DH	●	●	○	0/A	433MHz	Continental	●	●
현대	제네시스	2013/01-2016/12	BK 315MHz	BK	●	●	○	0	315MHz	TRW	●	●
현대	Genesis Coupe	2014/01-2016/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	Genesis Coupe	2012/01-2013/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	Genesis G70	2017/10-2020/06	433MHz	IK	●	●	○	0	433MHz	Schrader	●	●
현대	Genesis G80	2016/07-2020/06	433MHz	DH	●	●	○	0	433MHz	Continental	●	●
현대	Genesis G90	2016/07-2020/06	433MHz	HI	●	●	○	0	433MHz	Continental	●	●
현대	Grand Starex	2015/01-2018/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	그랜저	2017/01-2018/12	433MHz	IG/IG HEV	●	●	○	0	433MHz	Continental	●	●
현대	그랜저	2011/01-2017/12	HG 433MHz	HG	●	●	○	0	433MHz	TRW	●	●
현대	그랜저	2011/06-2015/12	HG 433MHz		●	●	○	0	433MHz	TRW	●	●
현대	그랜저	2014/01-2014/12	Hybrid 433MHz		●	●	○	0	433MHz	TRW	●	●
현대	그랜저	2015/01-2017/12	Hybrid 433MHz		●	●	○	0	433MHz	Continental	●	●
현대	이오닉	2016/01-2020/06	433MHz	AE	●	●	○	0	433MHz	Continental	●	●
현대	Kona	2017/01-2020/06	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	Maxcruz	2012/01-2018/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	Nexo	2018/04-2020/06	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
현대	Palisade	2019/01-2020/06	433MHz		○	●	○	C	433MHz	Schrader	●	●
현대	Porter	2014/01-2018/12	HR		●	●	○	0	433MHz	Continental	●	●
현대	Porter	2007/01-2018/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	싼타페	2018/01-2019/12	433MHz	TM	●	●	○	0	433MHz	Schrader	●	●
현대	싼타페	2012/06-2014/12	315MHz	NC	●	●	○	0	315MHz	Continental	●	●
현대	싼타페	2012/01-2015/12	433MHz	DM	●	●	○	0	433MHz	Continental	●	●
현대	싼타페	2009/01-2012/05	CM 433MHz	CM	●	●	○	0	433MHz	Lear	●	●
현대	Solati	2014/03-2019/06	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	쏘나타	2010/01-2013/12	433MHz	LF/LFA	●	●	○	0	433MHz	Continental	●	●
현대	쏘나타	2014/04-2019/12	Hi Line 433MHz	LF/LFA	●	●	○	0	433MHz	Schrader	●	●
현대	쏘나타	2010/01-2010/12	433MHz	YF	●	●	○	0	433MHz	Continental	●	●
현대	쏘나타	2014/01-2015/12	VDO 433MHz		●	●	○	0	433MHz	Continental	●	●
현대	Sonata Hybrid	2016/01-2019/12	433MHz	YF/LF HEV	●	●	○	0	433MHz	Schrader	●	●
현대	Sonata Hybrid	2011/01-2014/12	529333N100 433MHz		●	●	○	0	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
현대	Sonata Hybrid	2011/01-2019/12	529331J000 433MHz		●	●	○	0	433Mhz	Continental	●	●
현대	스타렉스	2007/01-2015/12	433Mhz	A1	○	●	○	C	433MHz	Continental	●	●
현대	스타렉스	2007/01-2007/12	315Mhz		○	●	○	C	315MHz	Continental	●	●
현대	투싼	2012/01-2015/12	Lo Line 433MHz	LM	●	●	○	0	433MHz	TRW	●	●
현대	투싼	2009/01-2013/12	433MHz	LM	●	●	○	0	433MHz	TRW	●	●
현대	투싼	2015/01-2018/12	433MHz	LM FCEV	●	●	○	0	433MHz	Schrader	●	●
현대	투싼	2015/05-2020/06	Hi Line 433MHz	TL	●	●	○	0	433MHz	Schrader	●	●
현대	투싼	2016/01-2017/12	TL 433MHz	TL	●	●	○	0	433MHz	TRW	●	●
현대	투싼	2012/01-2015/12	Hi line 433MHz	LM	●	●	○	0	433MHz	TRW	●	●
현대	벨로스터	2011/03-2018/12	FS 433MHz	FS	●	●	○	0	433MHz	Schrader	●	●
현대	벨로스터	2018/01-2020/06	JS 433MHz	JS	●	●	○	0	433MHz	Continental	●	●
현대	베라크루즈	2007/01-2013/12	433MHz		●	●	○	0	433MHz	Lear	●	●
현대	베라크루즈	2007/01-2012/12	CM 433MHz	EN	●	●	○	0	433MHz	Continental	●	●
현대	i30	2016/08-2020/06	433MHz	PD/Pde	●	●	○	0	433MHz	Continental	●	●
현대	i30	2012/01-2016/12	433MHz	GD	●	●	○	0/A	433MHz	Continental	●	●
현대	i40	2017/01-2019/12	433MHz	IF	●	●	○	0	433MHz	Continental	●	●
현대	i40	2011/01-2014/03	VF 433MHz	VF	●	●	○	0	433MHz	TRW	●	●
현대	i40	2014/04-2020/06	VF 433MHz	VF	●	●	○	0/A	433MHz	TRW	●	●
인피니티	EX Series	2007/01-2014/03	433MHz	P53B/J50	●	●	○	0	433MHz	Schrader	●	●
인피니티	FX Series	2008/03-2015/04	433MHz	P53C/S51	●	●	○	0	433MHz	Schrader	●	●
인피니티	G Series	2006/01-2014/02	433MHz	CV36/G312/L53A	●	●	○	0	433MHz	Schrader	●	●
인피니티	M Series	2010/01-2016/04	Y51 433MHz	M312/Y51	●	●	○	0	433MHz	Pacific	●	●
인피니티	Q30	2015/01-2019/12	433MHz	GD1A/H15	●	●	○	0/A	433MHz	Schrader	●	●
인피니티	Q50	2013/01-2019/12	433MHz	L53H/D53H/V37	●	●	○	0	433MHz	Continental	●	●
인피니티	Q60	2016/05-2019/12	433MHz	CV37	●	●	○	0	433MHz	Continental	●	●
인피니티	Q70	2013/01-2019/12	433MHz	L53E/Y51	●	●	○	0	433MHz	Pacific	●	●
인피니티	Q70	2018/10-2019/12	433MHz		●	●	○	0	433MHz	Continental	●	●
인피니티	QX60	2012/02-2019/12	433MHz	L50	●	●	○	0	433MHz	Continental	●	●
인피니티	QX70	2013/01-2019/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
인피니티	QX80	2013/01-2019/12	433MHz	Z62	●	●	○	0	433MHz	Pacific	●	●
재규어	E-페이스	2017/06-2019/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
재규어	F-페이스	2015/01-2019/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
재규어	F-타일	2014/01-2015/06	433MHz		○	●	○	A	433MHz	Continental	●	●
재규어	F-타일	2017/01-2019/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
재규어	I-페이스	2017/01-2019/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
재규어	XE	2014/01-2015/06	433MHz		○	●	○	A	433MHz	Continental	●	●
재규어	XE	2015/12-2019/12	433MHz	X760	●	●	○	0/A	433MHz	Continental	●	●
재규어	XF	2008/01-2014/06	433MHz	X250	●	●	○	0/A	433MHz	Continental	●	●
재규어	XF	2014/07-2015/05	433MHz	X260	●	●	○	0/A	433MHz	Continental	●	●
재규어	XF	2015/06-2019/12	433MHz	X260	●	●	○	0/A	433MHz	Continental	●	●
재규어	XJ	2016/01-2019/12	433MHz	X351	●	●	○	0/A	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
재규어	XJ	2010/01-2015/12	433Mhz	X351	●	●	○	0/A	433Mhz	Continental	●	●
재규어	XK	2006/01-2015/12	433MHz	X150	●	●	○	0/A	433Mhz	Continental	●	●
지프	체로키	2014/01-2016/12	433MHz	KL	●	●	●	0/A	433Mhz	TRW	●	●
지프	체로키	2017/01-2020/06	433MHz	KL	●	●	●	0/A	433Mhz	TRW	●	●
지프	컴맨더	2008/01-2010/12	433MHz	XK	●	●	●	0/A	433Mhz	Schrader	●	●
지프	컴맨더	2006/01-2007/12	433MHz	XK	●	●	●	0/A	433Mhz	Continental	●	●
지프	컴파스	2014/09-2017/12	433MHz	MK49	●	●	●	0/A	433Mhz	Schrader	●	●
지프	컴파스	2008/01-2009/12	315MHz	MK49	●	●	●	0/A	315Mhz	Continental	●	●
지프	컴파스	2017/01-2018/12	433MHz	551	○	●	○	A	433Mhz	Continental	●	●
지프	컴파스	2007/01-2007/12	315MHz	MK49	●	●	●	0/A	315Mhz	Continental	●	●
지프	컴파스	2006/05-2014/08	433MHz	MK49	●	●	●	0/A	433Mhz	Schrader	●	●
지프	그랜드 체로키	2012/01-2013/12	433MHz	WK74	●	●	●	0	433Mhz	Schrader	●	●
지프	그랜드 체로키	2018/01-2019/12	433Mhz	WK	●	●	●	0/A	433Mhz	Continental	●	●
지프	그랜드 체로키	2014/01-2019/12	433MHz	WK74	●	●	●	0	433Mhz	Schrader	●	●
지프	그랜드 체로키	2016/01-2017/12	433Mhz	WK	●	●	●	0/A	433Mhz	Continental	●	●
지프	그랜드 체로키	2011/01-2011/12	433MHz	WK74	●	●	●	0	433Mhz	Schrader	●	●
지프	패트리오트	2009/01-2014/12	315MHz	MK	●	●	●	0/A	315Mhz	Schrader	●	●
지프	패트리오트	2007/01-2008/12	433Mhz	MK	●	●	●	0/A	433Mhz	Continental	●	●
지프	레니게이드	2017/01-2018/12	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
지프	레니게이드	2015/01-2016/12	433Mhz		●	●	●	0/A	433Mhz	Continental	●	●
지프	랭글러	2014/01-2020/06	433MHz	JL	●	●	●	0/A	433Mhz	Schrader	●	●
지프	랭글러	2010/01-2013/12	433MHz	JK72	●	●	●	0/A	433Mhz	Schrader	●	●
기아	Bongo	2017/01-2018/12	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	Bongo	2014/01-2016/12	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	카렌스	2014/01-2019/12	433MHz	RP	●	●	○	0/A	433Mhz	Continental	●	●
기아	카니발	2018/01-2018/12	52933C1100 433MHz		●	●	○	0	433Mhz	Schrader	●	●
기아	카니발	2014/01-2018/12	Sedan 433MHz	YP	●	●	○	0	433Mhz	Schrader	●	●
기아	카니발	2005/01-2013/12	315MHz	YP	●	●	○	0	315Mhz	Lear	●	●
기아	카니발	2019/01-2019/12	433MHz	YP	●	●	○	0	433Mhz	Schrader	●	●
기아	K3	2012/01-2016/12	529333X305 433MHz		●	●	○	0	433MHz	TRW	●	●
기아	K3	2012/01-2019/12	433MHZ TRW	YDC/YD	●	●	○	0	433MHz	TRW	●	●
기아	K3	2019/01-2020/06	433MHZ Pacific	BDC/BD	●	●	○	0/A	433Mhz	Pacific	●	●
기아	K5	2015/07-2019/12	JF/Hybrid 433Mhz	JF/JF HEV	●	●	○	0/A	433Mhz	Continental	●	●
기아	K5	2013/01-2015/06	TF/Hybrid 433Mhz	TF/TF HEV	●	●	○	0	433Mhz	Continental	●	●
기아	K5	2011/01-2012/12	TF 433Mhz	TF/TF HEV	●	●	○	0	433Mhz	Continental	●	●
기아	K7	2016/01-2019/12	YG 433MHz	YG	●	●	○	0	433MHz	Continental	●	●
기아	K7	2008/01-2012/12	433MHz	VG	●	●	○	0	433MHz	Continental	●	●
기아	K7	2013/01-2016/12	VG/Hybrid 433MHz	VG	●	●	○	0	433MHz	Continental	●	●
기아	K9	2011/01-2018/12	433MHz	KH	●	●	○	0	433MHz	Schrader	●	●
기아	K9	2019/01-2019/12	RJ 433MHz	RJ	●	●	○	0	433Mhz	Schrader	●	●
기아	모하비	2007/01-2007/12	HM 433MHZ	HM	●	●	○	0	433Mhz	TRW	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
기아	모하비	2007/01-2007/12	433MHZ		●	●	○	0	433Mhz	TRW	●	●
기아	모하비	2016/01-2018/12	433MHZ		●	●	○	0	433Mhz	Continental	●	●
기아	모닝	2014/01-2019/06	433MHZ		●	●	○	0	433MHZ	Continental	●	●
기아	Morning 3	2017/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
기아	니로	2016/01-2020/06	433MHZ	DE	●	●	○	0	433Mhz	Continental	●	●
기아	Opirus	2006/01-2014/12	433MHZ		●	●	○	0	433Mhz	TRW	●	●
기아	Pride	2012/01-2017/12	UB 433MHZ		●	●	○	0	433MHZ	TRW	●	●
기아	Pride	2018/01-2018/12	Hi Line 433MHZ	YB	●	●	○	0	433MHZ	TRW	●	●
기아	Pride	2018/01-2018/12	Lo Line 433MHZ	YB	●	●	○	0	433MHZ	TRW	●	●
기아	Pride	2017/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
기아	Ray	2011/01-2018/12	Elec 433MHZ		●	●	○	0	433Mhz	Continental	●	●
기아	쏘렌토	2018/01-2018/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
기아	쏘렌토	2011/01-2015/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
기아	쏘렌토	2009/01-2010/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
기아	쏘렌토	2006/01-2008/12	433Mhz	XM	●	●	○	0	433Mhz	Continental	●	●
기아	쏘렌토	2016/01-2017/12	433MHZ	UMA	●	●	○	0	433Mhz	Continental	●	●
기아	쏘울	2013/11-2016/12	433Mhz		●	●	○	0	433Mhz	Schrader	●	●
기아	쏘울	2008/06-2013/10	AM 433Mhz	AM	●	●	○	0	433Mhz	Continental	●	●
기아	스포티지	2014/01-2015/12	SL 433Mhz	SL	●	●	○	0/A	433Mhz	TRW	●	●
기아	스포티지	2016/01-2020/06	QL/QLE 433Mhz	QL/QLE	●	●	○	0/A	433Mhz	Continental	●	●
기아	스포티지	2010/01-2013/12	Hi Line 433Mhz	SL	●	●	○	0	433Mhz	TRW	●	●
기아	스포티지	2010/01-2013/12	Lo Line 433Mhz	SL	●	●	○	0	433Mhz	TRW	●	●
기아	Sportage R	2014/01-2015/12	433Mhz		●	●	○	0	433MHZ	TRW	●	●
기아	Stinger	2017/10-2020/06	433Mhz	CK	●	●	○	0	433Mhz	Schrader	●	●
기아	Stinger	2017/01-2017/12	433Mhz		●	●	○	0	433Mhz	Schrader	●	●
기아	Stonic	2017/01-2020/06	Indirect		○	○	○	S	N/A	N/A	Indirect	●
람보르기니	아벤타도	2012/01-2019/12	433Mhz	LB834	○	●	○	A	433Mhz	Huf/Beru	●	●
람보르기니	허라칸	2014/01-2020/06	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
람보르기니	One off	2016/01-2020/06	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
람보르기니	Urus	2017/01-2019/12	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
랜드로버	디스커버리	2009/01-2015/09	433MHZ		○	●	○	A	433Mhz	Continental	●	●
랜드로버	디스커버리	2017/01-2019/12	433MHZ		●	●	○	0/A	433Mhz	Continental	●	●
랜드로버	디스커버리	2015/10-2016/12	433MHZ		●	●	○	0/A	433Mhz	Continental	●	●
랜드로버	디스커버리 스포츠	2015/09-2019/12	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●
랜드로버	프리랜더	2007/01-2016/12	433Mhz	Fr132	●	●	○	0/A	433Mhz	Continental	●	●
랜드로버	렌지로버	2015/06-2019/12	433MHZ	D6, Ra5	●	●	○	0/A	433Mhz	Continental	●	●
랜드로버	렌지로버	2010/01-2012/12	433MHZ	L322	●	●	○	0/A	433Mhz	Continental	●	●
랜드로버	렌지로버 에보크	2011/01-2015/09	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●
랜드로버	렌지로버 에보크	2015/10-2019/12	433MHZ		●	●	○	0/A	433Mhz	Continental	●	●
랜드로버	렌지로버 스포츠	2013/01-2015/05	433MHZ		●	●	○	0/A	433Mhz	Continental	●	●
랜드로버	렌지로버 스포츠	2015/06-2019/12	433MHZ		●	●	○	0/A	433Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
랜드로버	Range Rover Velar	2017/01-2020/06	433Mhz		●	●	○	O/A	433Mhz	Continental	●	●
렉서스	CT Series	2013/12-2019/12	433Mhz	080A	●	●	○	0	433Mhz	Pacific	●	●
렉서스	ES Series	2007/01-2012/05	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
렉서스	ES Series	2012/06-2018/05	433Mhz	980L	●	●	○	0	433Mhz	Pacific	●	●
렉서스	ES Series	2018/06-2019/12	433MHZ		●	●	○	0	433MHZ	Pacific	●	●
렉서스	GS Series	2012/01-2019/12	433Mhz	920L	●	●	○	0	433Mhz	Pacific	●	●
렉서스	IS Series	2006/01-2015/07	PMV-107J 315MHz		●	●	○	0	315Mhz	Pacific	●	●
렉서스	IS Series	2013/04-2019/12	433Mhz	030L/400A/7 20A/ XE30	●	●	○	0	433Mhz	Pacific	●	●
렉서스	LC Series	2017/01-2019/12	433MHZ		●	●	○	0	433MHZ	Pacific	●	●
렉서스	LS Series	2017/10-2019/12	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
렉서스	LS Series	2012/10-2017/09	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
렉서스	LX Series	2015/10-2019/12	433MHZ	URJ	●	●	○	0	433MHZ	Pacific	●	●
렉서스	NX Series	2014/03-2019/12	433Mhz	600A	●	●	○	0	433Mhz	Pacific	●	●
렉서스	RC Series	2014/01-2019/12	433Mhz	XC1/720A	●	●	○	0	433Mhz	Pacific	●	●
렉서스	RX Series	2015/11-2019/12	433Mhz	740A	●	●	○	0	433Mhz	Pacific	●	●
렉서스	RX Series	2015/10-2019/12	315MHZ		●	●	○	0	315MHZ	Pacific	●	●
렉서스	RX Series	2014/06-2015/10	433Mhz	640L	●	●	○	0	433Mhz	Pacific	●	●
렉서스	UX Series	2018/10-2019/12	433MHZ	URJ	●	●	○	0	433MHZ	Pacific	●	●
링컨	컨티넨탈	2017/01-2019/12	433MHZ		○	●	○	S	433Mhz	Schrader	●	●
링컨	MKC	2015/06-2018/12	433MHZ	2. OF SEL	●	●	●	O/S	433Mhz	Schrader	●	●
링컨	MKX	2015/01-2015/12	433Mhz		●	●	●	S	433Mhz	Schrader	●	●
링컨	MKX	2016/01-2019/12	433Mhz		●	●	●	O/S	433Mhz	Schrader	●	●
링컨	MKZ	2015/09-2019/12	433MHZ		○	●	○	S	433Mhz	Schrader	●	●
링컨	MKZ	2013/01-2016/12	433Mhz		●	●	●	O/S	433Mhz	Schrader	●	●
Lotus	3 Eleven	2015/01-2017/12	433MHZ		○	●	○	A	433Mhz	Schrader	●	●
Lotus	Elise	2008/01-2020/06	433MHZ	Monza	○	●	○	A	433Mhz	Schrader	●	●
Lotus	Evora	2010/01-2020/06	433MHZ		○	●	○	A	433Mhz	Schrader	●	●
Lotus	Exige	2000/09-2020/12	433MHZ		○	●	○	A	433Mhz	Schrader	●	●
마세라티	지블리	2013/01-2020/09	433MHZ	M156/ M157	●	●	○	O/A	433Mhz	Schrader	●	●
마세라티	그란짜브리오	2017/01-2018/12	433MHZ		○	●	○	C	433Mhz	Schrader	●	●
마세라티	레반테	2015/01-2018/12	433MHZ		●	●	○	O/A	433Mhz	Schrader	●	●
마세라티	콰트로폴테	2013/01-2018/12	433MHZ		○	●	○	C	433Mhz	Schrader	●	●
McLaren	500 Series	2015/01-2019/12	433MHZ		○	●	○	A	433Mhz	Huf/Beru	●	●
McLaren	600 Series	2014/03-2019/12	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
McLaren	700 Series	2017/01-2019/12	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
McLaren	P1	2013/01-2019/12	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
메르세데스 벤츠	A Class	2018/06-2019/12	433Mhz	W177	●	●	○	O/A	433Mhz	Huf/Beru	●	●
메르세데스 벤츠	A Class	2014/04-2018/05	433Mhz	W176	●	●	○	O/A	433Mhz	Schrader	●	●
메르세데스 벤츠	A Class	2012/01-2014/03	433MHZ	W176	●	●	○	O/A	433Mhz	Schrader	●	●
메르세데스 벤츠	AMG GT	2014/01-2020/06	C190 433MHZ		●	●	○	O/A	433Mhz	Schrader	●	●
메르세데스 벤츠	B Class	2011/11-2019/01	W246/W242 433MHz	W246	●	●	○	O/A	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
메르세데스 벤츠	C Class	2018/06-2020/06	433MHz	W205	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	C Class	2007/04-2014/02	433MHz	W204/W203	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	C Class	2018/01-2018/12	433MHz	C205	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	C Class	2014/03-2018/05	433MHz	W205	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	CLA Class	2014/06-2019/04	433MHz	C117	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	CLA Class	2012/12-2014/05	433MHz	C117	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	CLS Class	2012/01-2017/12	433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	CLS Class	2018/01-2020/06	C257 433MHz		●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	E Class	2017/01-2019/12	W213/BR238 433MHz		●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	E Class	2015/11-2019/12	W213/BR238 433Mhz		●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	E Class	2014/06-2018/12	W212 433MHz	W212	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	E Class	2009/07-2014/05	433MHz	W212	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	G Class	2007/04-2018/05	433MHz	463	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	G Class	2018/06-2020/06	433Mhz	G463/461	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	GLA Class	2018/01-2020/06	433MHz		●	●	○	0	433Mhz	Schrader	●	●
메르세데스 벤츠	GLC Class	2015/01-2019/07	433MHz	X253	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	GLK Class	2008/01-2015/09	433MHz	X204	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	GLS Class	2013/01-2019/06	X166 433MHz	X164	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	GLS Class	2018/01-2018/12	433MHz	C257	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	S Class	2013/07-2019/07	433MHz	W222	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	S Class	2009/06-2013/06	433MHz	W221	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	S Class	2017/01-2017/12	433MHz	C217	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	SL Class	2012/01-2020/06	433Mhz	W231	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	SLC Class	2016/01-2019/07	433MHz	R172	●	●	○	0/A	433Mhz	Schrader	●	●
메르세데스 벤츠	SLK Class	2007/04-2019/05	433MHz	R171, R172	●	●	○	0/A	433Mhz	Schrader	●	●
미니	3-5 Doors Hatch	2014/01-2019/12	433MHz		●	●	○	A	433Mhz	Continental	●	●
미니	클럽맨	2008/01-2013/12	Indirect	R55	○	○	○	A	N/A	N/A	Indirect	●
미니	클럽맨	2013/11-2019/12	433Mhz	F54	●	●	○	A	433Mhz	Continental	●	●
미니	Convertible	2017/01-2019/12	433MHz	R57	●	●	○	A	433Mhz	Continental	●	●
미니	Convertible	2014/01-2016/12	433MHz	R57	●	●	○	0/A	433Mhz	Huf/Beru	●	●
미니	Convertible	2010/01-2013/12	Indirect	R57	○	○	○	A	N/A	N/A	Indirect	●
미니	쿠페	2014/03-2019/12	433MHz		●	●	○	A	433Mhz	Continental	●	●
미니	컨트리맨	2014/07-2018/12	433Mhz	R60	●	●	○	0/A	433Mhz	Huf/Beru	●	●
미니	컨트리맨	2010/01-2013/12	Indirect	R60	○	○	○	A	N/A	N/A	Indirect	●
미니	쿠페	2014/01-2015/12	433MHz	R58	●	●	○	0/A	433Mhz	Huf/Beru	●	●
미니	쿠페	2012/01-2013/12	Indirect	R58	○	○	○	A	N/A	N/A	Indirect	●
미니	해치백	2013/11-2019/12	433Mhz	F56	●	●	○	A	433Mhz	Continental	●	●
미니	페이스맨	2014/07-2018/06	433Mhz	R61	●	●	○	0/A	433Mhz	Huf/Beru	●	●
미니	페이스맨	2012/01-2013/12	Indirect	R61	○	○	○	A	N/A	N/A	Indirect	●
미니	로드스터	2014/01-2015/12	433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
미니	로드스터	2012/01-2013/12	Indirect	R59	○	○	○	A	N/A	N/A	Indirect	●
니산	370Z	2014/08-2019/12	PAC 433MHz	RC53D(2)/Z34	●	●	○	0/A	433Mhz	Pacific	●	●
니산	알티마	2012/05-2018/09	433MHz	L33	●	●	○	0	433Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
니산	알티마	2018/10-2020/06	433MHz	L33	●	●	○	0	433Mhz	Continental	●	●
니산	Altima Sedan	2006/01-2012/12	315MHz	L33	●	●	○	0	315Mhz	Schrader	●	●
니산	GT-R	2007/01-2019/12	315MHz	R35	●	●	○	0	315Mhz	Schrader	●	●
니산	쥬크	2014/03-2019/12	433MHz		●	●	○	0	433Mhz	Pacific	●	●
니산	리프	2010/10-2019/12	433MHz	ZE0/B12G	●	●	○	0	433Mhz	Pacific	●	●
니산	Leaf Korea	2015/01-2019/12	433MHz		●	●	○	0	433Mhz	Continental	●	●
니산	맥시마	2015/04-2019/12	433Mhz	A36	●	●	○	0	433Mhz	Continental	●	●
니산	무라노	2014/10-2019/12	433MHz	Z52	●	●	○	0	433Mhz	Continental	●	●
니산	무라노	2014/01-2014/12	433MHz	Z51/Z52/P42 M	●	●	○	0	433Mhz	Pacific	●	●
니산	무라노	2008/01-2013/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
니산	패스파인더	2015/11-2019/12	433MHz	R52/P61B	●	●	○	0	433Mhz	Continental	●	●
푸조	2008	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
푸조	208	2012/05-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
푸조	208	2002/01-2002/12	433MHz		○	●	○	C	433Mhz	Schrader	●	●
푸조	3008	2013/09-2019/12	433Mhz		●	●	○	0/A	433Mhz	Schrader	●	●
푸조	308	2014/01-2019/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
푸조	308	2013/09-2019/12	433Mhz	T7	●	●	○	0	433Mhz	Schrader	●	●
푸조	308	2007/04-2013/08	433Mhz	T7	●	●	○	0	433Mhz	Schrader	●	●
푸조	407	2004/01-2011/08	433MHz	D2	●	●	○	0	433Mhz	Continental	●	●
푸조	5008	2009/01-2013/08	433MHz	T87	●	●	○	0	433Mhz	Schrader	●	●
푸조	508	2013/10-2019/12	433Mhz	W2	●	●	○	0/A	433Mhz	Schrader	●	●
푸조	508	2010/01-2013/09	433MHz		●	●	○	0	433Mhz	Schrader	●	●
포르쉐	718(982)	2016/01-2018/08	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	911	2013/01-2016/12	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	911	2015/01-2019/12	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
포르쉐	911	2012/02-2016/12	433MHz	991	●	●	○	A	433Mhz	Huf/Beru	●	●
포르쉐	911	2004/07-2012/01	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	911	2005/01-2012/12	315MHz	997	●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	911	2017/01-2019/12	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
포르쉐	911(991)	2011/12-2019/12	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	911(991)	2011/12-2015/08	433MHz	991	●	●	○	A	433Mhz	Huf/Beru	●	●
포르쉐	911(997)	2008/04-2015/08	433MHz	997	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	911(997)	2009/01-2011/12	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	911(997)	2005/01-2008/12	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	911(997)	2005/02-2008/03	433MHz	997	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	911(997)	2015/09-2019/12	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	911(터보)	2010/01-2012/12	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	911(터보)	2010/01-2019/12	433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	911(터보)	2007/01-2009/12	315MHz	997	●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	911(터보)	2007/01-2009/12	433MHz	997	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	918 스파이더	2013/01-2015/12	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	박스터	2009/01-2013/12	433MHz	987	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	박스터	2009/01-2012/12	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	박스터	2017/01-2019/12	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	박스터	2012/01-2016/12	433MHz	981	●	●	○	0/A	433Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
포르쉐	박스터	2013/01-2016/12	315MHz	2. 7L	●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	박스터	2004/01-2008/12	315MHz	987	●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	박스터	2005/02-2008/12	433MHz	987	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	박스터	2016/03-2019/12	433Mhz 982	982	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	Carrera GT	2003/09-2011/12	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	카이엔	2007/01-2010/12	433MHz	9PA1	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	카이엔	2007/01-2010/12	315MHz	9PA1	●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	카이엔	2011/01-2012/12	433MHz	92A	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	카이엔	2013/01-2014/10	433MHz	92A	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	카이엔	2010/09-2016/12	315MHz	92A	●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	카이엔	2018/01-2018/12	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	카이엔	2017/09-2019/12	433MHz	92A	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	카이엔	2014/11-2017/08	433MHz	92A	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	카이엔	2002/01-2006/12	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	카이엔	2002/01-2006/12	433MHz	9PA	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	Cayenne S	2014/06-2017/08	433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	Cayenne S	2007/01-2009/12	433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	Cayenne S	2008/01-2009/12	315MHz	4. 8L	●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	Cayenne S	2010/01-2014/05	433MHz	4. 8L	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	Cayenne S	2010/01-2012/12	315MHz	4. 8L	●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	Cayenne S	2017/09-2019/12	433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	케이맨	2009/01-2011/12	433MHz	987	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	케이맨	2009/01-2012/12	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	케이맨	2013/01-2016/12	315MHz	2. 7L	●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	케이맨	2012/01-2016/12	433MHz	981	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	케이맨	2017/01-2019/12	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
포르쉐	케이맨	2005/01-2008/12	433MHz	987	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	케이맨	2005/01-2008/12	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	Cayman (718)	2016/10-2020/06	982 433MHz	982	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	GT3	2010/01-2016/12	433MHz	996/997	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	GT3	2015/01-2015/12	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
포르쉐	GT3	2017/01-2019/12	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
포르쉐	GT3	2007/01-2009/12	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	GT3	2006/03-2009/12	433Mhz	996	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	마칸	2018/01-2018/12	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	마칸	2014/01-2019/12	433MHz	P0416	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	마칸	2014/01-2015/12	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	파나마라	2010/01-2012/12	315MHz		●	●	○	0/A	315Mhz	Huf/Beru	●	●
포르쉐	파나마라	2017/09-2020/06	433MHz	970	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	파나마라	2014/01-2016/12	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	파나마라	2013/07-2017/08	433MHz	970	●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	파나마라	2009/01-2014/02	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	Panamera S	2009/01-2013/06	433MHz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
포르쉐	Panamera S	2009/06-2013/12	315MHz	4. 8L	●	●	○	0/A	315Mhz	Huf/Beru	●	●
르노삼성	QM3	2013/01-2015/12	433Mhz		●	●	○	0	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
르노삼성	QM3	2016/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
르노삼성	QM5	2009/01-2013/12	315MHz		○	●	○	C	315MHz	Schrader	●	●
르노삼성	QM5	2007/01-2013/12	433MHz		●	●	○	O	433Mhz	Schrader	●	●
르노삼성	QM5	2014/01-2016/12	433Mhz		●	●	○	O	433Mhz	Continental	●	●
르노삼성	QM6	2017/01-2018/12	433Mhz		●	●	○	O	433Mhz	Continental	●	●
르노삼성	SM3	2009/01-2018/12	433Mhz		●	●	○	O	433Mhz	Continental	●	●
르노삼성	SM3 ZE	2015/01-2018/12	433Mhz		●	●	○	O	433Mhz	Continental	●	●
르노삼성	SM5	2010/01-2015/12	433Mhz		●	●	○	O	433Mhz	Continental	●	●
르노삼성	SM5	2016/01-2018/12	433Mhz		●	●	○	O	433Mhz	Continental	●	●
르노삼성	SM6	2015/01-2018/12	433Mhz		●	●	○	O	433Mhz	Continental	●	●
르노삼성	SM7	2012/01-2015/12	433Mhz		●	●	○	O	433Mhz	Continental	●	●
르노삼성	SM7	2016/01-2018/12	433Mhz		●	●	○	O	433Mhz	Continental	●	●
롤스로이스	Cullinan	2018/03-2020/06	433MHz	R31	○	●	○	A	433Mhz	Schrader	●	●
롤스로이스	다운	2016/01-2020/06	433Mhz	RR6	○	●	○	C	433Mhz	Huf/Beru	●	●
롤스로이스	고스트	2010/01-2020/06	433MHz	RR04	○	●	○	C	433Mhz	Huf/Beru	●	●
롤스로이스	팬텀	2012/01-2016/12	433MHz	RR02	○	●	○	A	433Mhz	Huf/Beru	●	●
롤스로이스	팬텀	2017/01-2019/12	PR11 433MHz		○	●	○	A	433Mhz	Schrader	●	●
롤스로이스	컬리넌	2013/08-2020/06	433Mhz	RR04	○	●	○	C	433Mhz	Huf/Beru	●	●
쌍용	엑티온	2018/07-2019/12	Q200 433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
쌍용	엑티온	2014/01-2019/12	QJ 433MHz		○	●	○	A	433Mhz	Schrader	●	●
쌍용	체어맨	2005/01-2013/12	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
쌍용	체어맨	2014/06-2019/12	433Mhz		●	●	○	A	433Mhz	Schrader	●	●
쌍용	코란도	2008/01-2013/12	315MHz		○	●	○	A	315Mhz	Huf/Beru	●	●
쌍용	코란도	2013/08-2019/12	C200 433MHz		○	●	○	A	433Mhz	Schrader	●	●
쌍용	카이런	2006/01-2014/05	315MHz		○	●	○	A	315Mhz	Huf/Beru	●	●
쌍용	카이런	2014/06-2016/09	433Mhz		○	●	○	A	433Mhz	Schrader	●	●
쌍용	무쏘	2016/01-2019/12	433Mhz		○	●	○	A	433Mhz	Schrader	●	●
쌍용	렉스턴	2018/01-2019/12	Y400 433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
쌍용	렉스턴	2014/01-2017/12	Y300 433MHz		●	●	○	A	433Mhz	Schrader	●	●
쌍용	렉스턴	2006/01-2013/12	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
쌍용	Rodius	2014/01-2019/12	AJ 433MHz		○	●	○	A	433Mhz	Schrader	●	●
쌍용	Rodius	2008/01-2013/12	315MHz		○	●	○	A	315Mhz	Huf/Beru	●	●
쌍용	티볼리	2015/05-2019/12	X100 433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
쌍용	Turismo	2014/01-2019/12	AJ 433MHz		○	●	○	A	433Mhz	Schrader	●	●
테슬라	Model 3	2016/01-2020/06	433Mhz		○	●	○	A	433Mhz	Continental	●	●
테슬라	Model S	2014/09-2020/08	433MHz		○	●	○	A	433Mhz	Continental	●	●
테슬라	Model X	2014/10-2020/06	Continental 433Mhz		○	●	○	A	433Mhz	Continental	●	●
도요타	86	2014/01-2020/12	433MHz		●	●	○	O	433Mhz	Pacific	●	●
도요타	아발론	2013/01-2018/04	433Mhz		●	●	○	O	433Mhz	Pacific	●	●
도요타	아발론	2018/04-2019/12	433Mhz	740A	●	●	○	O	433Mhz	Pacific	●	●
도요타	캠리	2014/01-2017/12	433MHz	XV50	●	●	○	O	433MHz	Pacific	●	●
도요타	캠리	2016/01-2019/12	433MHz	045L	●	●	○	O/A	433MHz	Pacific	●	●
도요타	Camry Hybrid	2014/01-2017/09	433MHz	XV50/XV70	●	●	○	O	433MHz	Pacific	●	●
도요타	FJ 크루저	2014/06-2019/12	433MHz	155L	●	●	○	O	433Mhz	Pacific	●	●
도요타	GT86	2014/01-2019/12	433Mhz	E88	●	●	○	O	433Mhz	Pacific	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
도요타	랜드크루저	2014/01-2019/12	433MHZ		●	●	○	0	433Mhz	Pacific	●	●
도요타	Land Cruiser Prado	2014/01-2017/09	433MHz	611L	●	●	○	0	433Mhz	Pacific	●	●
도요타	프리우스	2014/01-2018/12	433Mhz	590L/030A/XW30/XW50/690A/277N	●	●	○	0	433Mhz	Pacific	●	●
도요타	프리우스	2019/01-2019/12	433MHZ		●	●	○	0	433MHZ	Pacific	●	●
도요타	프리우스 C	2014/03-2019/12	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
도요타	프리우스 V	2014/11-2017/11	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
도요타	RAV4	2013/01-2018/12	433Mhz XA40	410A/XA40/120L	●	●	○	0	433Mhz	Pacific	●	●
도요타	씨에나	2014/06-2019/12	433MHz	500N/500L	●	●	○	0	433MHz	Pacific	●	●
도요타	벤자	2014/06-2015/12	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
폭스바겐	비틀	2012/12-2019/12	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
폭스바겐	비틀	2012/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	CC	2011/06-2017/12	433MHz	VC17	●	●	○	0/A	433Mhz	Huf/Beru	●	●
폭스바겐	CC	2018/01-2019/12	MQB 433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
폭스바겐	EOS	2014/01-2015/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	골프	2012/01-2012/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
폭스바겐	골프	2013/01-2020/06	Indirect		○	○	○	S	N/A	N/A	Indirect	●
폭스바겐	제타	2010/01-2018/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	뉴 비틀	2012/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	뉴 비틀	2011/08-2020/06	433MHz		●	●	○	A	433Mhz	Huf/Beru	●	●
폭스바겐	파사트	2014/09-2020/06	433MHz	B8	●	●	○	0/A	433Mhz	Huf/Beru	●	●
폭스바겐	페이톤	2001/12-2007/05	433MHz	VW611	●	●	○	0/A	433Mhz	Huf/Beru	●	●
폭스바겐	페이톤	2010/06-2019/12	433MHz	Vh67	●	●	○	0/A	433Mhz	Huf/Beru	●	●
폭스바겐	폴로	2009/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	티구안	2016/01-2020/06	433MHz	VW376/5N2	●	●	○	0/A	433Mhz	Huf/Beru	●	●
폭스바겐	티구안	2011/05-2015/12	433MHz	5N	●	●	○	0/A	433Mhz	Huf/Beru	●	●
폭스바겐	투아렉	2014/08-2020/06	433Mhz	7P5/7P6108	●	●	○	0/A	433Mhz	Huf/Beru	●	●
폭스바겐	투아렉	2010/01-2014/07	433MHz	VW526	●	●	○	0/A	433Mhz	Huf/Beru	●	●
볼보	C30	2011/01-2013/12	433Mhz	Y279	●	●	○	0/A	433Mhz	Continental	●	●
볼보	C30	2006/01-2010/12	433Mhz	Y279	●	●	○	0/A	433Mhz	Continental	●	●
볼보	C30 일렉트릭	2010/01-2010/12	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
볼보	C30 일렉트릭	2011/01-2013/12	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
볼보	C70	2011/01-2014/06	433Mhz	V70064	●	●	○	0/A	433Mhz	Continental	●	●
볼보	C70	2008/01-2010/12	433Mhz	V70064	●	●	○	0/A	433Mhz	Continental	●	●
볼보	C70	2006/01-2007/12	433Mhz	V70064	●	●	○	0/A	433Mhz	Continental	●	●
볼보	S40	2011/01-2014/06	433Mhz	V40044	●	●	○	0/A	433Mhz	Continental	●	●
볼보	S40	2003/01-2010/12	433Mhz	V40044	●	●	○	0/A	433Mhz	Continental	●	●
볼보	S60	2013/02-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	S60	2010/01-2013/01	315MHz		●	●	○	A	315Mhz	Schrader	●	●
볼보	S60	2010/01-2013/01	433MHz	Y283	●	●	○	0/A	433Mhz	Continental	●	●
볼보	S80	2013/03-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	S80	2006/01-2013/02	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
볼보	S80	2006/01-2013/02	315MHz		●	●	○	A	315Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
볼보	S90	2016/01-2020/06	433Mhz	V541	●	●	○	0/A	433Mhz	Schrader	●	●
볼보	S90	2016/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	V40	2012/01-2020/06	433Mhz	Y555, Y556	●	●	○	0/A	433Mhz	Continental	●	●
볼보	V40	2015/01-2020/06	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	V50	2011/01-2016/12	433MHz	V5004-124	●	●	○	0/A	433Mhz	Continental	●	●
볼보	V60	2017/11-2020/06	433Mhz		●	●	○	0/A	433Mhz	Schrader	●	●
볼보	V60	2015/09-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	V60	2014/07-2019/12	433Mhz 31341893		●	●	○	0/A	433Mhz	Continental	●	●
볼보	V60	2008/01-2014/06	433MHz	Y352	●	●	○	0/A	433Mhz	Continental	●	●
볼보	V70	2007/01-2016/12	433MHz	Y285	●	●	○	0/A	433Mhz	Continental	●	●
볼보	V90	2015/01-2020/06	433Mhz	V542	●	●	○	0/A	433Mhz	Schrader	●	●
볼보	V90	2017/01-2018/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	XC40	2017/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	XC60	2015/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	XC60	2008/05-2019/12	433MHz	Y413	●	●	○	0/A	433Mhz	Continental	●	●
볼보	XC70	2014/07-2017/12	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
볼보	XC70	2010/01-2014/06	433MHz	Y381	●	●	○	0/A	433Mhz	Continental	●	●
볼보	XC70	2008/01-2009/12	433MHz	Y381	●	●	○	0/A	433Mhz	Continental	●	●
볼보	XC90	2016/09-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	XC90	2015/01-2019/12	433MHz	V526	●	●	○	0/A	433Mhz	Schrader	●	●
볼보	XC90	2005/01-2014/12	433MHz	Y289	●	●	○	0/A	433Mhz	Schrader	●	●