AUTEL TS401 Update Remember to check monthly for latest software updates.

Please note: TS401 needs no registration. Updates are performed via a computer with Internet access.



• Go to www.maxitpms.com. Click on Support and select Registration & Update. Click "MaxiLinkII" to download the application.



• Come to Registration & Update website page, click TS401 software update pack to download the zip file.



• Unzip and install MaxiLinkII. Once installed, the MaxiLink2 shortcut displays on the desktop.

	本地磁盘(D:) ▶ 软件 ▶ TS401 ▶	07003627o5x3 -	4 7				
	新建文件夹						
	名称	修改日期	类型				
л	TS401_GL_V5.31.bin	2017/11/20 15:11	BIN				
4	TS401_V5.31.aut	2017/11/20 15:09	AUT				

• Unzip the file. Remember to note the location of extracted folder.



 Use the USB cable to connect the tool to the computer. Select Update Mode on the tool.

· Press Y button to place the tool in Update Mode.

Scan Tools	Open	×	Scan Tools	
TPMS	← → + ↑ □ = 15035104rpb (7) > US v ♂ Search US	P 7	TPMS	Update Program
TS101 TS401 DTC lookup	Organize • New folder	B:: • III 💿 modified Type	TS101 TS401 DIC lockup	Torget Torget
Manual	Control Contro Control Control Control Control Control Co		Manual	
	NE Fotures Biologic sector and V K Filename TS01,V2d1ain V Inter Open	× Cancel		392 2 1164 sur the diverse in Staplish Hole. 394 2 103 - Cell Hole In Staplish Hole In Staplish Hole. 394 4 103 - cell Hole In Start Addres. C Literri Michael ISS000 1948 (7)(1007) 401 (216) 4 and E Literri Film States

AUTEL TS401 Update

Launch MaxiLink2 on the PC and then select TS401 on the left-hand side of the screen under the TPMS tab.
 Under Update Program, click on Select File and browse to the software update you downloaded. Open the folder labeled GL, select the file within (the file extension is .bin) and click on Update.

• The application will communicate with the tool and update. The PC application and the tool will display a message once the update is completed.

Next, under Update DTC, click on Select File, browse to file (the file extension is .aut) and click on Open, and then click on Update.

The application will communicate with the tool and update its software. The PC application and the tool will display
a message once the update is completed.

IMPORTANT: Both the TS401 file and the DTC file must be updated for the tool to function correctly.