



MX-Sensor_V6.12 Function List For EU Market (Note:For reference only)

NOTES:

● This function is supported. ○ This function is not supported. Mark explaining (Red:New, Yellow: Modify)

Special Declaration:

- 1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.
- 2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-----------------|-----------------|----------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Abarth | 124 Spider | 10/2016-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Abarth | 124 Spider | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 4A Grande Punto | 01/2007-12/2010 | 433MHz | 199 | ○ | ● | ○ | C | 433Mhz | TRW | ● | ● |
| Abarth | 4B Punto EVO | 01/2010-12/2013 | 433MHz | 199 | ○ | ● | ○ | A | 433Mhz | TRW | ● | ● |
| Abarth | 500 | 01/2008-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 500 | 01/2008-12/2019 | 433MHz | | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Abarth | 500C | 01/2010-06/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 500C | 08/2011-11/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Abarth | 595 | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 695 Biposto | 01/2015-06/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 81 Nuova Punto | 01/2012-12/2013 | 433MHz | 199 | ○ | ● | ○ | C | 433Mhz | TRW | ● | ● |
| Abarth | Punto Evo | 01/2010-12/2013 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Abarth | Punto Evo | 01/2013-12/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Acura | NSX | 01/2016-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Alfa Romeo | 159 | 07/2005-12/2013 | 433MHz | 939 | ● | ● | ○ | A | 433Mhz | TRW | ● | ● |
| Alfa Romeo | 169 | 11/2015-12/2017 | 433MHz | N936 | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Alfa Romeo | 4C | 01/2013-06/2020 | 433MHz | 960/961 | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Alfa Romeo | 6C | 10/2016-06/2020 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Alfa Romeo | 8C | 12/2006-12/2010 | 433Mhz | 920 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Alfa Romeo | Brera | 01/2005-07/2012 | 433MHz | 939/946 | ● | ● | ○ | C | 433Mhz | TRW | ● | ● |
| Alfa Romeo | Executive | 11/2018-12/2019 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Alfa Romeo | Giulia | 04/2014-12/2016 | 433MHz | UT | ● | ● | ● | 0/A | 433Mhz | Continental | ● | ● |
| Alfa Romeo | Giulia | 01/2016-12/2019 | 433MHz | 952 | ● | ● | ● | 0/A | 433Mhz | Continental | ● | ● |
| Alfa Romeo | Giulietta | 01/2014-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alfa Romeo | Giulietta | 01/2010-12/2013 | 433MHz | | ○ | ● | ○ | C | 433Mhz | TRW | ● | ● |
| Alfa Romeo | Giulietta | 01/2014-06/2020 | 433MHz | 940 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Alfa Romeo | Grand SUV | 11/2018-12/2019 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Alfa Romeo | MiTo | 08/2013-06/2019 | 433MHz | 955 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Alfa Romeo | MiTo | 01/2008-07/2013 | 433MHz | 955 | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| Alfa Romeo | Quadrifoglio | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433Mhz | Continental | ● | ● |
| Alfa Romeo | Quadrifoglio | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Alfa Romeo | Spider | 01/2015-06/2019 | 433MHz | J12A | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Alfa Romeo | Spider | 06/2006-12/2017 | 433MHz | 946 | ○ | ● | ○ | C | 433Mhz | TRW | ● | ● |
| Alfa Romeo | Spider | 01/2006-12/2010 | 433MHz | 939 | ○ | ● | ○ | C | 433Mhz | TRW | ● | ● |
| Alfa Romeo | Stelvio | 01/2017-06/2020 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Alpina | Alpina 3 | 01/2013-12/2019 | 433MHz | F30/F32 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|------------------|-----------------|----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Alpina | Alpina 3 | 10/2018-12/2019 | 433Mhz | G20 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | Alpina 3 | 01/2002-06/2006 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | Alpina 3 | 10/2009-12/2012 | 433MHz | E90 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | Alpina 3 | 07/2006-09/2009 | 433MHz | E90/E91/E92 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | Alpina 4 | 07/2013-06/2020 | (F32/F33/F36) 433MHz | F30/F32 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Alpina | Alpina 5 | 02/2017-06/2020 | G30 433MHz | | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Alpina | Alpina 5 | 03/2014-01/2017 | 433MHz | F10 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | Alpina 5 | 01/2010-02/2014 | 433MHz | F10 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | Alpina 5 | 01/2005-12/2009 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | Alpina 6 | 03/2014-12/2019 | 433MHz | F12 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | Alpina 6 | 12/2010-02/2014 | 433MHz | F12 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | Alpina 6 | 03/2006-11/2010 | 433MHz | E63 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | Alpina 7 | 01/2016-12/2019 | 433MHz | G11 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Alpina | Alpina 7 | 09/2010-12/2015 | 433MHz | F01 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | D3 | 03/2014-12/2019 | 433MHz | F30/F32 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Alpina | D3 | 01/2008-02/2014 | 433MHz | E90 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | D4 | 07/2013-06/2020 | 433MHz | F30/F32 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Alpina | D5 | 02/2010-03/2014 | 433MHz | E90 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | D5 | 04/2014-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | XD3 | 03/2014-06/2018 | 433MHz | F25 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | XD3 | 09/2010-02/2014 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | XD3 | 01/2018-06/2020 | 433Mhz | G01 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Alpina | XD3 | 09/2010-03/2014 | 433MHz | F25 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Alpina | XD4 | 09/2018-06/2020 | 433Mhz | G02 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Aston Martin | Cygnat | 01/2011-06/2018 | 433MHz | | ● | ● | ○ | A | 433Mhz | Pacific | ● | ● |
| Aston Martin | DB11 | 01/2016-06/2020 | 433Mhz | VH500 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Aston Martin | DB9 | 01/2005-12/2011 | Smartire 433MHz | | ○ | ● | ○ | C | 433Mhz | Smartire | ● | ● |
| Aston Martin | DB9 | 01/2004-01/2018 | 433Mhz | AM803 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 09/2007-08/2012 | 433Mhz | AM803 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 09/2012-12/2015 | 433MHz | AM803 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 01/2018-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Aston Martin | DBS Superleggera | 01/2018-06/2020 | 433Mhz | VH500 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Aston Martin | DBX | 10/2018-06/2020 | SCH 433Mhz | | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Aston Martin | DBX | 04/2020-12/2020 | HUF 433MHz | | ○ | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Aston Martin | One-77 | 01/2011-12/2012 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Aston Martin | Rapide | 03/2010-06/2020 | 433MHz | VH400 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Aston Martin | Rapide S | 01/2010-12/2019 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Aston Martin | V12 Zagato | 09/2012-12/2015 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Aston Martin | Vanquish | 10/2012-12/2019 | 433MHz | AM310 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Aston Martin | Vantage | 07/2005-06/2020 | 433MHz | AM305 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Aston Martin | Vantage | 01/2005-12/2011 | Smartire 433MHz | | ○ | ● | ○ | C | 433Mhz | Smartire | ● | ● |
| Aston Martin | Virage | 01/2011-12/2012 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Aston Martin | Zagato | 01/2011-08/2012 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------|-----------------|---------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Audi | A1 | 06/2010-06/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | A3 | 01/2005-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A3 | 06/2012-06/2020 | 433MHz | 8L | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A4 | 01/2012-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A4 | 08/2008-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A4 | 11/1996-12/2010 | 433MHz | B7 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A4 Allroad | 03/2009-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A4 Avant | 01/2018-06/2020 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A5 | 12/2006-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A5 | 12/2006-06/2020 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A6 | 06/2009-12/2010 | 433MHz | 4F | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A6 | 07/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 | 05/2004-05/2009 | 433MHz | 4B | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2009-12/2011 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 | 01/2011-06/2020 | 433MHz | 4G | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 01/2006-10/2009 | 433MHz | 4B | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 04/2000-12/2005 | 433Mhz | 4B | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 11/2009-12/2019 | 433MHz | 4G | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 01/2013-06/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 Allroad | 07/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 Allroad | 10/2018-06/2020 | 433MHz 5Q0907275 | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A6 Avant | 03/2004-01/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A6 Avant | 04/1997-02/2004 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A6 Avant | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 Quattro | 06/2009-12/2010 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A6 Quattro | 01/2011-12/2015 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A6 Quattro | 01/2004-05/2009 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A7 | 01/2012-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A7 | 01/2009-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A7 | 09/2010-06/2020 | 433MHz 5Q0907275 | 4G | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A8 | 01/2009-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A8 | 01/1999-09/2002 | 433MHz | 4D | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A8 | 01/2016-06/2020 | 433MHz 5Q0907275 | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A8 | 10/2002-10/2009 | 433Mhz | 4E | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A8 | 11/2009-10/2017 | 433Mhz | 4H/4L | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | A9 | 01/2018-06/2020 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | C-MPV | 03/2009-12/2018 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | Q2 | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | Q2 | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q3 | 07/2011-06/2020 | 433MHz | 8U | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | Q3 | 06/2011-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q4 | 10/2019-12/2020 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | Q5 | 09/2008-06/2020 | 433MHz | 8R | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------|-----------------|----------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Audi | Q5 | 01/2008-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q7 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q7 | 09/2005-12/2014 | 433MHz | 4L/AU716 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2015-06/2020 | 433MHz | 4L/AU726 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Audi | Q8 | 01/2018-06/2020 | 433MHz | 4M | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | R8 | 06/2009-03/2015 | 433MHz | AU714 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2006-05/2009 | 433MHz | AU714 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | R8 | 04/2015-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | RS3 | 10/2016-12/2019 | 433MHz | 8V | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | RS3 | 01/2013-12/2016 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS4 | 01/2012-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS4 | 01/2018-06/2020 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | RS4 | 04/2006-12/2018 | 433MHz | 8E/B7 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | RS5 | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS5 | 01/2017-12/2019 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS6 | 01/2000-12/2005 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2008-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | RS6/RS6 Plus | 04/2000-09/2005 | 433MHz | 4B | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | RS6/RS6 Plus | 01/2008-12/2010 | 433MHz | C6 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | RS6/RS6 Plus | 01/2013-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | RS7 | 03/2018-06/2020 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2010-02/2018 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S1 | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S3 | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S4 | 01/2004-12/2007 | 433MHz | B7 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | S6 | 07/2009-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2004-06/2009 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Audi | S8 | 09/1999-09/2002 | 433MHz | D2 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | S8 | 10/2002-10/2009 | 433MHz | D3 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | S8 | 11/2009-10/2017 | 433MHz | D4 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | S8 | 11/2017-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | SQ2 | 01/2019-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ5 | 01/2014-06/2020 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | SQ5 | 01/2014-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ7 | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ7 | 01/2016-12/2019 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | TT | 02/2014-06/2020 | 433MHz | AU334 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | TT | 04/2006-02/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TT | 03/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TT RS | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | TTS | 01/2012-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | e-tron | 11/2018-06/2020 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------|-----------------|-----------------------|-----------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| BAIC | BJ40 | 01/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | BJ40L | 06/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | BJ40L Golden | 06/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | BJ80 | 01/2016-12/2016 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | BJ80 | 01/2017-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| BAIC | EH Series | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | EU Series | 01/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | EX3 | 06/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | EX5 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | S3L | 01/2016-06/2018 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| BAIC | S5 | 01/2017-06/2018 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| BAIC | S6 | 11/2015-06/2018 | 433Mhz | | ● | ● | ○ | 0/A | 433MHz | BAIC | ● | ● |
| BAIC | S7 | 01/2017-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| BAIC | Senova CC | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | Senova D50 | 01/2014-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | Senova D70 | 01/2013-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | Senova X35 | 01/2016-12/2016 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | Senova X55 | 01/2016-12/2016 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | Senova X65 | 01/2015-12/2015 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BAIC | WeiWang S50 | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| BMW | 1 Series | 07/2010-06/2020 | 433MHz | F20/F21/F40 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | 1 Series | 03/2014-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 1 Series | 09/2010-02/2014 | 433MHz | E88/E82 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 1 Series | 12/2006-08/2010 | 433MHz | E88/E82 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 2 Series | 01/2014-12/2019 | 433Mhz | F22/F23/F45/F46 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | 3 Series | 12/2018-06/2020 | 433Mhz | G20 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 3 Series | 10/2010-11/2013 | 433MHz | F30 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 3 Series | 09/2009-09/2010 | 433MHz | E9x | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 3 Series | 01/2006-08/2009 | 433MHz | E9x | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 3 Series | 03/1999-12/2011 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 3 Series | 01/1999-12/2005 | 433MHz | E46 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 3 Series | 01/2014-12/2019 | 433Mhz | F31/F35 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | 3 Series GT | 03/2014-12/2019 | 433MHz | F34 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | 4 Series | 03/2014-06/2020 | F32/F33/F36 433MHz | F32/F33/F36 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | 5 Series | 01/2001-12/2006 | 433MHz | E65 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series | 09/1998-07/2003 | 433MHz | E39 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series | 03/2006-08/2010 | 433MHz | E60/E61/F07 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series | 09/2010-02/2015 | 433MHz | F10/F11/F07/F18 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series | 03/2014-12/2017 | 433MHz | F10/F11 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series | 01/2017-12/2019 | 433Mhz | G30/G31/G38 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | 5 Series GT | 04/2014-12/2018 | 433MHz | F07 LCI | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 01/2011-12/2016 | 433MHz | F10/F07 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 01/2017-12/2019 | 433Mhz | G32 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------|-----------------|----------------|-----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | 6 Series | 01/2010-02/2014 | 433MHz | F12/F13/F06 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 6 Series | 03/2014-12/2019 | 433MHz | F12/F13/F06 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 6 Series | 09/2016-06/2020 | 433Mhz G14/G32 | G14/G32 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | 6 Series | 01/2006-12/2009 | 433MHz | E63/E64 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 7 Series | 09/2010-02/2014 | 433MHz | F01/F02/F03/F04 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 7 Series | 03/2014-05/2015 | 433MHz | F01/F02/F03/F04 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 7 Series | 06/2015-06/2020 | 433Mhz | G11/G12 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | 7 Series | 01/2006-08/2010 | 433MHz | E65/E66 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 7 Series | 09/1998-12/2005 | 433MHz | E38 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 8 Series | 10/2017-06/2020 | 433Mhz | G15 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | M2 | 11/2014-12/2019 | 433MHz | F87 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | M3 | 01/2007-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M3 | 01/2014-12/2018 | 433Mhz | F80 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | M3 | 01/1999-12/2006 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | M4 | 04/2014-12/2019 | 433Mhz | F82/F83 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | M5 | 01/2018-06/2020 | 433Mhz (F90) | F90 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | M5 | 03/2014-12/2017 | 433MHz | F10 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | M6 | 03/2014-12/2018 | 433MHz | F12 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | M7 | 03/2014-12/2017 | 433MHz | F01 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | M8 | 01/2019-06/2020 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | Motorcycle | 01/2010-12/2019 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| BMW | X1 | 03/2014-09/2015 | 433MHz | E84 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X1 | 09/2008-02/2014 | 433MHz | E84 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X1 | 08/2015-12/2019 | 433MHz | F48 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | X2 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | X3 | 03/2003-10/2010 | 433MHz | E83 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X3 | 11/2010-03/2014 | 433MHz | F25 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X3 | 04/2014-12/2017 | 433Mhz | F25 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X3 | 01/2017-06/2020 | G01/G08 433MHz | | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | X4 | 03/2017-06/2020 | 433Mhz | G02 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | X4 | 05/2013-12/2019 | 433MHz | F26 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X5 | 10/1999-10/2006 | 433MHz | E53 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X5 | 09/2017-06/2020 | 433MHz | G05 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | X5 | 05/2013-12/2019 | 433Mhz | F15/F85 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | X5 | 10/2010-06/2013 | 433MHz | E70 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X5 | 01/2007-12/2010 | Indirect (E70) | E70 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X5 | 11/2006-09/2010 | 433MHz | E70 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X6 | 01/2020-06/2020 | 433Mhz | | ● | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| BMW | X6 | 12/2007-11/2011 | 433MHz | E71 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X6 | 12/2011-07/2014 | 433MHz | E71 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X6 | 08/2014-12/2019 | 433MHz | F16/F86 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | X6 HYBRID | 07/2012-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------------------|-----------------|----------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| BMW | X7 | 01/2018-12/2019 | 433Mhz | G02 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | Z4 | 03/2019-06/2020 | 433Mhz | G02 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | Z4 | 09/2010-02/2014 | 433MHz | E89/E71 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | Z4 | 03/2014-02/2019 | 433MHz | E89 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | Z4 | 03/2006-08/2010 | 433MHz | E86/E89 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | i3 | 01/2013-12/2019 | 433Mhz | I01/I12 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | i8 | 01/2013-12/2019 | 433MHz | I01/I12 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BORGWARD | BX5 | 01/2016-12/2019 | 433Mhz | | ● | ● | ○ | O | 433Mhz | DIAS | ● | ● |
| BORGWARD | BX7 | 01/2016-12/2019 | 433Mhz | | ● | ● | ○ | O | 433Mhz | DIAS | ● | ● |
| BYD | E5 | 01/2016-06/2019 | 433Mhz | | ● | ● | ○ | O | 433Mhz | BYD | ● | ● |
| BYD | E6 | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| BYD | G5 | 01/2014-12/2015 | 433Mhz | | ● | ● | ○ | O | 433Mhz | BYD | ● | ● |
| BYD | G6 | 01/2011-12/2015 | 433Mhz | | ● | ● | ○ | O | 433Mhz | BYD | ● | ● |
| BYD | Qin | 01/2015-06/2019 | 433Mhz | | ● | ● | ○ | O | 433MHz | BYD | ● | ● |
| BYD | Qin NEW | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| BYD | Qin Pro | 01/2018-12/2019 | SCH 433Mhz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| BYD | S7 | 01/2015-06/2018 | 433Mhz | | ● | ● | ○ | O | 433Mhz | BYD | ● | ● |
| BYD | Sirui | 01/2013-12/2015 | 433Mhz | | ● | ● | ○ | O | 433Mhz | BYD | ● | ● |
| BYD | Song | 01/2018-06/2019 | Baolong 433MHz | | ○ | ● | ○ | C | 433Mhz | Baolong | ● | ● |
| BYD | Song | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| BYD | Song | 01/2016-12/2017 | 433Mhz | | ● | ● | ○ | O | 433Mhz | BYD | ● | ● |
| BYD | Song MAX | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| BYD | Surui | 01/2015-12/2016 | 433Mhz | | ● | ● | ○ | O | 433Mhz | BYD | ● | ● |
| BYD | Tang | 01/2015-12/2017 | 433Mhz | | ● | ● | ○ | O | 433Mhz | BYD | ● | ● |
| BYD | Tang | 01/2018-12/2019 | SCH 433Mhz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| BYD | Tang NEW | 01/2017-06/2019 | 433Mhz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| BYD | Yuan | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| BYD | Yuan | 01/2016-12/2017 | 433Mhz | | ● | ● | ○ | O | 433Mhz | BYD | ● | ● |
| BYD | Yuan EV | 06/2018-12/2019 | SCH 433Mhz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Bentley | Arnage | 01/2008-09/2011 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bentley | Azure | 01/2007-12/2018 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bentley | Bentayga | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bentley | Brooklands | 01/2008-12/2011 | 433Mhz | | ● | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Bentley | Brooklands Coupe | 01/2008-06/2016 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bentley | Continental | 03/2014-06/2018 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2006-12/2011 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bentley | Continental Flying Spur | 03/2005-06/2020 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 09/2003-05/2005 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 06/2005-06/2020 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2011-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bentley | GTC | 07/2006-06/2020 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2010-06/2020 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BlueSG | Car Share | 01/2011-12/2011 | 433Mhz | | ○ | ● | ○ | C | 433Mhz | Alligator | ● | ● |
| Bugatti | Chiron | 01/2016-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------|-----------------|--------------------|-----------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Bugatti | Royale | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bugatti | Veyron | 01/2005-12/2015 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Bugatti | Vitesse | 01/2016-12/2016 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Buick | Park Avenue | 01/1997-12/2005 | 433MHz | G-CAR | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| CMC | A180 | 07/2016-12/2019 | 433MHz | | ● | ● | ○ | O | 433Mhz | Orange Electronic | ● | ● |
| CMC | A190 | 07/2016-12/2019 | 433MHz | | ● | ● | ○ | O | 433Mhz | Orange Electronic | ● | ● |
| CMC | VERYCA | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| CMC | ZINGER | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Cadillac | ATS | 01/2016-12/2019 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | ATS | 01/2015-12/2015 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | ATS | 01/2014-12/2014 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | ATS | 01/2013-12/2013 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | ATS | 01/2012-12/2012 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2016-12/2016 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2015-12/2015 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Cadillac | BLS | 01/2006-12/2010 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2016-12/2019 | 433Mhz 13598773 | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2019-06/2020 | 433MHz 13516165 | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | CTS | 01/2017-12/2019 | 433MHz | GMX322 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Cadillac | CTS | 01/2009-12/2009 | 433MHz | GMX206/ GMX226 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | CTS | 01/2016-06/2020 | 433MHz | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | CTS | 01/2006-12/2007 | 433MHz | GMX322 | ● | ● | ○ | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | CTS | 01/2008-12/2008 | 433MHz | GMX206/ GMX226 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Cadillac | CTS | 01/2010-12/2013 | 433MHz | GMX206/ GMX226 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | CTS | 06/2013-12/2013 | 433MHz | A1LL | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2014 | 433MHz | GMX206/ GMX226 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2016 | 433MHz | GMX322 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Cadillac | CTS | 06/2013-12/2013 | 433MHz | GMX322 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Cadillac | CTS | 01/2015-12/2015 | 433MHz | GMX206/ GMX226 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2016-12/2019 | 433MHz | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | ELR | 01/2016-06/2018 | 433MHz | D1BLI | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2015-12/2019 | 433MHz | GMT900/ GMTK2XL/ K2UL | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2014-12/2014 | 433MHz | GMT900/ GMTK2XL/ K2UL | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2013-12/2013 | 433MHz | GMT900/ GMTK2XL | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|----------------------|----------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Cadillac | Escalade | 01/2012-12/2012 | 433MHz | GMT900/GMTK2XL | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2009-12/2011 | 433MHz | GMT926 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2007-12/2008 | 433MHz | GMT926 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | Escalade | 12/2005-12/2006 | 433MHz | GMT926 | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Cadillac | SRX | 01/2016-12/2016 | 433MHz | C1UL | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | SRX | 01/2014-12/2016 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | SRX | 01/2013-12/2013 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | SRX | 01/2010-12/2012 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | SRX | 06/2009-12/2009 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | SRX | 01/2009-12/2009 | 433MHz | GMT265 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | SRX | 01/2007-12/2008 | 433MHz | GMT265 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | SRX | 01/2005-12/2006 | 433MHz | GMT265 | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | STS | 01/2005-12/2007 | 433MHz | GMX295 | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | STS | 01/2008-06/2011 | 433MHz | GMX295 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | XLR | 01/2004-12/2009 | 433Mhz | | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | XT4 | 11/2018-06/2020 | 433MHz | E2UL | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2016-12/2018 | 433Mhz 13598773 | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2018-06/2020 | 433Mhz 13516165 | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | XT6 | 01/2019-06/2020 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Cadillac | XTS | 01/2012-12/2012 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | XTS | 01/2013-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Cadillac | XTS | 01/2015-12/2018 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| ChangAn | CS35 | 01/2016-12/2017 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | BAOLONG | ● | ● |
| ChangAn | CS35 | 01/2015-12/2015 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | BAOLONG | ● | ● |
| ChangAn | CS35 Plus | 01/2018-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS55 | 01/2017-12/2019 | Lo Confi 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS55 | 01/2017-12/2019 | Hi Confi 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 | 01/2014-12/2016 | 2WD 433Mhz | | ● | ● | ○ | 0 | 433MHz | BAOLONG | ● | ● |
| ChangAn | CS75 | 01/2014-12/2016 | 4WD 433Mhz | | ● | ● | ○ | 0 | 433MHz | BAOLONG | ● | ● |
| ChangAn | CS75 | 01/2017-12/2019 | 2WD 433Mhz | | ● | ● | ○ | 0 | 433MHz | BAOLONG | ● | ● |
| ChangAn | CS75 | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | BAOLONG | ● | ● |
| ChangAn | CS85 | 03/2019-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS95 | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | BAOLONG | ● | ● |
| ChangAn | CX70 | 01/2016-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| ChangAn | EADO | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | LINMAX | 01/2017-12/2018 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| ChangAn | OuShang | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| ChangAn | OuShang | 01/2017-12/2019 | 3B 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| ChangAn | Roeton | 01/2017-12/2018 | 433Mhz 3601010W10 | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| ChangAn | Roeton | 01/2013-12/2017 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-------------|-----------------|-----------------|---------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| ChangAn | Roeton CC | 01/2017-12/2019 | Lo Confi 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | Roeton CC | 01/2017-12/2019 | Hi Confi 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | ARRIZO 5 | 01/2016-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| Chery | ARRIZO 5 | 07/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Chery | Arrizo | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Chery | E3 | 01/2013-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Chery | ● | ● |
| Chery | Fulwin | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Chery | QQ | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Chery | Tiggo | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Chery | Tiggo 3 | 01/2016-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Chery | Tiggo 3 | 07/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Chery | Tiggo 3xe | 07/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Chery | Tiggo 3xe | 01/2018-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| Chery | Tiggo 5 | 01/2013-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Chery | Tiggo 5e | 07/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Chery | Tiggo 5e | 01/2017-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| Chery | Tiggo 7 | 06/2016-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Chery | Tiggo 7 | 07/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Chery | Tiggo 7 NEW | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| Chery | Tiggo 8 | 01/2018-06/2018 | Baolong 433MHz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| Chery | Tiggo 8 | 01/2018-12/2019 | VDO 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Chevrolet | Aveo | 01/2015-06/2020 | 433MHz | G1SC/G1JC/T250/T300 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Aveo | 10/2010-12/2010 | 433MHz | G1SC/G1JC/T300 | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2011-05/2012 | 433MHz | G1SC/G1JC/T300 | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Aveo | 06/2012-12/2012 | 433MHz | G1SC/G1JC/T300 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2013-12/2014 | 433MHz | G1SC/G1JC/T250/T300 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Bolt EV | 01/2017-06/2020 | 433Mhz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2012-12/2012 | 433MHz | GMX521 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2013-12/2013 | 433MHz | GMX521 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2014-12/2015 | 433MHz | GMX521 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2010-12/2011 | 433MHz | GMX521 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2016-12/2016 | 433MHz | 1AG37/A1BC | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2017-06/2020 | 433MHz | 1AG37/A1BC | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Captiva | 01/2012-12/2019 | 433Mhz 25789964 | C100 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Captiva | 06/2006-12/2008 | 433Mhz | C100 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------------|-----------------|-----------------|---------------------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Captiva | 01/2009-12/2011 | 433Mhz | C100 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2015-12/2019 | 433MHz | G1LC | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2012-12/2014 | 433MHz | G1LC | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Chevrolet | Colorado | 07/2011-12/2012 | 433MHz | GMI700 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2013-12/2017 | 433MHz | GMI700 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Colorado (LCV) | 07/2006-12/2012 | 433MHz | GMT355 | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Colorado (LCV) | 01/2003-06/2006 | 433MHz | GMT355 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2015-12/2019 | C7 433MHz | GMX245 | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Chevrolet | Corvette | 06/2004-12/2009 | C6 433MHz | GMX245 | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2010-12/2013 | C6 433MHz | GMX245 | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2014-12/2019 | C7 433MHz | Y1BC | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2013-12/2015 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2011-12/2011 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Cruze | 10/2008-12/2010 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2012-12/2012 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2016-12/2018 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2019-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Epica | 01/2006-12/2011 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2020-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2009-12/2013 | 433MHz | GMT610 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Express Series | 07/2007-12/2008 | 433MHz | GMT610 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Express Series | 07/2002-06/2007 | 433MHz | GMT610 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2014-06/2020 | 433MHz | GMT610 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Lacetti | 06/2003-12/2014 | Clamp in 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Lacetti | 06/2003-12/2014 | Snap in 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2013-06/2014 | 433MHz | V300 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2011-06/2012 | 433MHz | V300 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2012-12/2012 | 433MHz | V300 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2016-12/2016 | 433MHz | V300/ GMX351/ GMX386 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2017-12/2019 | 433MHz | V300 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-------------|-----------------|---------|----------------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Malibu | 07/2014-12/2015 | 433MHz | V300/ GMX351/ GMX386 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Malibu | 06/2010-06/2011 | 433MHz | V300 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Chevrolet | Matiz | 01/2001-03/2005 | 433MHz | M100 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Matiz | 06/2014-12/2019 | 433MHz | M100 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Chevrolet | Matiz | 04/2005-06/2014 | 433MHz | M200 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Niva | 06/2014-06/2020 | 433MHz | | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2017-06/2020 | 433MHz | J309 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2012-12/2012 | 433MHz | J309 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2015-12/2016 | 433MHz | J309/D1NC | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Orlando | 09/2010-12/2011 | 433MHz | J309 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2013-12/2014 | 433MHz | J309 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2014-12/2014 | 433MHz | K2XC | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2015-12/2019 | 433MHz | K2XC | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2013-12/2014 | 433MHz | M1JC | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Spark | 07/2009-12/2012 | 433MHz | M1JC | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2005-06/2009 | 433MHz | M200 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2015-12/2015 | 433MHz | M1JC | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2016-06/2020 | 433MHz | M1JC | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2015-12/2015 | 433MHz | GMT931 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2016-12/2018 | 433MHz | GMT931 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2006-12/2006 | 433MHz | GMT931 | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2007-12/2008 | 433MHz | GMT931 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2009-12/2013 | 433MHz | GMT931 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2014-12/2014 | 433MHz | GMT931 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2015-12/2015 | 433MHz | GMT921 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2014-12/2014 | 433MHz | GMT921 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2016-12/2019 | 433MHz | GMT921 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Tracker | 07/2013-12/2014 | 433MHz | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2015-06/2020 | 433MHz | | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2009-12/2009 | 433MHz | | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2006-12/2008 | 433MHz | GMT360 | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2001-12/2005 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2013-12/2014 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2010-12/2012 | 433MHz | C105 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2018-06/2020 | 433Mhz | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2012-12/2012 | 433MHz | G1UC | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2013-12/2014 | 433MHz | G1UC | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2015-06/2020 | 433MHz | G1UC | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2016-12/2018 | 433MHz | D1JCI | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Volt | 06/2010-12/2012 | 433MHz | D1JCI | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2013-12/2014 | 433MHz | D1JCI | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Volt | 06/2015-06/2018 | 433MHz | D2JCI | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2015-12/2015 | 433MHz | D1JCI | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chrysler | 200 | 01/2015-12/2019 | 433MHz | | ● | ● | ● | O/A | 433Mhz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------------|-----------------|----------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chrysler | 300 | 01/2011-12/2013 | 433MHz | LX | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Chrysler | 300 | 01/2018-12/2019 | 433MHz | LE48 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Chrysler | 300 | 01/2014-12/2017 | 433MHz | LE48 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Chrysler | 300 | 01/2014-12/2017 | 433MHz | LX | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Chrysler | 300 | 06/2005-06/2010 | 433MHz | LE48 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Chrysler | 300 | 01/2009-12/2010 | 433MHz | LX | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Chrysler | 300C | 06/2010-12/2019 | 18 inch 433Mhz | | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Chrysler | 300C | 06/2010-12/2019 | 20 inch 433Mhz | | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Chrysler | 300C | 06/2005-05/2010 | 433MHz | LE48 | ● | ● | ● | O/A | 433Mhz | Continental | ● | ● |
| Chrysler | Crossfire | 01/2004-12/2008 | 433MHz | | ● | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Chrysler | Delta | 01/2008-12/2012 | 433MHz | | ○ | ● | ○ | C | 433Mhz | TRW | ● | ● |
| Chrysler | Delta | 01/2013-12/2017 | 433MHz | 844 | ● | ● | ○ | O | 433Mhz | TRW | ● | ● |
| Chrysler | Grand Voyager | 01/2016-12/2019 | 433MHz | RU | ● | ● | ● | O/A | 433Mhz | Continental | ● | ● |
| Chrysler | Grand Voyager | 01/2007-12/2010 | 433MHz | RT | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Chrysler | Grand Voyager | 01/2011-12/2019 | 433MHz | RT | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chrysler | Pacifica | 01/2004-12/2005 | 433MHz | | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Chrysler | Pacifica | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O/A | 433Mhz | Continental | ● | ● |
| Chrysler | Sebring | 06/2006-12/2015 | 433MHz | | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2007-12/2010 | 433MHz | | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2011-12/2013 | 433MHz | RT | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2014-12/2016 | 433MHz | RT | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Chrysler | Viper | 09/2012-12/2017 | 433MHz | | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Chrysler | Voyager | 01/2011-12/2019 | 433MHz | RT | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Chrysler | Voyager | 01/2007-12/2010 | 433MHz | RT | ● | ● | ● | O | 433Mhz | Continental | ● | ● |
| Chrysler | Ypsilon | 04/2011-06/2019 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Chrysler | Ypsilon | 01/2011-06/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Chrysler | Ypsilon | 01/2008-03/2011 | 433MHz | | ○ | ● | ○ | C | 433Mhz | TRW | ● | ● |
| Citroen | Berlingo | 03/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | Berlingo | 10/2013-12/2019 | 433MHz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Citroen | Berlingo | 05/2008-09/2013 | 433MHz | B9 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Citroen | C-Cactus | 07/2014-12/2016 | 433MHz | B71 | ● | ● | ○ | O/S | 433Mhz | Schrader | ● | ● |
| Citroen | C-Elysee | 09/2012-12/2019 | 433MHz | M3/M4 | ● | ● | ○ | O/S | 433Mhz | Schrader | ● | ● |
| Citroen | C-ZERO | 01/2011-12/2019 | 433Mhz | | ● | ● | ○ | O/S | 433Mhz | Continental | ● | ● |
| Citroen | C1 | 06/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C3 | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | O/S | 433Mhz | Schrader | ● | ● |
| Citroen | C3 | 01/2010-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Citroen | C3 | 09/2009-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C4 | 10/2013-12/2019 | 433MHz | B58 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Citroen | C4 | 01/2004-09/2013 | 433MHz | B53/B7 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Citroen | C4 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | C4 | 09/2004-07/2008 | 433MHz | B5 | ● | ● | ○ | O | 433Mhz | Continental | ● | ● |
| Citroen | C4 Aircross | 04/2012-12/2019 | 433MHz | | ● | ● | ○ | O/S | 433Mhz | Continental | ● | ● |
| Citroen | C5 | 09/2013-12/2019 | 433MHz | X7 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Citroen | C5 | 08/2004-08/2013 | 433MHz | X3/X40 | ● | ● | ○ | O | 433Mhz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Citroen | C5 | 03/2001-07/2004 | 433Mhz | X40 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | C5(LCV) | 10/2007-12/2015 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | C6 | 09/2005-05/2013 | 433MHz | X6 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Citroen | C8 | 10/2005-12/2015 | 433MHz | V3 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Citroen | C8 | 06/2002-09/2005 | 433MHz | V3 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | C8 | 07/2014-06/2018 | 433MHz | A55 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Citroen | DS3 | 12/2009-12/2014 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | DS3 | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | DS3 | 01/2015-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | DS4 | 12/2010-01/2014 | 433MHz | B75 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | DS4 | 02/2014-12/2019 | 433MHz | B81 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Citroen | DS4 Crossback | 03/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | DS4(LCV) | 12/2010-01/2014 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | DS5 | 01/2011-01/2014 | 433MHz | B81 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | DS5 | 02/2014-12/2019 | 433MHz | X2/50 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | DS5(LCV) | 06/2011-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | DS6 | 01/2016-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | DS7 | 03/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | DS9 | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Citroen | E-Mehari | 10/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | Jumper | 01/2006-05/2014 | 433MHz | B9 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | Jumper | 05/2006-04/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Jumper Combi | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Citroen | Jumper Combi 2 | 01/2007-06/2014 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | Jumper Combi 2 | 07/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | Jumper/Relay | 05/2014-12/2019 | BUS 433MHz | B58 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | Jumper/Relay | 05/2014-12/2019 | VAN 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Citroen | Jumpy | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Jumpy Combi 3 | 01/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Jumpy/Dispatch | 01/2011-09/2014 | 433MHz 9677130580 | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | Jumpy/Dispatch | 11/2013-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Citroen | Nemo | 10/2007-09/2014 | 433MHz | B53/B7 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Citroen | Nemo | 01/2008-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Nemo | 10/2014-12/2019 | 433MHz | B53/B7 | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Citroen | Relay | 01/2013-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Citroen | Relay | 05/2006-05/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Space Tourer | 10/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| DFM | 580 | 01/2016-06/2018 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFM | 580 | 01/2017-12/2019 | SA04 433Mhz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFM | 580 | 01/2017-12/2019 | SA02/SA03 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | CM7 | 01/2014-12/2016 | Snap in 433Mhz | | ● | ● | ○ | 0 | 433Mhz | DIAS | ● | ● |
| DFM | CM7 | 01/2014-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | DFPV A30 | 01/2017-12/2017 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|---------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| DFM | DFPV A9 | 01/2016-12/2016 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| DFM | DFPV AX4 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| DFM | DFPV AX5 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| DFM | DFPV AX7 | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| DFM | F600 | 01/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | Jingyi S50 | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | Jingyi S50 EV | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| DFM | Jingyi S50 EV | 01/2018-06/2019 | BaoLong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | Jingyi X5 | 01/2014-06/2019 | Snap in 433MHz | | ● | ● | ○ | 0 | 433Mhz | DIAS | ● | ● |
| DFM | Jingyi X5 | 01/2014-06/2019 | Clamp in 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | Jingyi X5 | 06/2017-12/2019 | Continental 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| DFM | M6 | 01/2018-12/2019 | BaoLong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | M6 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| DFM | M7 | 01/2018-12/2019 | BaoLong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | M7 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| DFM | MX5 | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| DFM | MX6 | 01/2015-12/2016 | QY1036 433MHz | | ○ | ● | ○ | C | 433Mhz | Baolong | ● | ● |
| DFM | MX6 | 07/2015-12/2016 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Baolong | ● | ● |
| DFM | S500 | 11/2015-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | S560 | 01/2018-06/2019 | SA02/SA03 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | S560 | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFM | S560 | 01/2018-06/2019 | SA04 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFM | SX6 | 01/2018-12/2019 | BaoLong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | SX6 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | T5 | 01/2018-12/2019 | BaoLong 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | T5 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| DFM | X6 | 01/2017-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFM | ix5 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Dacia | Dokker | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Dokker | 01/2014-12/2019 | SD 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Dacia | Duster | 02/2010-12/2019 | SD 433MHz | H79 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Dacia | Duster | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Lodgy | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Lodgy | 01/2012-12/2019 | SD 433MHz | J92 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Dacia | Logan | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Logan | 11/2012-12/2019 | SD 433MHz | L52/K52 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Dacia | Oroch Pickup | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Sandero | 10/2012-12/2019 | SD 433MHz | B52 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|----------------|-----------------|----------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Dacia | Sandero | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Daewoo | Genra | 08/2013-12/2016 | 433Mhz | J200 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Daewoo | Matiz Kasten | 09/1998-06/2018 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Daewoo | Nexia | 06/2014-12/2016 | 433Mhz | T-CAR | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Dodge | Avenger | 01/2014-12/2014 | 433MHz | | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Dodge | Avenger | 01/2006-12/2013 | 433MHz | JS41D | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Dodge | Caliber | 01/2006-12/2011 | 433MHz | PM49 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Caravan | 06/2011-12/2017 | 433MHz | | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Challenger | 01/2019-06/2020 | 433MHz | LC22 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Challenger | 01/2014-12/2018 | 433MHz | LC22 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Challenger | 01/2011-12/2013 | 433MHz | LC22 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Challenger | 01/2008-12/2010 | 433MHz | LC22 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Challenger SRT | 01/2015-06/2020 | 433MHz | LD | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Dodge | Charger | 08/2017-06/2020 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Charger | 10/2014-07/2017 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Charger | 01/2014-09/2014 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Charger | 01/2011-12/2013 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Charger | 01/2010-12/2010 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Charger | 01/2009-12/2009 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2015-12/2015 | 433MHz | | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2016-06/2020 | 433MHz | | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Dodge | Dakota | 01/2009-12/2011 | 433MHz | | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Dakota | 01/2012-12/2013 | 433MHz | | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Dakota | 01/2014-12/2015 | 433MHz | | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Durango | 01/2011-12/2013 | 433MHz | WD75 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Durango | 01/2014-12/2017 | 433MHz | WD75 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Durango | 01/2018-06/2020 | 433MHz | WD75 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2008-12/2010 | 433MHz | | ● | ● | ● | 0 | 433Mhz | Continental | ● | ● |
| Dodge | Grand Caravan | 01/2011-12/2013 | 433MHz | | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2014-06/2020 | 433MHz | | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Journey | 01/2009-12/2010 | 433MHz | JC49 | ● | ● | ● | 0/A | 433Mhz | Continental | ● | ● |
| Dodge | Journey | 01/2011-06/2020 | 433MHz | JC49 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Nitro | 06/2006-12/2012 | 433MHz | KA | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Ram Series | 01/2014-12/2017 | 433MHz | DS/DJ | ● | ● | ● | 0 | 433Mhz | TRW | ● | ● |
| Dodge | Ram Series | 01/2010-12/2013 | 433MHz | DS/DJ | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Ram Series | 01/2006-12/2009 | 433MHz | | ● | ● | ● | 0/A | 433Mhz | Continental | ● | ● |
| Dodge | Ram Series | 01/2018-06/2020 | 433MHz | DS/DJ | ● | ● | ● | 0 | 433Mhz | TRW | ● | ● |
| Dodge | SRT Viper | 01/2010-12/2017 | 433MHz | | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Dodge | Viper | 01/2013-12/2016 | 433MHz | ZD | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| FAW | BESTURN B30 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | BESTURN B50 | 01/2011-12/2016 | Lear 433Mhz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| FAW | BESTURN B50 | 01/2012-12/2016 | TRW 433Mhz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| FAW | BESTURN B50F | 01/2015-06/2018 | Baolong 433Mhz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| FAW | BESTURN B50F | 01/2015-06/2018 | 433MHz | | ○ | ● | ○ | C | 433MHz | FAW | ● | ● |
| FAW | BESTURN B70 | 01/2012-12/2016 | Lear 433Mhz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|-----------------|---------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| FAW | BESTURN B70 | 01/2012-06/2019 | TRW 433Mhz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| FAW | BESTURN B90 | 01/2012-12/2016 | Lear 433Mhz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| FAW | BESTURN B90 | 01/2012-12/2016 | TRW 433Mhz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| FAW | BESTURN T77 | 01/2019-12/2019 | Baolong 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | BESTURN X40 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| FAW | BESTURN X80 | 07/2016-06/2019 | Baolong 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | BESTURN X80 | 01/2013-06/2016 | Lear 433Mhz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| FAW | BESTURN X80 | 01/2013-06/2016 | TRW 433Mhz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| FAW | BESTURN X80F | 09/2016-06/2019 | Baolong 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | HongQi H5 | 01/2017-12/2018 | BaoLong 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | HongQi H7 | 01/2016-12/2016 | BaoLong 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | HongQi H7 | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| FAW | HongQi H7 | 01/2014-12/2017 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Lear | ● | ● |
| FAW | Junpai A70 | 01/2016-12/2016 | 433Mhz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| FAW | Junpai A70E | 01/2017-12/2017 | 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| FAW | Junpai D60 | 10/2014-06/2016 | 433Mhz | | ○ | ● | ○ | S | 433MHz | Xiali | ● | ● |
| FAW | Junpai D60 | 07/2016-12/2017 | New 433Mhz | | ○ | ● | ○ | S | 433Mhz | Xiali | ● | ● |
| FAW | SENIA R7 | 01/2016-06/2019 | Hi Confi 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| FAW | SENIA R7 | 01/2016-06/2019 | Lo Confi 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAW | SENIA R9 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Ferrari | 360 Spider | 07/2007-07/2009 | 433Mhz | F131 | ○ | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | 458 Italia | 01/2014-12/2015 | 433MHz | F142 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | 458 Italia | 09/2007-12/2013 | 433MHz | F142 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | 458 Speciale | 01/2013-12/2016 | 433Mhz | F142 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | 458 Spider | 09/2009-12/2019 | 433Mhz | F142 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | 488 | 01/2015-06/2020 | 433Mhz | F142 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | 550 Maranello | 01/2002-12/2006 | 433MHz | F133e | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | 550 Maranello | 06/1997-12/2001 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | 575M Maranello | 01/2002-12/2006 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | 599 GTB | 01/2004-12/2014 | 433MHz | F141 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | 599 GTO | 01/2004-12/2012 | 433MHz | F141 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | 612 Scaglietti | 01/2004-12/2011 | 433MHz | F137 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | 812 Superfast | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Ferrari | CTC4 Lusso T | 01/2017-12/2019 | 433Mhz | | ○ | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | California | 10/2008-12/2017 | 433MHz | F149 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | Enzo | 01/2003-12/2006 | 433MHz | F140 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 10/2012-12/2015 | 433MHz | F151/ F152 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 01/2016-12/2020 | 433MHz | F152 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | F12 tdf | 01/2015-12/2018 | 433Mhz | F151/ F152 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ferrari | F430 | 07/2007-10/2009 | 433MHz | F131E | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | F430 | 09/2004-06/2007 | 433Mhz | F131E | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | F430 | 01/2007-12/2009 | 433MHz (F131EV0) | F131E | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | F430 Scuderia | 07/2007-06/2012 | 433MHz | F131E | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | F550/575 | 01/1996-11/2009 | 433Mhz | F133 | ○ | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | F8 Tributo | 01/2019-12/2019 | 433Mhz | F151/F152 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | FF | 01/2011-01/2020 | 433MHz | F151 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | FXX | 01/2005-12/2006 | 433MHz | F140 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | GTC4 Lusso | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | La Ferrari | 07/2013-06/2020 | 433MHz | F150 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | Monza SP1/SP2 | 01/2019-12/2019 | 433Mhz | F151/F152 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ferrari | Portofino | 10/2017-12/2019 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Fiat | 1-Tonne Pickup | 01/2016-06/2019 | 433MHz | 4P00 | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Fiat | 124 Spider | 01/2016-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 124 Spider | 08/2015-12/2019 | 433MHz | NF/J12F | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Fiat | 500 | 01/2014-06/2020 | 433MHz | 312 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Fiat | 500 | 01/2014-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500 | 01/2007-12/2013 | 433MHz | 312 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Fiat | 500 | 01/2007-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500C | 01/2014-06/2019 | 433MHz | 312 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Fiat | 500C | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500C | 01/2007-12/2013 | 433MHz | 312 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Fiat | 500L | 01/2007-12/2019 | 433MHz | 330 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Fiat | 500L | 01/2012-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500X | 01/2014-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500X | 01/2015-12/2015 | 433MHz | 334 | ● | ● | ● | O | 433Mhz | Continental | ● | ● |
| Fiat | Albea | 10/2013-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Bravo | 01/2007-10/2016 | 433MHz | 198 | ● | ● | ○ | C | 433Mhz | TRW | ● | ● |
| Fiat | Bravo | 01/2013-12/2014 | Clamp in 433MHz | 198 | ● | ● | ○ | A | 433Mhz | TRW | ● | ● |
| Fiat | Bravo | 01/2013-12/2014 | Snap in 433MHz | | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Croma | 01/2005-06/2011 | 433MHz | | ● | ● | ○ | A | 433Mhz | TRW | ● | ● |
| Fiat | Doblo | 01/2010-06/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Doblo | 12/2009-12/2019 | 433MHz | 223/263 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Fiat | Doblo | 01/2020-06/2020 | 433MHz | X2/50 | ○ | ● | ● | C | 433Mhz | Schrader | ● | ● |
| Fiat | Ducato | 01/2006-05/2014 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Ducato | 06/2014-09/2020 | 433MHz | X2/50 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Fiat | Egea | 10/2015-06/2020 | Snap in 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Egea | 10/2015-06/2020 | Clamp in 433MHz | | ○ | ● | ○ | A | 433Mhz | TRW | ● | ● |
| Fiat | Fiorino | 01/2015-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Fiorino | 01/2014-06/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------|-----------------|-----------------|---------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Fiat | Fiorino | 10/2007-12/2014 | 433MHz | 225 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Freemont | 03/2011-06/2014 | 433MHz | JF | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Fiat | Freemont | 07/2014-03/2018 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Fiat | Fullback | 01/2016-06/2020 | 433MHz | 4P00/ KTOT | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Fiat | Grande Punto | 01/2012-12/2015 | 433MHz | 199 | ● | ● | ○ | A | 433Mhz | TRW | ● | ● |
| Fiat | Idea | 01/2003-12/2012 | 433MHz | 350 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Fiat | Linea | 03/2007-12/2017 | 433MHz | 200 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Palio | 01/2007-12/2015 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Palio | 08/2011-12/2017 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Panda | 01/2012-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Panda | 11/2011-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Professional | 01/2016-12/2016 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Fiat | Punto | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Punto | 09/2005-12/2018 | 433MHz | 199 | ○ | ● | ○ | C | 433Mhz | TRW | ● | ● |
| Fiat | Punto Evo | 01/2009-12/2012 | 433MHz | 199 | ● | ● | ● | O/A | 433Mhz | TRW | ● | ● |
| Fiat | Qubo | 10/2007-03/2020 | 433MHz | 225 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Qubo | 01/2007-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | Scudo | 01/2016-06/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Scudo | 11/2013-06/2019 | 433MHz | 3H/G9 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Scudo | 01/2006-10/2013 | 433MHz | G9 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Sedici | 01/2014-12/2016 | 433MHz | YY2 | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Fiat | Strada | 01/2012-12/2019 | 433MHz | 178/326 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Talento | 01/2016-12/2019 | 433MHz | FJL/X82 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Tipo | 01/2015-06/2020 | Clamp in 433MHz | | ○ | ● | ○ | A | 433Mhz | TRW | ● | ● |
| Fiat | Tipo | 01/2015-06/2020 | Snap in 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Fiat | Tipo | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Toro Pickup | 01/2016-06/2020 | 433MHz | 334 | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Fiat | Ulysse | 10/2005-06/2011 | 433MHz | UL0102/179/V1 | ● | ● | ○ | O | 433Mhz | Continental | ● | ● |
| Fiat | Ulysse | 06/2002-09/2005 | 433MHz | FL166/179/V1 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Ford | B-MAX | 05/2012-12/2018 | 433MHz | B232 | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | B-MAX | 05/2012-12/2016 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | C-Max | 08/2010-12/2019 | 433MHz | C344 | ● | ● | ● | O/S/A | 433Mhz | Schrader | ● | ● |
| Ford | C-Max | 01/2014-12/2019 | 433MHz | CB7/CEU/C344 | ● | ● | ● | S/A | 433Mhz | Schrader | ● | ● |
| Ford | C-Max | 08/2010-12/2016 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Ecosport | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | O/S | 433Mhz | Schrader | ● | ● |
| Ford | Ecosport | 01/2013-10/2017 | 433MHz | B515 | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | Edge | 01/2015-12/2020 | 433MHz | CD389/CD539 | ● | ● | ● | O/S/A | 433Mhz | Schrader | ● | ● |
| Ford | Edge | 06/2014-12/2014 | U387 433MHz | U387 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Ford | Edge | 06/2014-12/2014 | 433MHz | CD389/CD539 | ● | ● | ● | O/S/A | 433Mhz | Schrader | ● | ● |
| Ford | Escape | 05/2012-12/2014 | 433MHz | C520 | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Ford | Escape | 01/2015-12/2018 | 433MHz | C520 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Escape | 01/2014-12/2019 | 433MHz | C520 (2) | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Escape | 04/2007-12/2012 | 315MHz | U377 | ● | ● | ○ | S | 315Mhz | Schrader | ● | ● |
| Ford | Expedition | 01/2005-12/2006 | 433MHz | U222 | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Expedition | 01/2011-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Expedition | 01/2007-12/2008 | 433MHz | U222 | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Expedition | 01/2015-12/2019 | 433MHz | | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Ford | Explorer | 01/2011-12/2015 | 433MHz | U502 | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Ford | Explorer | 01/2016-12/2017 | 433MHz | U502 | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Explorer | 01/2018-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | F-150 | 09/2008-12/2010 | 433Mhz | P415 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | F-150 | 01/2011-12/2014 | 433MHz | P415 | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Ford | F-150 | 01/2015-12/2018 | 433MHz | P415 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | F-150 | 01/2015-12/2019 | 433MHz | P552 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | F-Series | 01/2010-12/2015 | 433MHz | P415 | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Ford | F-Series | 09/2008-12/2009 | 433MHz | P415 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Fiesta | 05/2014-12/2017 | 433MHz | B299 | ● | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | Fiesta | 01/2017-12/2019 | 433MHz | B479 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Fiesta | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Fiesta ST | 06/2017-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Ford | Fiesta ST | 01/2014-05/2017 | 433MHz | | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | Fiesta Van | 01/2014-12/2019 | 433MHz | B256/257 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Focus | 05/2018-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Focus | 01/2015-12/2018 | 433Mhz | C346 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Focus | 01/2014-12/2014 | 433MHz | C346 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Focus | 12/2010-12/2018 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Focus C-Max | 01/2014-12/2018 | 433MHz | C214 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Focus IV | 09/2018-05/2019 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Focus RS | 08/2015-12/2018 | 433MHz | P3T/600A | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Focus ST | 03/2018-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Focus ST | 05/2014-02/2018 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Focus (LCV) | 12/2010-12/2018 | 433Mhz | C346 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Galaxy | 01/2006-12/2014 | 433MHz | CD340 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Ford | Galaxy | 01/2015-12/2020 | 433MHz | CD390 | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | Grand C-MAX | 06/2016-12/2019 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | KA | 09/2008-12/2018 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Ford | KA | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Ford | KA III | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | KA+ | 01/2016-12/2019 | 433MHz | KAF | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Kuga | 01/2013-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Ford | Kuga | 11/2012-12/2013 | 433MHz | C520 | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Ford | Kuga | 01/2014-12/2019 | 433MHz | C520 | ● | ● | ● | 0/S/A | 433Mhz | Schrader | ● | ● |
| Ford | Mondeo | 03/2007-12/2012 | Clamp in 433MHz | CD345 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Ford | Mondeo | 09/2017-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-----------------|-----------------|-----------------|--------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Ford | Mondeo | 01/2013-06/2015 | Clamp in 433MHz | CD345 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Ford | Mondeo | 10/2014-12/2017 | Snap in 433MHz | CD391 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Mustang | 09/2004-12/2006 | 433Mhz | S197 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Mustang | 01/2015-12/2020 | 433MHz | S550 | ● | ● | ● | 0/S/A | 433Mhz | Schrader | ● | ● |
| Ford | Mustang | 01/2015-12/2015 | 433MHz | S197 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Mustang | 01/2007-12/2009 | 433Mhz | S197 | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Mustang | 01/2010-12/2014 | 433MHz | S197 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Ranger | 05/2014-12/2014 | 433MHz | P375 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Ranger | 01/2012-02/2014 | 315MHz | P375 | ● | ● | ● | 0/S | 315Mhz | Continental | ● | ● |
| Ford | Ranger | 01/2006-12/2007 | 315MHz | J97 | ● | ● | ○ | S | 315Mhz | Continental | ● | ● |
| Ford | Ranger | 01/2016-12/2020 | Lo Line 433MHz | P375 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Ranger | 01/2016-12/2019 | Hi Line 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Ranger | 01/2008-12/2011 | 315MHz | | ● | ● | ○ | S | 315Mhz | Continental | ● | ● |
| Ford | Ranger | 01/2015-12/2015 | 433MHz | P375 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | S-MAX | 01/2015-12/2019 | 433Mhz | CD539/ CD389 | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | S-Max | 01/2006-06/2015 | 433Mhz | CD340 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Ford | Tourneo Connect | 06/2018-12/2019 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Tourneo Connect | 01/2014-05/2018 | 433MHz | V408 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Tourneo Courier | 01/2014-12/2019 | 433MHz | B460 | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | Tourneo Custom | 04/2013-12/2019 | 433MHz | V362 | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | Transit | 01/2014-12/2014 | 433Mhz | V348 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Transit | 01/2015-12/2018 | 433Mhz | V184/V347/V 348 | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Transit | 06/2013-12/2014 | 433Mhz | V363 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Transit | 01/2015-12/2019 | 433Mhz | V363 | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Ford | Transit Chassis | 06/2013-05/2019 | 433MHz | V363 | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | Transit Combi | 01/2019-12/2019 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Transit Combi | 01/2014-12/2018 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2013-12/2018 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Transit Connect | 03/2018-12/2019 | 433MHz | V408 | ● | ● | ● | 0/S/A | 433Mhz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2013-12/2018 | 433MHz | V363 | ● | ● | ● | 0/S/A | 433Mhz | Schrader | ● | ● |
| Ford | Transit Courier | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Transit Courier | 10/2014-12/2020 | 433MHz | B460 | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | Transit Courier | 01/2014-09/2014 | 433MHz | B460 | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | Transit Custom | 01/2014-12/2019 | 433MHz | V363 | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | Transit LCV | 01/2013-12/2019 | 433MHz | | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | Vignale Mondeo | 01/2015-12/2019 | 433MHz | | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Ford | Vignale S-Max | 01/2015-12/2019 | 433MHz | | ○ | ● | ○ | S/A | 433Mhz | Schrader | ● | ● |
| Foton | Sauvana | 01/2015-12/2019 | 433Mhz | | ● | ● | ○ | S/O | 433Mhz | TTE | ● | ● |
| Foton | Tunland | 01/2011-12/2019 | 433Mhz | | ● | ● | ○ | S/O | 433Mhz | TTE | ● | ● |
| GMC | Savana | 01/2002-06/2007 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| GMC | Savana | 07/2007-12/2008 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|------------|-----------------|----------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| GMC | Savana | 01/2009-12/2012 | 433MHz | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| GMC | Sierra | 07/2009-12/2017 | 433MHz | GMT902 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| GMC | Sierra | 01/2015-12/2018 | 433MHz | K2XG2 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| GMC | Sierra | 01/2014-12/2014 | 433MHz | K2XG2 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| GMC | Sierra | 01/2013-12/2013 | 433MHz | K2XG2 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| GMC | Sierra | 06/2006-06/2009 | 433MHz | GMT902 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2009-12/2013 | 433MHz | GMT922 (2) | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2015-12/2019 | 433MHz | K2UG (2) / GMT922 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2014-12/2014 | 433MHz | K2UG / GMT922 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2007-12/2008 | 433MHz | GMT922 (2) | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2005-12/2006 | 433MHz | GMT922 (2) | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Geely | Atlas | 01/2015-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | BINRUI | 01/2018-12/2019 | SAT 433Mhz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | BINRUI | 01/2018-12/2019 | SCH 433Mhz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | BINYUE | 07/2018-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | EC7 | 01/2012-12/2014 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | EC7 | 01/2009-12/2012 | Black 433Mhz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | EC7 | 01/2009-12/2012 | Orange 433Mhz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | EC7 | 01/2012-12/2018 | TTE 433Mhz | | ● | ● | ○ | 0 | 433Mhz | TTE | ● | ● |
| Geely | EC8 | 01/2011-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Whetron | ● | ● |
| Geely | EMGRAND | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Baolong | ● | ● |
| Geely | EMGRAND EV | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | EMGRAND GL | 01/2017-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Geely | EMGRAND GS | 01/2015-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Geely | EMGRAND RS | 08/2015-06/2018 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | EV | 01/2016-06/2019 | TTE 433Mhz | | ● | ● | ○ | 0 | 433Mhz | TTE | ● | ● |
| Geely | FY11 | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | GC9 | 01/2015-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Geely | GE | 01/2015-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Geely | GE11 | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | GL | 01/2018-12/2019 | SCH 433Mhz | | ○ | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Geely | GSE | 01/2018-12/2019 | SCH 433Mhz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | GX7 | 01/2014-12/2015 | Lear 433Mhz | | ○ | ● | ○ | C | 433MHz | Lear | ● | ● |
| Geely | GX7 | 01/2014-12/2015 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | GX9 | 01/2015-12/2017 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | S1 | 01/2017-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | SC6 | 01/2014-12/2017 | TTE 433Mhz | | ● | ● | ○ | 0 | 433Mhz | TTE | ● | ● |
| Geely | SX7 | 01/2013-12/2014 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | SX7 | 01/2013-12/2014 | TTE 433Mhz | | ● | ● | ○ | 0 | 433Mhz | TTE | ● | ● |
| Geely | VF11 | 01/2019-12/2019 | CHINA-5 433Mhz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | VF11 | 01/2019-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | X3 | 01/2018-12/2019 | 433Mhz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|---------------|-----------------|------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Geely | X3 | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Geely | Yuanjing | 01/2018-12/2018 | 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Geely | Yuanjing X6 | 01/2016-06/2019 | NEW 433Mhz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Yuanjing X6 | 01/2015-12/2016 | 433Mhz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| GreatWall | M4 | 01/2015-12/2017 | 433Mhz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| GreatWall | M4 | 01/2018-12/2019 | 433Mhz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| GreatWall | P8 | 08/2017-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| GreatWall | Steed | 01/2015-12/2017 | 433MHz | | ○ | ● | ○ | S | 433Mhz | SAT | ● | ● |
| GreatWall | Steed | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | S | 433Mhz | SAT | ● | ● |
| GreatWall | Tracker | 01/2015-12/2017 | 433MHz | | ○ | ● | ○ | S | 433Mhz | SAT | ● | ● |
| GreatWall | Tracker | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | S | 433Mhz | SAT | ● | ● |
| GreatWall | VV5 | 01/2017-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| GreatWall | VV6 | 01/2018-12/2018 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| GreatWall | VV7 | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| GreatWall | Voleex C20 | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| GreatWall | Voleex C30 | 01/2015-12/2017 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | SAT | ● | ● |
| GreatWall | Voleex C30 | 01/2014-12/2015 | SAT 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| GreatWall | Voleex C30 | 01/2018-12/2019 | 433Mhz | | ○ | ● | ○ | 0 | 433Mhz | SAT | ● | ● |
| GreatWall | Voleex C50 | 01/2015-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| GreatWall | Voleex C50 | 01/2011-12/2014 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | SAT | ● | ● |
| GreatWall | Wingle | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | SAT | ● | ● |
| GreatWall | Wingle 5 | 01/2016-12/2018 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| GreatWall | Wingle 5 | 01/2011-12/2015 | 433Mhz | | ○ | ● | ○ | S | 433Mhz | SAT | ● | ● |
| GreatWall | Wingle 6 | 01/2012-12/2015 | SAT 433Mhz | | ○ | ● | ○ | S | 433Mhz | SAT | ● | ● |
| GreatWall | Wingle 6 | 01/2015-11/2018 | SCH 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| GreatWall | Wingle 7 | 06/2018-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| HSV | ClubSport GXP | 01/2010-12/2010 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| HSV | GTS | 01/2007-12/2012 | 433MHz | HT0078 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| HSV | Grange | 01/2007-12/2012 | 433MHz | HR0078 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| HSV | Maloo GXP | 01/2010-12/2010 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| HSV | R8 | 01/2007-12/2012 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| HSV | Senator | 01/2007-12/2012 | 433MHz | HE0078 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Haval | F5 | 01/2018-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | F7 | 01/2018-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | H1 | 01/2014-12/2017 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | H2 | 01/2014-06/2017 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | H2 | 07/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | H2s NEW | 01/2016-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | H4 | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | H5 | 01/2017-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | SAT | ● | ● |
| Haval | H5 | 01/2010-12/2016 | 433Mhz | | ○ | ● | ○ | S | 433Mhz | SAT | ● | ● |
| Haval | H5 Classics | 01/2015-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | H6 | 01/2011-12/2018 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | SAT | ● | ● |
| Haval | H6 Coupe | 06/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | H6 Coupe | 01/2015-05/2017 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Haval | H6 NEW | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | H7 | 01/2016-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | H7L | 06/2017-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | H8 | 01/2013-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | H9 | 01/2014-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Haval | M2 | 01/2014-12/2015 | 433Mhz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Haval | M6 | 01/2017-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | SAT | ● | ● |
| Holden | Colorado | 01/2013-12/2017 | 433MHz | GMI700 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Holden | WM Caprice | 01/2007-12/2012 | 433MHz | WM | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Honda | Accord | 01/2015-12/2015 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Accord | 01/2014-12/2019 | Direct 433MHz | 2GA/2GB/QE | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Honda | Accord | 01/2009-12/2013 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | CR-V | 01/2015-12/2019 | Direct 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Honda | CR-V | 01/2012-12/2018 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | CR-Z | 01/2010-12/2014 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Civic | 01/2013-12/2018 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Civic | 01/2015-12/2019 | Direct 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Honda | Civic | 01/2009-12/2012 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Clarity | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Crosstour | 01/2012-12/2016 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Honda | Goldwing | 01/2009-12/2016 | MOTOR Cycle 315MHz | | ○ | ○ | ○ | S | 315MHz | Continental | Activate Only | ● |
| Honda | HR-V | 09/2014-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | HR-V | 11/2014-12/2019 | Direct 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Honda | Insight | 01/2010-12/2014 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Jazz | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Jazz | 01/2014-12/2019 | Direct 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Honda | NSX | 01/2016-12/2019 | Direct 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | NSX | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Hummer | H2 | 01/2008-12/2008 | 433MHz | H28 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Hummer | H2 | 07/2006-12/2007 | 433MHz | H28 | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Hummer | H2 | 01/2002-06/2006 | 433MHz | H28 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Hummer | H3 | 01/2005-12/2006 | 433MHz | H38/GMT345 | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Hummer | H3 | 01/2007-12/2012 | 433MHz | H38/GMT345 | ● | ● | ● | S | 433Mhz | Schrader | ● | ● |
| Hyundai | Accent | 01/2014-06/2020 | Lo Line 433Mhz | RB | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Accent | 04/2011-06/2020 | Hi Line 433MHz | RB | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Azera | 09/2014-02/2017 | 433Mhz | HG | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Azera | 01/2011-08/2014 | 433Mhz | HG | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| Hyundai | Azera | 03/2017-12/2019 | 433Mhz | IG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|---------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | C-Green | 01/2016-06/2019 | AE 433MHz | AE | ○ | ● | ○ | C | 433MHz | TRW | ● | ● |
| Hyundai | Centennial | 07/2009-12/2013 | 433Mhz | VI Old | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| Hyundai | Centennial | 01/2013-12/2015 | 433Mhz | VI New | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Creta | 01/2016-12/2019 | Russia 433MHz | GSB/GSR | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 11/2015-06/2020 | 433MHz | GSB/GSR | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Hyundai | Creta | 01/2016-12/2019 | Other 433MHz | GS | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Elantra | 01/2012-12/2012 | 433Mhz | MD | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| Hyundai | Elantra | 01/2008-12/2012 | FD 433MHz | FD | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Elantra | 01/2015-06/2020 | AD 433Mhz | AD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 01/2013-12/2018 | 433Mhz | MD/UD | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| Hyundai | Equus | 01/2013-12/2016 | 433MHz | VI New | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Equus | 01/2008-12/2013 | 433MHz | VI Old | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Genesis | 01/2007-12/2014 | BH 433MHZ | BH | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Genesis | 01/2013-12/2017 | DH 433Mhz | DH | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Hyundai | Genesis Coupe | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Genesis G70 | 10/2017-06/2020 | 433Mhz | IK | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Hyundai | Genesis G80 | 07/2016-06/2020 | 433Mhz | DH | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Genesis G90 | 07/2016-06/2020 | 433MHz | HI | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Grand SantaFe | 04/2013-12/2019 | NC/DM 433MHz | NC | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Grandeur | 01/2017-06/2020 | 433MHz | IG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Grandeur | 01/2011-12/2017 | HG 433MHz | HG | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| Hyundai | Grandeur | 06/2011-12/2015 | HG 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | H-1 | 01/2013-05/2014 | 315Mhz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | H-1 | 06/2014-12/2019 | TQ | TQ | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | H100 | 01/2014-12/2019 | 433MHz | TQ | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | H300 | 01/2014-12/2020 | 433MHz | LU/AU | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | H300 | 01/2010-12/2013 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq | 01/2016-06/2020 | 433MHz | AE | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Kauai | 01/2017-06/2020 | | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Kona | 01/2017-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Nexo | 04/2018-06/2020 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Hyundai | Palisade | 01/2019-06/2020 | 433Mhz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Hyundai | Porter | 01/2014-12/2018 | HR | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Santa Fe | 04/2017-12/2018 | 433Mhz | DM/DMI | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Santa Fe | 04/2013-03/2017 | 433Mhz | DM/DMI | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Santa Fe | 06/2012-03/2013 | DM/NC 433Mhz | DM/NC | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Santa Fe | 01/2006-12/2008 | CM 433Mhz | CM | ● | ● | ○ | 0 | 433Mhz | Lear | ● | ● |
| Hyundai | Santa Fe | 03/2018-06/2020 | TM 433MHZ | TM/TMA | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Hyundai | Santa Fe | 01/2009-05/2012 | CM 433Mhz | CM | ● | ● | ○ | 0 | 433Mhz | Lear | ● | ● |
| Hyundai | Santa Fe Sport | 01/2015-12/2019 | 315MHz | DMA | ● | ● | ○ | 0 | 315Mhz | Continental | ● | ● |
| Hyundai | Santa Fe Sport | 01/2013-12/2014 | 315Mhz | DMA | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Solaris | 01/2014-12/2019 | 433MHz | HC | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Solaris | 01/2011-03/2017 | 433MHz | RB | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | Sonata | 04/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------------|-----------------|----------------|--------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Sonata | 04/2014-12/2019 | Hi Line 433MHz | LF/LFA | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata | 01/2014-02/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Sonata Hybrid | 08/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Hyundai | Sonata Hybrid | 08/2017-06/2020 | Hi Line 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Hyundai | Starex | 03/2011-06/2020 | 433MHz | A1 | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Hyundai | Sub-Compact SUV | 01/2015-06/2019 | 433MHz | IB | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Hyundai | Tucson | 11/2013-09/2015 | Lo line 433Mhz | EL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Tucson | 01/2016-06/2020 | 433Mhz | TL/TLE | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Hyundai | Tucson | 01/2015-12/2015 | 433Mhz | TL/TLE | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Hyundai | Tucson | 01/2010-05/2015 | 433Mhz | LM | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| Hyundai | Tucson | 06/2015-08/2013 | 433Mhz | LM | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Hyundai | Tucson | 07/2013-06/2015 | Hi line 433Mhz | EL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Veloster | 01/2019-06/2020 | FS 433MHz | FS | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Hyundai | Veloster | 03/2011-12/2018 | FS 433Mhz | FS | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Hyundai | Veracruz | 01/2009-12/2013 | EN 433Mhz | EN | ● | ● | ○ | 0 | 433Mhz | Lear | ● | ● |
| Hyundai | i10 | 10/2007-10/2013 | IA/PA 433MHz | IA/PA | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | i10 | 11/2013-06/2020 | IA 433MHz | IA | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Hyundai | i20 | 01/2013-12/2016 | 433MHz | PB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i20 | 06/2008-12/2012 | 433MHz | PB | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | i20 | 10/2014-06/2020 | 433MHz | GB | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Hyundai | i30 | 05/2007-03/2014 | 433MHz | FD/Fde | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | i30 | 08/2016-06/2020 | 433MHz | PD/Pde | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 01/2018-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Hyundai | i30 | 04/2014-12/2018 | 433MHz | GD | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Hyundai | i30 | 12/2011-12/2017 | 433Mhz | Gde | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | i40 | 01/2017-12/2019 | 433MHz | IF | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i40 | 01/2011-03/2014 | VF 433MHz | VF | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| Hyundai | i40 | 04/2014-06/2020 | VF 433MHz | VF | ● | ● | ○ | 0/A | 433Mhz | TRW | ● | ● |
| Hyundai | i800 | 01/2013-02/2014 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Hyundai | i800 | 03/2014-06/2020 | 433MHZ | TQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | iLoad | 01/2014-06/2020 | TQ 433MHz | TQ | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | iMax | 01/2015-12/2016 | TQ 433MHz | TQ | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | ix20 | 10/2013-03/2017 | JC/IX5 433MHz | JC/IX5 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Hyundai | ix20 | 04/2017-06/2020 | JC/IX5 433MHz | JC/IX5 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Hyundai | ix20 | 01/2010-09/2013 | JC 433MHz | JC | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | ix25 | 01/2017-12/2019 | 433MHz | OS | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | ix35 | 09/2013-12/2019 | Lo Line 433Mhz | LMC/EL/ELH/LM FCEV | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| Hyundai | ix35 | 01/2010-08/2013 | LM/EL 433MHz | LM/EL | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| Hyundai | ix35 | 10/2015-06/2020 | TL/TLE 433MHz | TL/TLE | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Hyundai | ix35 | 09/2013-12/2016 | 433MHz | LM | ● | ● | ○ | 0/A | 433Mhz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|------------|-----------------|--------------------|----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | ix35 | 01/2017-09/2017 | FUEL CELL 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 09/2013-12/2015 | Hi Line 433MHz | EL | ● | ● | ○ | 0/A | 433Mhz | TRW | ● | ● |
| Hyundai | ix35 | 01/2013-12/2019 | FUEL CELL 433MHz | EL | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| Hyundai | ix55 | 10/2008-12/2019 | 433MHz | EN | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Hyundai | ix55 | 01/2007-12/2012 | EN 433MHz | EN | ● | ● | ○ | 0 | 433Mhz | Lear | ● | ● |
| Infiniti | EX Series | 01/2007-03/2014 | 433MHz | P53B/J50 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Infiniti | EX Series | 04/2010-09/2018 | 315MHz | J50 | ● | ● | ○ | 0 | 315Mhz | Pacific | ● | ● |
| Infiniti | FX Series | 03/2008-04/2015 | 433MHz | P53C/S51 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Infiniti | G Series | 01/2006-02/2014 | 433MHz | CV36/G312/L53A | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Infiniti | G Series | 04/2010-12/2015 | 315MHz | V36 | ● | ● | ○ | 0 | 315Mhz | Pacific | ● | ● |
| Infiniti | M Series | 01/2008-12/2013 | L53E 433MHz | L53E | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Infiniti | M Series | 01/2010-04/2016 | Y51 433MHz | M312/Y51 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Infiniti | Q30 | 01/2015-12/2019 | 433MHZ | GD1A/H15 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Infiniti | Q50 | 06/2013-12/2019 | 433MHz | L53H/D53H/V37 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Infiniti | Q60 | 01/2013-12/2019 | 433Mhz Continental | L53H/D53H | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Infiniti | Q60 | 07/2013-06/2016 | 433MHz | L53A/CV36 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Infiniti | Q70 | 01/2013-12/2019 | 433MHZ | L53E/Y51 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Infiniti | Q70 | 01/2014-04/2014 | 433MHz | M312 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Infiniti | Q70 | 10/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Infiniti | QX30 | 09/2015-12/2019 | 433MHz | GD1A/H15 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Infiniti | QX40 | 04/2017-06/2019 | 433MHz | PD2A | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Infiniti | QX50 | 01/2014-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Infiniti | QX50 | 01/2014-12/2019 | PAC 433MHz | P53B/J50 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Infiniti | QX50 | 11/2015-12/2019 | VDO 433MHz | P53B(2) | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Infiniti | QX56/QX80 | 01/2010-07/2015 | 433MHz | JA60 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Infiniti | QX60 | 11/2012-12/2019 | 433MHz | P42J | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Infiniti | QX70 | 07/2013-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Infiniti | QX70 | 01/2016-12/2019 | VDO 433MHz | P53J | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Infiniti | QX70 | 01/2014-12/2019 | PAC 433MHz | P53C/S51 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Infiniti | QX80 | 01/2013-12/2019 | 433MHz | Z62 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Isuzu | D-Max | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Isuzu | MU-X | 11/2016-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Baolong | ● | ● |
| JAC | Iev7s | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | S | 433Mhz | JAC | ● | ● |
| JAC | J4 | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | J6 | 01/2011-12/2016 | 433MHz | | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | J6 A30 | 01/2015-12/2016 | 433MHz | | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | J6 A30 | 01/2012-12/2012 | 433MHz | | ○ | ● | ○ | C | 433Mhz | JAC | ● | ● |
| JAC | J6 B15 | 01/2012-12/2016 | 433MHz | | ○ | ● | ○ | C | 433Mhz | JAC | ● | ● |
| JAC | Refine A60 | 01/2015-12/2017 | 433MHz | | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | Refine M2 | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | Refine M4 | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| JAC | Refine M5 | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | Refine M6 | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | Refine R3 | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | Refine S2 | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | Refine S2 | 01/2015-12/2019 | Steel 433MHz | | ○ | ● | ○ | C | 433Mhz | JAC | ● | ● |
| JAC | Refine S3 | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | Refine S5 | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | Refine S7 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | T6 | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| JAC | iEV6E | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | S | 433Mhz | JAC | ● | ● |
| Jaguar | E-Pace | 06/2017-12/2019 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | F-Pace | 12/2015-12/2019 | 433MHz | X761 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | F-Type | 01/2016-12/2019 | 433MHz | X152 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | F-Type | 01/2012-12/2015 | 433MHz | X152 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | I-Pace | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | S-Type | 01/2006-12/2008 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | X-Type | 01/2007-12/2015 | 433MHz | X400 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | XE | 12/2015-12/2019 | 433MHz | X760 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | XE | 01/2015-11/2015 | 433MHz | X760 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | XF | 06/2015-12/2019 | 433MHz | X260 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | XF | 07/2014-05/2015 | 433MHz | X260 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | XF | 01/2007-12/2015 | 433MHz | X250 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | XJ | 01/2016-12/2019 | 433Mhz | X351 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | XJ | 01/2010-12/2015 | 433Mhz | X351 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | XJ | 08/2005-02/2010 | 433MHz | X350 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | XK | 01/2006-12/2015 | 433MHz | X150 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jaguar | XKR | 01/2006-12/2014 | 433HZ | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Jeep | B-CUV | 10/2014-12/2016 | 433MHz | 520 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jeep | C-CUV | 01/2016-06/2019 | 433MHz | MP | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Jeep | Cherokee | 01/2018-12/2019 | 433MHz 68324960AA | | ○ | ● | ○ | C | 433Mhz | TRW | ● | ● |
| Jeep | Cherokee | 01/2014-12/2016 | 433MHz | KL | ● | ● | ● | O/A | 433Mhz | TRW | ● | ● |
| Jeep | Cherokee | 01/2002-12/2004 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Jeep | Cherokee | 01/2005-12/2013 | 433MHz 56029359AC | KK | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Jeep | Cherokee | 01/2017-06/2020 | 433MHz | KL | ● | ● | ● | O/A | 433Mhz | TRW | ● | ● |
| Jeep | Commander | 01/2006-12/2010 | 433MHz | XK | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Jeep | Compass | 01/2017-12/2019 | 433MHz | 551 | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Jeep | Compass | 09/2014-12/2017 | 433MHz | MK49 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Jeep | Compass | 05/2006-08/2014 | 433MHz | MK49 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Jeep | Compass | 01/2017-06/2020 | 433MHz | MP/MX | ● | ● | ● | O/A | 433Mhz | Continental | ● | ● |
| Jeep | D-CUV | 05/2013-12/2016 | 433MHz | KL | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2018-06/2020 | 433MHz | WK | ● | ● | ● | O/A | 433Mhz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2016-12/2017 | 433MHz | WK | ● | ● | ● | O/A | 433Mhz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2014-12/2019 | 433MHz | WK74 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2012-12/2013 | 433MHz | WK74 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jeep | Grand Cherokee | 01/2011-12/2011 | 433MHz | WK74 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 06/2006-12/2010 | 433MHz | WH | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2001-12/2004 | 433MHz | WK/WJ | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2005-05/2006 | 433MHz | | ● | ● | ● | 0 | 433Mhz | Continental | ● | ● |
| Jeep | Liberty | 01/2010-12/2015 | 433MHz | Li0103 | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Jeep | Liberty | 01/2005-12/2009 | 433MHz | | ● | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Jeep | Patriot | 12/2006-12/2017 | 433MHz | MK74 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Jeep | Renegade | 01/2018-12/2019 | 433MHz | BU/520 | ● | ● | ● | 0/A | 433Mhz | Continental | ● | ● |
| Jeep | Renegade | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Jeep | Renegade | 01/2014-12/2017 | 433MHz | BU/520 | ● | ● | ● | 0/A | 433Mhz | Continental | ● | ● |
| Jeep | Renegade | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Jeep | Wrangler | 01/2014-06/2020 | 433MHz | JL | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Jeep | Wrangler | 09/2010-12/2019 | 433MHz | JK72 | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Jeep | Wrangler | 06/2006-08/2010 | 433MHz | JK72 | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| KIA | Borrego | 01/2009-12/2011 | 315MHz | HM | ● | ● | ○ | 0 | 315Mhz | TRW | ● | ● |
| KIA | Cadenza | 01/2017-12/2018 | 529333N100 433MHz | YG | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Cadenza | 06/2013-07/2016 | 433MHz | VG | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| KIA | Cadenza | 08/2016-06/2020 | 52933D9100 433MHz | YG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Carens | 01/2012-06/2020 | RP 433MHz | RP/UN | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| KIA | Carnival | 01/2014-12/2018 | Sedan 433MHz | YP | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| KIA | Carnival | 01/2019-12/2019 | 433MHz | YP | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| KIA | Carnival | 01/2016-12/2018 | YP 433MHz | YP/VQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Ceed | 05/2018-06/2020 | CD 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Pacific | ● | ● |
| KIA | Ceed | 03/2012-04/2018 | JD 433MHz | JD | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Ceed | 01/2006-02/2012 | ED 433MHz | ED | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Ceed SW | 01/2019-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| KIA | Ceed SW | 09/2012-04/2018 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Ceed SW | 01/2006-08/2012 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Ceed SW | 05/2018-12/2018 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Cerato | 02/2009-12/2014 | TD 433MHz | | ○ | ● | ○ | C | 433Mhz | TRW | ● | ● |
| KIA | Cerato | 01/2012-12/2013 | YD 315MHz | | ● | ● | ○ | 0 | 315Mhz | Continental | ● | ● |
| KIA | Cerato | 01/2017-06/2020 | YD 433MHz | | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| KIA | Cerato | 01/2015-12/2016 | BD 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | E-Niro | 10/2018-06/2020 | 433MHZ | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Forte | 01/2016-12/2018 | 315MHz | | ● | ● | ○ | 0 | 315Mhz | TRW | ● | ● |
| KIA | K2700 | 06/2014-12/2018 | 433MHz | PU | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| KIA | Magentis | 01/2013-12/2015 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| KIA | Mohave | 01/2008-08/2014 | 433MHz | | ○ | ● | ○ | C | 433Mhz | TRW | ● | ● |
| KIA | Mohave | 09/2014-12/2019 | Lo line 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Mohave | 09/2014-12/2019 | Hi line 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Mohave | 01/2016-12/2018 | 433MHZ | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Morning | 01/2017-06/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------|-----------------|----------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| KIA | Morning | 01/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Niro | 01/2016-06/2020 | 433MHz | DE | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Optima | 01/2011-12/2012 | 433Mhz | TF/TF HEV | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Optima | 01/2016-12/2019 | Hybrid 433Mhz | JF HEV/PHEV | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| KIA | Optima | 01/2013-12/2016 | 433Mhz | TF/TF HEV | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| KIA | Optima | 10/2015-06/2020 | JF 433MHz | JF/JFA | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Picanto | 04/2014-12/2017 | TA 433MHz | TA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Picanto | 01/2016-12/2019 | 433MHz | TA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Picanto | 01/2017-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| KIA | Pro Ceed | 01/2008-08/2012 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Pro Ceed | 09/2012-04/2018 | JD 433MHz | JD | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Pro Ceed | 05/2018-06/2020 | CD 433MHz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| KIA | Quoris | 01/2013-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Rio | 01/2012-06/2014 | UB 433Mhz | UB | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| KIA | Rio | 06/2014-06/2020 | Lo line 433Mhz | UB | ● | ● | ○ | 0/A | 433Mhz | TRW | ● | ● |
| KIA | Rio | 06/2014-06/2020 | Hi line 433Mhz | UB | ● | ● | ○ | 0/A | 433Mhz | TRW | ● | ● |
| KIA | Rio | 12/2016-06/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| KIA | Rondo | 01/2013-06/2019 | 315MHz | RP | ● | ● | ○ | 0/A | 315Mhz | Continental | ● | ● |
| KIA | Sedona | 01/2015-06/2020 | 433MHz | YP | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| KIA | Sorento | 01/2009-06/2012 | XM 433Mhz | XM | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Sorento | 07/2012-06/2020 | UM/XM 433Mhz | UM/XM | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Sorento | 01/2018-06/2020 | 433MHz | UMA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Soul | 06/2008-10/2013 | AM 433Mhz | AM | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Soul | 01/2019-06/2020 | SK3 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Soul | 11/2013-12/2019 | PS 433Mhz | PS | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| KIA | Soul EV | 06/2014-12/2019 | PS EV 433MHz | PS EV | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| KIA | Sportage | 01/2014-12/2015 | SL 433Mhz | SL | ● | ● | ○ | 0/A | 433Mhz | TRW | ● | ● |
| KIA | Sportage | 01/2016-06/2020 | QL/QLE 433Mhz | QL/QLE | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| KIA | Sportage | 01/2010-12/2013 | Lo Line 433Mhz | SL | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| KIA | Sportage | 01/2010-12/2013 | Hi Line 433Mhz | SL | ● | ● | ○ | 0 | 433Mhz | TRW | ● | ● |
| KIA | Stinger | 10/2017-06/2020 | 433Mhz | CK | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| KIA | Stonic | 11/2017-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Stonic | 01/2017-06/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| KIA | Venga | 06/2010-03/2014 | YN 433MHz | YN | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | Venga | 04/2014-06/2020 | YN 433MHz | YN | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| KIA | XCeed | 01/2018-06/2020 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Pacific | ● | ● |
| Lada | Granta | 07/2016-12/2019 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Lada | Granta | 09/2012-06/2016 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Lada | Kalina | 05/2013-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Lada | Largus | 10/2015-12/2018 | 433MHz | | ○ | ● | ○ | C | 433MHz | SCHRADER | ● | ● |
| Lada | Vesta | 09/2015-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|--------------------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lada | Xray | 02/2016-12/2018 | 433MHZ | | ○ | ● | ○ | C | 433MHZ | SCHRADER | ● | ● |
| Lamborghini | Aventador | 05/2011-06/2020 | 433MHz | LB834 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Lamborghini | Few Off | 01/2018-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Lamborghini | Gallardo | 01/2003-06/2018 | 433MHz | LB714/LB724 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Lamborghini | Huracan | 01/2014-06/2020 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Lamborghini | LP640 | 06/2007-01/2010 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Lamborghini | Murcielago | 01/2006-12/2015 | 433MHz | LB824 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Lamborghini | One off | 01/2016-06/2020 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Lamborghini | Reventon | 01/2008-12/2010 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Lamborghini | Urus | 01/2018-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Lancia | Delta | 06/2014-06/2020 | 433MHz | PK | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Lancia | Delta | 01/2008-05/2014 | 433MHz | 844 | ● | ● | ○ | C | 433Mhz | TRW | ● | ● |
| Lancia | Flavia | 10/2010-12/2011 | 433MHz | JS27 | ● | ● | ● | 0 | 433Mhz | Continental | ● | ● |
| Lancia | Flavia | 01/2012-12/2014 | 433MHz | JS27 | ● | ● | ● | 0/A | 433Mhz | Continental | ● | ● |
| Lancia | Flavia | 01/2014-12/2016 | 433MHz | UF | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Lancia | Musa | 01/2004-12/2014 | 433MHz | 848 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Lancia | Phedra | 06/2002-09/2005 | SCH 433MHz | 179 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Lancia | Phedra | 03/2002-12/2012 | Conti 433MHz | 179 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Lancia | Thema | 01/2011-12/2018 | 433MHz | LX | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Lancia | Voyager | 11/2015-12/2017 | 433MHz | RU/RA | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Lancia | Voyager | 01/2011-10/2015 | 433MHz | RT/RU | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Lancia | Voyager | 07/2007-12/2010 | 433MHz | RT | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Lancia | Ypsilon | 01/2011-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Lancia | Ypsilon | 01/2011-12/2016 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Land Rover | Defender | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Discovery | 12/2009-12/2014 | 433Mhz | Di4 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Discovery | 01/2015-12/2016 | 433Mhz | Di4 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Discovery | 01/2005-11/2009 | 433Mhz | Di092 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Discovery | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Discovery Sport | 09/2015-12/2019 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2015-08/2015 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Discovery5 | 06/2018-12/2019 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | FreeLander | 01/2007-12/2016 | 433Mhz | Fr132 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover | 03/2002-12/2004 | 433Mhz | L30 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Land Rover | Range Rover | 01/2005-12/2009 | 433MHz | L322 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2010-12/2012 | 433MHz | L322 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover | 06/2015-12/2019 | 433MHz | D6, Ra5 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2013-05/2015 | 433MHz | D5, D6, Ra5 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 10/2015-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 01/2015-02/2019 | 433MHz FW931A159AB | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2011-12/2014 | 433MHz | Ev52 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover Grand Evoque | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-------------------|-----------------|----------------|---------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Range Rover Sport | 06/2014-12/2014 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-08/2013 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 06/2015-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2015-05/2015 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2006-12/2009 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 01/2017-06/2020 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2014-12/2015 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2005-12/2013 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Lexus | C-CUV | 11/2014-12/2016 | 433MHz | 600A | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | CT Series | 12/2013-12/2019 | 433Mhz | 080A | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | ES Series | 06/2018-12/2019 | 433MHZ | | ● | ● | ○ | 0 | 433MHZ | Pacific | ● | ● |
| Lexus | ES Series | 06/2012-05/2018 | 433Mhz | 980L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | ES Series | 01/2007-05/2012 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | GS Series | 01/2005-12/2011 | 433Mhz | GS32 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | GS Series | 01/2012-12/2019 | 433Mhz | 920L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | GX Series | 08/2013-12/2019 | 433Mhz | J150 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | GX Series | 01/2006-12/2009 | 433Mhz | J120 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | IS Series | 04/2013-12/2019 | 433Mhz | 030L/400A/720A/XE30 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | IS Series | 01/2006-03/2013 | 433Mhz | XE20 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | LC Series | 05/2017-06/2020 | Hi Line 433MHz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | LC Series | 05/2017-06/2020 | Lo Line 433MHz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | LC Series | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHZ | Pacific | ● | ● |
| Lexus | LFA | 01/2010-12/2012 | 433Mhz | LFA | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | LS Series | 10/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | LS Series | 10/2012-09/2017 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | LS Series | 08/2006-09/2012 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | LX Series | 10/2015-12/2019 | 433MHZ | URJ | ● | ● | ○ | 0 | 433MHZ | Pacific | ● | ● |
| Lexus | LX Series | 06/2012-09/2015 | 433MHz | URJ | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | LX Series | 01/2005-12/2010 | 433Mhz | URJ | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | NX Series | 03/2014-12/2019 | 433Mhz | 600A | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | RC Series | 01/2014-12/2019 | 433Mhz | XC1/720A | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | RX Series | 01/2006-12/2010 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | RX Series | 11/2015-12/2019 | 433Mhz | 740A | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | RX Series | 06/2014-10/2015 | 433Mhz | 640L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Lexus | SC Series | 05/2007-06/2010 | 433Mhz | UZZ40 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|----------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Lexus | UX Series | 10/2018-12/2019 | 433MHZ | URJ | ● | ● | ○ | O | 433MHZ | Pacific | ● | ● |
| Lifan | 820 | 01/2015-12/2016 | 433Mhz | | ○ | ● | ○ | S | 433MHZ | LiFan | ● | ● |
| Lifan | MaiWei | 01/2016-12/2018 | 433MHZ | | ● | ● | ○ | O | 433MHZ | LiFan | ● | ● |
| Lifan | X50 | 01/2014-12/2015 | 433Mhz | | ○ | ● | ○ | S | 433MHZ | LiFan | ● | ● |
| Lincoln | MKZ | 01/2015-12/2019 | 433MHZ | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2015-12/2015 | 315MHz | | ● | ● | ● | S | 315Mhz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2011-12/2014 | 433MHZ | FA0114 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2016-12/2019 | 433MHZ | FA0114 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Lotus | 3 Eleven | 01/2015-12/2017 | 433MHZ | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Lotus | Elise | 01/2008-06/2020 | 433MHZ | Monza | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Lotus | Evora | 06/2009-06/2020 | 433MHZ | Eagle | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Lotus | Exige | 09/2000-12/2020 | 433MHZ | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Luxgen | M7 | 01/2017-06/2019 | 433MHZ | | ● | ● | ○ | O | 433Mhz | TTE | ● | ● |
| Luxgen | S3 | 01/2016-12/2018 | 433MHZ | | ● | ● | ○ | C | 433Mhz | TTE | ● | ● |
| Luxgen | S5 | 01/2016-12/2018 | 433MHZ | | ● | ● | ○ | C | 433Mhz | TTE | ● | ● |
| Luxgen | U5 | 01/2016-06/2019 | 433MHZ | | ● | ● | ○ | C | 433Mhz | SAT | ● | ● |
| Luxgen | U6 | 01/2016-12/2019 | 433MHZ | | ● | ● | ○ | C | 433Mhz | TTE | ● | ● |
| Luxgen | U7 | 01/2016-06/2019 | 433MHZ | | ● | ● | ○ | C | 433Mhz | TTE | ● | ● |
| Luxgen | V7 | 01/2017-06/2019 | 433MHZ | | ● | ● | ○ | C | 433Mhz | TTE | ● | ● |
| MAN | TGE | 04/2017-12/2020 | 433MHZ | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| MG | 3 | 01/2016-12/2019 | 433MHZ | | ● | ● | ○ | O/A | 433Mhz | Baolong | ● | ● |
| MG | EZS | 01/2019-12/2019 | 433MHZ | | ● | ● | ○ | O/A | 433Mhz | Baolong | ● | ● |
| MG | GS | 09/2016-01/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | GS | 01/2017-12/2019 | 433MHZ | | ● | ● | ○ | O/A | 433Mhz | Baolong | ● | ● |
| MG | HS | 01/2018-12/2018 | 433MHZ | | ● | ● | ○ | O/A | 433Mhz | Baolong | ● | ● |
| MG | MG3 | 09/2013-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | MG6 | 01/2012-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | ZS | 01/2017-06/2019 | 433MHZ | | ● | ● | ○ | O/A | 433Mhz | Baolong | ● | ● |
| Mahindra | Bolero | 06/2014-12/2019 | 433MHZ | | ○ | ● | ○ | A | 433MHZ | Schrader | ● | ● |
| Mahindra | Genio | 06/2014-12/2018 | 433MHZ | | ○ | ● | ○ | A | 433MHZ | Schrader | ● | ● |
| Mahindra | Goa | 06/2014-12/2019 | 433MHZ | W105 | ○ | ● | ○ | A | 433MHZ | Schrader | ● | ● |
| Mahindra | KUV100 | 01/2016-12/2019 | 433MHZ | | ○ | ● | ○ | A | 433MHZ | Schrader | ● | ● |
| Mahindra | NC | 06/2014-12/2018 | 433MHZ | CL/MM | ○ | ● | ○ | A | 433MHZ | Schrader | ● | ● |
| Mahindra | Quanto | 01/2016-12/2019 | 433MHZ | | ○ | ● | ○ | A | 433MHZ | Schrader | ● | ● |
| Mahindra | Scorpio | 06/2014-12/2019 | 433MHZ | U202 | ○ | ● | ○ | A | 433MHZ | Schrader | ● | ● |
| Mahindra | Thar | 06/2014-12/2019 | 433MHZ | | ○ | ● | ○ | A | 433MHZ | Schrader | ● | ● |
| Mahindra | XUV500 | 01/2013-12/2019 | 433MHZ | | ○ | ● | ○ | A | 433MHZ | Schrader | ● | ● |
| Mahindra | e20 | 06/2014-12/2019 | 433MHZ | | ○ | ● | ○ | A | 433MHZ | Schrader | ● | ● |
| Maserati | 4200 | 06/2001-12/2007 | 433MHZ | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Maserati | Alfieri | 01/2016-06/2020 | 433MHZ | M165 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Maserati | Coupe | 07/2009-12/2013 | 433MHZ | M145 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Maserati | Coupe | 01/2002-06/2009 | 433MHZ | M145 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Maserati | GT Coupe | 03/2014-06/2019 | 433MHZ | M138 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Maserati | GT Coupe | 01/2014-06/2019 | 433MHZ | M145 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Maserati | GT Coupe | 01/2002-12/2013 | 433MHZ | M145 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------------|-----------------|------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Maserati | Ghibli | 01/2013-09/2020 | 433MHz | M156/M157 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Maserati | GranCabrio | 07/2015-12/2017 | SCH 433MHz | M147 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Maserati | GranCabrio | 09/2009-12/2019 | Huf 433MHz | M147 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Maserati | GranCabrio | 01/2008-08/2009 | 433MHz | M147 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 01/2008-08/2010 | 433MHz | M145 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 01/2014-12/2019 | 433MHz | M145 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Maserati | GranTurismo | 09/2010-12/2013 | 433MHz | M145 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Maserati | GranTurismo Sport | 01/2016-07/2017 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Maserati | GranTurismo Sport | 08/2017-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Maserati | Levante | 01/2016-06/2020 | 433MHz | M161 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Maserati | Levante | 04/2015-12/2017 | 433MHz | WM | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Maserati | Quattroporte | 01/2013-06/2021 | 433MHz | M156 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Maserati | Quattroporte | 01/2011-12/2015 | 433MHz | M139 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 01/2010-12/2010 | 433MHz | M139 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 04/2003-12/2009 | 433MHz | M139 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Maybach | GLS SUV | 01/2019-06/2020 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Maybach | Landulet | 01/2018-12/2019 | 433Mhz | | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Maybach | Landulet | 10/2008-12/2014 | 433MHz | Ma009-127 | ● | ● | ○ | 0/S | 433Mhz | Huf/Beru | ● | ● |
| Maybach | Maybach 57 | 02/2002-12/2013 | 433Mhz | Ma007 | ● | ● | ○ | 0/S | 433Mhz | Huf/Beru | ● | ● |
| Maybach | Maybach 62 | 02/2002-12/2013 | 433Mhz | Ma007 | ● | ● | ○ | 0/S | 433Mhz | Huf/Beru | ● | ● |
| Maybach | S Series | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Mazda | B Series LCV | 05/2011-12/2018 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Mazda | BT Pickup | 05/2011-12/2019 | 433MHz | J26E | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Mazda | BT-50 | 01/2012-06/2020 | 433MHz | J26E | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Mazda | CX-3 | 08/2014-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mazda | CX-3 | 08/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-5 | 11/2014-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-5 | 11/2011-12/2019 | 433MHz | J53C/J72A | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mazda | CX-7 | 10/2009-12/2018 | 433MHz | J31H | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mazda | CX-9 | 10/2006-12/2012 | 433MHz | J50C | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mazda | CX-9 | 01/2016-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-9 | 01/2013-12/2019 | 433MHz | J50C | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mazda | MX-5 | 03/2010-12/2019 | 433MHz | NC/J04C/J12A | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mazda | MX-5 | 03/2015-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 2 | 02/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 2 | 12/2007-12/2019 | 433MHz | DY/DE/DJ/J03/J64F | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mazda | Mazda 3 | 06/2009-05/2014 | 433MHz | BL/BM | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mazda | Mazda 3 | 06/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 3 | 06/2014-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mazda | Mazda 5 | 01/2010-12/2019 | 433MHz | J74G | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2008-12/2010 | 433MHz | GH/GJ | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|------------------|-----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mazda | Mazda 6 | 01/2011-12/2019 | 433MHz | GH/GJ/J61A/J71E | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Premacy | 03/2014-12/2018 | 433MHz | J54L | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| McLaren | 500 Series | 01/2015-12/2016 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| McLaren | 500 Series | 01/2017-12/2019 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 03/2014-12/2019 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| McLaren | 700 Series | 01/2017-12/2019 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| McLaren | MP4-12C | 06/2011-04/2014 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| McLaren | P1 | 01/2013-12/2019 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| McLaren | Senna | 01/2017-12/2019 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| McLaren | Sports Series | 01/2015-06/2020 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| McLaren | Super Series | 03/2011-06/2020 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | A Class | 04/2014-05/2018 | 433MHz | W176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | A Class | 01/2012-03/2014 | 433MHz | W176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | A Class | 06/2018-12/2019 | 433MHz | W177 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | AMG | 07/1999-03/2002 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | AMG | 01/2010-12/2019 | 433MHz | W197 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 11/2018-12/2019 | X290 | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 08/2019-12/2021 | C190 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 11/2018-12/2019 | X290 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 01/2014-06/2020 | C190 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | B Class | 11/2011-01/2019 | W246/W242 433MHz | W246 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | B Class | 02/2019-06/2020 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | C Class | 03/2014-05/2018 | 433MHz | W205 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | C Class | 01/2000-12/2006 | 433MHz (W203) | W203 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | C Class | 04/2007-02/2014 | 433MHz | W204/W203 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | C Class | 08/2019-12/2021 | 433MHz | C205 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | C Class | 06/2018-06/2020 | 433MHz | W205 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CL Class | 06/2009-06/2019 | 433MHz | C216/C217 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CL Class | 01/2006-07/2009 | 433MHz (C216) | C216 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | CL Class | 01/1998-02/2006 | 433MHz | C215 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | CLA Class | 05/2019-06/2020 | 433Mhz | C118 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | CLA Class | 06/2014-04/2019 | 433MHz | C117 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CLA Class | 12/2012-05/2014 | 433MHz | C117 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CLC Class | 01/2008-06/2018 | 433MHz | CL203 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CLK Class | 04/2007-06/2018 | 433MHz | W209/W207 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CLS Class | 10/2004-12/2004 | 433MHz | W219 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | CLS Class | 01/2018-06/2020 | C257 433MHz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CLS Class | 07/2009-12/2017 | 433MHz | W218 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CLS Class | 01/2005-06/2009 | 433MHz | W219 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | Citan | 01/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercedes | Citan | 09/2012-06/2020 | 433MHz | W415 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | E Class | 07/2018-06/2020 | 433MHz (W213) | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Mercedes | E Class | 11/2015-12/2019 | W213/BR238 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | E Class | 06/2014-12/2018 | W212 433MHz | W212 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | E Class | 01/2014-10/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercedes | E Class | 07/2009-05/2014 | 433MHz | W212 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | E Class | 06/2005-06/2009 | 433MHz | W211 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Mercedes | E Class | 01/2002-05/2005 | 433MHz | W211 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | E Class AMG | 07/1999-03/2002 | 433MHz | W210 | ● | ● | ○ | 0/S | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | EQC | 09/2019-06/2020 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | G Class | 01/2014-06/2020 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | G Class | 04/2007-05/2018 | 433MHz | 463 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | G Class | 01/2018-12/2019 | 315Mhz | G463/461 | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Mercedes | G Class | 06/2018-06/2020 | 433Mhz | G463/461 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GL Class | 04/2006-09/2009 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Mercedes | GL Class | 06/2009-12/2012 | 433MHz | X164 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GL Class | 01/2013-06/2019 | 433MHz | X166 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLA Class | 08/2019-03/2020 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLA Class | 06/2014-07/2019 | 433MHz | X156 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLB Class | 01/2019-06/2020 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | GLC Class | 08/2019-07/2022 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLC Class | 01/2015-07/2019 | 433MHz | X253 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLE Class | 09/2015-11/2019 | 433MHz | X166 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLE Class | 01/2019-06/2020 | 433Mhz | V167 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | GLK Class | 10/2015-06/2019 | 433MHz | X253 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLK Class | 01/2008-09/2015 | 433MHz | X204 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLS Class | 07/2019-06/2020 | 433Mhz | X167 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | GLS Class | 01/2013-06/2019 | X166 433MHz | X164 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLT | 06/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Mercedes | GT | 09/2018-06/2020 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GT-S AMG | 01/2014-12/2019 | 433MHz | C190 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | M Class | 01/2010-12/2014 | 433MHz | W166 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | M Class | 01/2005-05/2011 | 433Mhz | W164 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Mercedes | ML Class | 06/2011-12/2019 | 433MHz | W166 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | ML Class | 08/2009-05/2011 | 433MHz | W164 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | ML Class | 07/2005-07/2009 | 433MHz | W164 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Mercedes | Marco Polo | 01/2014-12/2019 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Metris | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | R Class | 06/2005-07/2009 | 433MHz | W251 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Mercedes | R Class | 08/2009-06/2018 | 433MHz | W251 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | S Class | 08/2019-06/2020 | 433MHz | W222 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | S Class | 07/2013-07/2019 | 433MHz | W222 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | S Class | 06/2009-06/2013 | 433MHz | W221 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | S Class | 07/1999-09/2005 | 433MHz | W220 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | S Class | 10/2005-05/2009 | 433MHz | W221 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Mercedes | S Class coupe | 01/2003-09/2005 | 433MHz | C215 | ● | ● | ○ | 0/S | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | S Class coupe | 07/1999-12/2002 | 433MHz | C215 | ● | ● | ○ | 0/S | 433Mhz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | S Class coupe | 01/2013-06/2020 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | SL Class | 05/2005-12/2011 | 433Mhz | W230 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Mercedes | SL Class | 01/2000-04/2005 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | SL Class | 01/2012-06/2020 | 433Mhz | W231 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | SL Roadster | 08/2001-06/2005 | 433MHz | R230 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | SLC Class | 01/2016-07/2019 | 433MHz | R172 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | SLC Class | 08/2019-06/2021 | 433MHz | R172 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | SLK Class | 04/2007-05/2019 | 433MHz | R171, R172 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | SLR Class | 04/2004-12/2015 | 433MHz | R199 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | SLR McLaren | 01/2004-12/2011 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | SLS Class | 01/2010-06/2019 | 433MHz | 197 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Sprinter | 06/2006-10/2011 | 433MHz | W906 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Mercedes | Sprinter | 11/2011-06/2020 | 433MHz | 906 (NVC3) | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Sprinter | 01/2018-06/2020 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | Sprinter Combi | 01/2006-10/2011 | 433MHz | 906 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Mercedes | Sprinter Combi | 10/2018-12/2019 | 433Mhz | 906 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | Sprinter Combi | 11/2011-09/2018 | 433MHz | 906 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | V Class | 01/2014-12/2019 | 433Mhz | W447 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Vario | 03/2014-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Vario | 12/2012-12/2013 | 433MHz | | ● | ● | ○ | 0/S | 433Mhz | Schrader | ● | ● |
| Mercedes | Viano | 07/2003-05/2014 | Continental 433MHz | W639 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Mercedes | Viano | 06/2014-06/2019 | SCH 433Mhz | W639 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Vito | 07/2014-06/2020 | 433MHz | W640 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Vito | 05/2003-06/2014 | 433MHz | W639 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Mercedes | X Class | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Mini | 3-5 Doors Hatch | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | All | 08/2007-10/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Cabrio | 07/2014-12/2015 | R57 433MHz | R57 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Cabrio | 01/2016-12/2019 | F57 433MHz | F57 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Cabrio | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Clubman | 11/2013-12/2019 | 433Mhz | F54 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Clubman | 09/2009-10/2013 | 433MHz | R55 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Clubman | 08/2007-08/2009 | 433MHz | R55 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Clubvan | 01/2016-12/2019 | 433MHz | F54 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Clubvan | 07/2012-12/2015 | 433MHz | R55 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Convertible | 01/2016-12/2019 | 433MHz (F57) | F57 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Convertible | 01/2014-12/2016 | 433MHz (R57) | R57 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Cooper | 06/2015-12/2019 | F55, F56 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Cooper | 03/2014-05/2015 | 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Cooper | 09/2007-09/2009 | 433MHz | R58 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Cooper S Cabrio | 07/2014-12/2017 | 433MHz | R57 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Countryman | 07/2015-06/2020 | 433Mhz | F60 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Countryman | 07/2014-12/2018 | 433Mhz | R60 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Countryman | 01/2009-06/2014 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|------------------|-----------------|-----------------|----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mini | Coupe | 07/2011-06/2018 | 433MHz | R58 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Hatchback | 11/2013-12/2019 | 433MHz | F56 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Mini | 01/2010-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Mini | 03/2014-12/2019 | 433MHz | F55/F56 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Mini | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | One | 03/2014-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Paceman | 07/2018-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Paceman | 07/2014-06/2018 | 433MHz | R61 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Paceman | 01/2009-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Roadster | 05/2014-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Roadster | 12/2011-12/2014 | 433MHz | R59 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | SAV Studie | 07/2014-12/2014 | 433MHz | R58 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mitsubishi | ASX | 01/2014-12/2020 | 433Mhz | GA0 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | Attrage | 03/2014-06/2020 | 433Mhz | A10 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | B-SUV | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | C-SUV | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Colt | 03/2014-12/2018 | 433MHz | ZM | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | Colt Plus | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Mitsubishi | Eclipse Cross | 03/2017-12/2020 | Snap-in 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross | 01/2017-12/2019 | Clamp-in 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | L200 | 03/2014-12/2020 | 433Mhz | KA0T/KJOT | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | Lancer | 03/2014-12/2019 | 433MHz | CY0 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | Lancer Sportback | 01/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 05/2013-06/2020 | 433Mhz | A00 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | Mirage G4 | 03/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | Montero | 03/2014-12/2019 | 433MHz | V80 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | Outlander | 01/2014-12/2019 | 433MHz | CWO/GFO | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | Outlander | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Mitsubishi | Pajero | 03/2014-12/2019 | 433MHz | V80 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | Shogun | 06/2014-12/2019 | 433MHz | V80 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | Shogun Sport | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | Shogun Sport | 01/2018-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mitsubishi | Spacestar | 03/2014-12/2019 | 433MHz | A00 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Mitsubishi | i-MiEV | 03/2014-12/2020 | 433Mhz | HA0/HAV/HA3W | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | 370Z | 08/2014-12/2019 | PAC 433MHz | RC53D(2)/Z34 | ● | ● | ○ | O/A | 433Mhz | Pacific | ● | ● |
| Nissan | 370Z | 01/2008-07/2014 | 433MHz | C53D/Z34 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | Almera | 01/2013-12/2019 | 433MHz | LB1A/G11/B10 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Armada | 01/2004-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | Atleon | 01/2014-12/2019 | 433MHz | F91A/F91B/F91G | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | B-EV | 01/2014-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | C-Hatch | 10/2014-06/2019 | 433MHz | B12L/C13 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-------------|-----------------|--------------------|-----------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Cabstar | 06/2014-12/2019 | 433MHz | F91A/F24 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Cube | 10/2014-12/2019 | 433MHz | X12B | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Cube | 01/2008-09/2014 | 433MHz | Z12/X12B | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | Evalia | 01/2012-12/2019 | 433MHz | X11M | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Frontier | 10/2002-08/2014 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | Frontier | 09/2014-06/2019 | 433MHz | H60A | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | GT-R | 01/2016-12/2019 | VDO 433MHz | D52E | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | GT-R | 11/2013-03/2020 | PAC 433Mhz | D52E | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | GT-R | 09/2007-12/2013 | 433MHz | R35 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | Interstar | 06/2014-06/2019 | 433MHz | X70 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | Juke | 06/2010-12/2019 | 433MHz | F15/P12C | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | Leaf | 12/2017-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Leaf | 10/2010-12/2016 | 433MHz | ZE0/B12G | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | Micra | 03/2014-12/2019 | 433MHz | B02A/K13 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | Micra | 04/2010-01/2017 | 433MHz | K13 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | Micra | 02/2017-12/2019 | 433Mhz | K14 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Murano | 01/2015-12/2019 | Russia 433MHz | Z52 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Murano | 10/2014-05/2015 | P42M 433MHz | P42M | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Murano | 06/2014-12/2019 | P42M 433MHz | Z51/Z52/P42M | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | Murano | 10/2007-09/2014 | P42D 433MHz | Z51/P42D | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | NP300 | 01/2009-10/2015 | 433MHz Schrader | H61B | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | NP300 | 09/2014-12/2019 | 433MHz | H60A | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | NT500 | 03/2014-06/2019 | 433MHz | F91G | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | NV200 | 01/2016-06/2017 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Nissan | NV200 | 08/2015-12/2019 | 433MHz | M20/X11M | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | NV200 | 10/2014-07/2015 | 433MHz | M20/X11M | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | NV200 | 09/2009-12/2019 | 433Mhz Continental | K14 | ● | ● | ○ | 0/S | 433Mhz | Continental | ● | ● |
| Nissan | NV200 EV | 04/2014-12/2019 | 433MHz | ME0 | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Nissan | NV300 | 09/2014-12/2019 | 433MHz | J4/X82 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | NV400 | 01/2014-12/2019 | 433MHz | X62 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | NV400 Combi | 03/2014-12/2019 | 433MHz | X61F | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Navara | 01/2017-06/2020 | 433MHz | Y62 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | Navara | 10/2004-12/2016 | 433MHz | D22/D23/D40/H61B/H60A | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | Note | 09/2004-12/2019 | 433MHz | J02C/E12/L11E | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Pathfinder | 08/2004-08/2012 | 433MHZ | R51 | ● | ● | ○ | 0 | 433MHZ | Continental | ● | ● |
| Nissan | Pathfinder | 11/2015-12/2019 | 433MHz | R52/P61B | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Pathfinder | 09/2012-10/2015 | 433MHZ | P61B | ● | ● | ○ | 0 | 433MHZ | Continental | ● | ● |
| Nissan | Patrol | 12/2014-12/2019 | 433MHz | Y62 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | Patrol | 01/2010-11/2014 | 433MHz | Y61/Y62 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | Pixo | 01/2009-12/2014 | 433MHz | YC5 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | Primastar | 01/2014-06/2019 | 433MHz | X83 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|------------------|-----------------|------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Primera | 01/2002-12/2008 | 433MHz | P12/B12L | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | Pulsar | 01/2014-12/2019 | 433MHz | C13M/C13/B12L | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | QX50 | 02/2018-12/2019 | PAC 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | Qashqai | 06/2019-12/2019 | 433MHz | J10/J11/P32S | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Nissan | Qashqai | 06/2018-05/2019 | 433MHz | J10/J11/P32S | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Nissan | Qashqai | 01/2014-05/2018 | 433MHz | J10/J11/P32S | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Nissan | Qashqai | 01/2013-12/2013 | 433MHz | J10/J11/P32S | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Nissan | Rogue | 10/2013-12/2019 | 433MHz | T32 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Sentra | 01/2013-12/2019 | 433MHz | L12F | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | TERRANO | 06/2014-12/2019 | 433MHz | H79N | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | Teana | 02/2013-04/2018 | 433MHz | L33 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Teana | 05/2018-12/2019 | 433MHz | L42L | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Terra | 01/2018-12/2019 | 433MHz | Y62 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Nissan | Tiida | 01/2012-12/2019 | 433MHz | C11/B12/B11C | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Titan | 10/2003-08/2004 | 433MHz | A60 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Nissan | X-Trail | 11/2013-08/2016 | 433MHz | T32/P32R | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | X-Trail | 09/2016-12/2019 | 433MHz | T32 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Nissan | Xterra | 01/2012-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Adam | 07/2014-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Adam | 01/2012-06/2014 | 433MHz | GM 4403 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Adam S & Rocks S | 07/2014-12/2019 | 433MHz | | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Adam Turbo | 01/2015-12/2019 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Agila | 06/2014-12/2019 | 433MHz | H0310 | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Opel/Vauxhall | Ampera | 01/2015-12/2019 | 433MHz | D2JCI | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Ampera | 07/2005-12/2017 | 433MHz | D1JOI | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Ampera-e | 01/2016-12/2019 | 433MHz | G2KCZ | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 01/2016-12/2019 | 433Mhz | C105 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 06/2014-12/2015 | 433Mhz | C105 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 11/2010-05/2014 | 433Mhz | C105 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 01/2006-10/2010 | 433Mhz | C105 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra GTC | 01/2015-12/2015 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra GTC | 01/2016-12/2018 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra H | 01/2004-09/2009 | 433MHz | GM A3300 | ● | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 06/2014-12/2014 | 433MHz | GM P3400 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 01/2009-09/2011 | 433MHz | GM P3400 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 10/2011-05/2014 | 433MHz | GM P3400/GM A3300 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 01/2015-12/2017 | 433MHz | GM P3400 | ● | ● | ● | 0/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J OPC | 06/2014-12/2015 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J OPC | 10/2011-05/2014 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J OPC | 01/2009-09/2011 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|---------------------|-----------------|---------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Opel/Vauxhall | Astra K | 10/2015-12/2019 | 433MHz | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Sports Tourer | 06/2015-12/2018 | 433MHz | D2J0 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Sports Tourer | 01/2015-12/2015 | 433MHz | | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Van | 01/2006-12/2013 | 433MHz | GM A3300 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Van | 01/2015-12/2018 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Van | 01/2014-12/2014 | 433MHz | D2J0/ GM P3400 | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Bolt | 01/2017-06/2020 | 433MHz | G2KCZ | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Cabrio | 06/2014-12/2019 | 433MHz | | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Cabrio | 01/2013-05/2014 | 433MHz | | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Cascada | 01/2013-05/2014 | 433MHz | D1A0 | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Cascada | 06/2014-12/2019 | 433MHz | D1A0 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Combo | 10/2011-06/2018 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Combo Life | 06/2018-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Combo Tourer | 03/2011-05/2018 | 15 inch 433MHz | 263 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Combo Tourer | 03/2011-05/2018 | 16 inch 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 01/2014-10/2014 | 433MHz | GM S4400 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 01/2006-06/2014 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Corsa | 01/2006-12/2013 | 433MHz | GM S4400 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 11/2014-06/2020 | Turbo 433MHz | C0145 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 11/2014-12/2019 | Non Turbo 433MHz | C0145 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa Opc | 01/2015-12/2018 | 433MHz | | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa VXR | 01/2015-12/2018 | 433MHz | | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa Van | 01/2014-12/2018 | 433MHz | GM 4530 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Crossland | 01/2017-06/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Equinox | 01/2017-12/2019 | 433MHz | D2UC | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | GTC | 10/2015-06/2020 | 433MHz | | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Grandland | 01/2017-06/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Insignia | 06/2017-06/2020 | 433MHz | | ● | ● | ● | O/S/A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 05/2014-09/2015 | 433MHz | GM G3700 | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 01/2008-04/2014 | 433Mhz | GM G3700 | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 10/2015-05/2017 | 433MHz | GM G3700 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia CT | 01/2015-12/2019 | 433MHz | | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia ST | 01/2015-12/2019 | 433MHz | | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Karl/Viva | 01/2015-12/2019 | 433MHz | M2J0 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Maloo | 06/2016-12/2017 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Maloo R8 LSA | 01/2014-12/2018 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Meriva B | 07/2014-06/2017 | 433MHz | GM S4470 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Mokka | 08/2015-09/2016 | 433MHz | G1U0 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Mokka | 01/2012-07/2015 | 433MHz | G1U0 | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Mokka X | 10/2016-12/2019 | 433MHz | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Movano B | 06/2009-06/2020 | 433MHz | X62 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|---------------------|-----------------|----------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Opel/Vauxhall | Signum | 08/2002-08/2009 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | VXR8 | 01/2008-12/2019 | 433MHz | Z2 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Vectra | 08/2002-06/2009 | 433MHz | 0e86/ GM Z3200 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Vectra Estate | 06/2009-06/2014 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Viva | 01/2015-12/2019 | 433Mhz | M2J0 | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Vivaro B | 01/2015-12/2019 | 433MHz | X82/X83 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Vivaro B | 03/2014-12/2014 | 433MHz | X82/X83 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Vivaro Combi/Tourer | 01/2019-06/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Zafira | 01/2005-06/2011 | 433MHz | GM A3370 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira B | 06/2014-12/2019 | 433MHz | B | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira B | 01/2004-05/2014 | 433MHz | B | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira Tourer C | 06/2014-12/2019 | 433MHz | C/ GM P3470 | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira Tourer C | 01/2009-05/2014 | 433MHz | C/ GM P3470 | ● | ● | ● | O/A | 433Mhz | Schrader | ● | ● |
| Peugeot | 1007 | 10/2004-04/2011 | 433MHz | A08/PF1 | ● | ● | ○ | O | 433Mhz | Continental | ● | ● |
| Peugeot | 107 | 01/2012-12/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 108 | 06/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 108 | 06/2014-12/2018 | 433MHz | B3 | ● | ● | ○ | O/S | 433Mhz | Pacific | ● | ● |
| Peugeot | 2008 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 2008 | 02/2013-04/2014 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Peugeot | 2008 | 05/2014-12/2019 | 433MHz | | ● | ● | ○ | O/S | 433Mhz | Schrader | ● | ● |
| Peugeot | 207 | 11/2005-09/2013 | 433MHz | A7 | ● | ● | ○ | O | 433Mhz | Continental | ● | ● |
| Peugeot | 207 | 10/2013-12/2016 | 433MHz | A7 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Peugeot | 207+ | 01/2013-12/2013 | 433MHz | | ● | ● | ○ | O | 433Mhz | Continental | ● | ● |
| Peugeot | 208 | 01/2012-12/2019 | 433MHz | A9 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Peugeot | 208 | 05/2012-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 3008 | 10/2013-12/2019 | 433MHz | T84 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Peugeot | 3008 | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 3008 | 11/2008-08/2013 | 433Mhz | T84 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Peugeot | 3008 (LCV) | 01/2008-12/2015 | 433Mhz | T84 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Peugeot | 301 | 10/2012-12/2019 | 433MHz | M3/M4 | ● | ● | ○ | O/S | 433Mhz | Schrader | ● | ● |
| Peugeot | 307 | 01/2002-02/2007 | 433MHz | | ● | ● | ○ | O | 433Mhz | Continental | ● | ● |
| Peugeot | 307 | 03/2007-12/2008 | 433MHz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Peugeot | 308 | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | 308 | 09/2013-12/2019 | 433Mhz | T7 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Peugeot | 308 | 04/2007-08/2013 | 433Mhz | T7 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Peugeot | 4008 | 01/2014-12/2019 | 433MHz | J3 | ● | ● | ○ | O/S | 433Mhz | Continental | ● | ● |
| Peugeot | 407 | 01/2004-08/2011 | 433MHz | D2 | ● | ● | ○ | O | 433Mhz | Continental | ● | ● |
| Peugeot | 408 | 01/2013-12/2019 | 433MHz | T73 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Peugeot | 5008 | 09/2013-12/2019 | 433MHz | T87 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Peugeot | 5008 | 01/2009-08/2013 | 433MHz | T87 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Peugeot | 5008 | 10/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 5008 (LCV) | 01/2009-12/2017 | 433MHz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------|-----------------|------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Peugeot | 508 | 09/2010-09/2013 | 433Mhz | W2 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Peugeot | 508 | 10/2013-12/2019 | 433Mhz | W2 | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Peugeot | 508 | 10/2018-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 508 (LCV) | 09/2010-12/2017 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Peugeot | 607 | 01/2000-09/2004 | 433MHz | 6042/Z8 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Peugeot | 607 | 10/2004-12/2011 | 433Mhz | Z8 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Peugeot | 807 | 06/2002-09/2004 | 433MHz | V2/8052 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Peugeot | 807 | 10/2004-12/2015 | 433Mhz | V2/80092 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Peugeot | Bipper | 01/2013-12/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Peugeot | Bipper | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Boxer | 01/2010-04/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Boxer | 05/2014-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Schrader | ● | ● |
| Peugeot | Boxer Combi | 12/2013-12/2019 | 433MHz | X2/50 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Peugeot | Expert | 01/2011-05/2014 | 433MHz | G9 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Peugeot | Expert | 06/2014-12/2016 | 433MHz | G9 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Peugeot | Expert | 10/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | ION | 01/2011-12/2019 | 433MHz | | ● | ● | ○ | 0/S | 433Mhz | Continental | ● | ● |
| Peugeot | Partner | 01/2008-05/2014 | 433MHz | B9 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Peugeot | Partner | 03/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | Partner | 06/2014-12/2019 | 433MHz | B9 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Peugeot | RCZ | 02/2010-09/2013 | 433Mhz | T75 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Peugeot | RCZ | 10/2013-06/2017 | 433Mhz | T75 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Peugeot | Rifter | 06/2018-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Traveller | 10/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Porsche | 718 (982) | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | 911 | 07/2004-01/2012 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | 911 (991) | 09/2015-12/2019 | 433Mhz | 991 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | 911 (991) | 12/2011-08/2015 | 433MHz | 991 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | 911 (992) | 01/2019-06/2020 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | 911 (997) | 07/2004-03/2008 | 433MHz | 997 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | 911 (997) | 09/2015-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | 911 (997) | 04/2008-08/2015 | 433MHz | 997 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | 911 (Turbo) | 01/2007-12/2009 | 433MHz | 997 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | 911 (Turbo) | 01/2010-12/2019 | 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | 918 Spyder | 03/2012-06/2018 | 433MHz | 918 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2005-12/2008 | 433MHz | 987 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2009-12/2013 | 433MHz | 987 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2014-02/2016 | 433MHz | 981 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Boxster | 03/2016-12/2019 | 433Mhz 982 | 982 | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Carrera GT | 01/2003-12/2006 | 433MHz | GT | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2002-12/2006 | 433MHz | 9PA | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 05/2014-08/2017 | 433MHz | 92A | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 09/2017-12/2019 | 433MHz | 92A | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2011-04/2014 | 433MHz | 92A | ● | ● | ○ | 0/A | 433Mhz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Porsche | Cayenne | 01/2007-12/2010 | 433MHz | 9PA | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 09/2017-12/2019 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 06/2014-08/2017 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 01/2007-12/2009 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2009-12/2015 | 987 433MHz | 987 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2005-12/2008 | 987 433MHz | 987 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayman | 05/2014-12/2016 | GTS 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayman | 04/2013-12/2016 | 981 433MHz | 981 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Cayman (718) | 10/2016-06/2020 | 982 433MHz | 982 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | GT3 | 03/2006-12/2009 | 433Mhz | 996 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2010-12/2016 | 433Mhz | 997 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Macan | 07/2013-06/2020 | 433MHz | P0416 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2009-06/2013 | 433MHz | 970 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Panamera | 07/2013-08/2017 | 433MHz | 970 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Panamera | 09/2017-06/2020 | 433MHz | 970 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | Taycan | 11/2018-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| QOROS | 3 | 01/2014-12/2019 | 433Mhz J523114013 | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| QOROS | 5 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Qoros | 2 | 01/2016-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Qoros | 3 | 01/2016-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Renault | Alaskan | 04/2017-12/2019 | 433Mhz | | ○ | ● | ○ | C | 433Mhz | Pacific | ● | ● |
| Renault | Alaskan Pickup | 11/2016-12/2019 | 433Mhz | | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Renault | Alpine A110 | 07/2018-12/2019 | 433Mhz | | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Renault | Arkana | 01/2019-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Captur | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Captur | 01/2013-12/2019 | 433Mhz | J87 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Renault | Clio III | 04/2005-05/2014 | X85 433MHz | X85 | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Renault | Clio IV | 06/2014-12/2019 | X85/X98 433MHz | X85/X98 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Renault | Clio IV | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Espace IV | 07/2002-12/2014 | 433Mhz | J81 | ● | ● | ● | O | 433Mhz | Schrader | ● | ● |
| Renault | Espace V | 01/2015-12/2019 | 433Mhz | JFC | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Renault | Fluence | 01/2009-12/2019 | L38 433Mhz | L38 | ● | ● | ○ | O | 433Mhz | Continental | ● | ● |
| Renault | Initiale Paris | 01/2015-12/2019 | 433Mhz | | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Renault | Kadjar | 04/2015-12/2019 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Renault | Kangoo | 10/2017-12/2019 | 433MHz | XFG | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Renault | Kangoo | 10/2007-12/2017 | 433MHz | X61 | ● | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Renault | Kangoo Van | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Renault | Kaptur | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Renault | Koleos | 01/2013-07/2016 | Y 433Mhz | | ● | ● | ○ | O | 433Mhz | Continental | ● | ● |
| Renault | Koleos | 08/2016-06/2020 | 433Mhz | | ● | ● | ○ | O | 433Mhz | Continental | ● | ● |
| Renault | Koleos | 02/2008-12/2015 | LCV 433MHz | H45 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Renault | Koleos | 01/2008-12/2013 | 433Mhz | H45 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|----------------|-----------------|--------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Renault | Laguna II | 12/2000-09/2007 | 433Mhz | X74 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Renault | Laguna III | 06/2007-12/2015 | X91 433Mhz | X91 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Renault | Laguna IV | 04/2015-06/2019 | 433Mhz | LFD | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Renault | Latitude | 09/2010-12/2015 | 433Mhz | L43 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Renault | Latitude | 01/2016-06/2018 | 433Mhz | LFD | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Renault | Master | 11/2009-12/2019 | 433Mhz | X62 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Renault | Megane I | 01/1997-08/2002 | B32/X95/X64 433MHz | B32/X95/X64 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Renault | Megane II | 09/2002-04/2009 | B32/X84 433MHz | B32/X84 | ● | ● | ● | 0 | 433Mhz | Continental | ● | ● |
| Renault | Megane III | 10/2008-03/2016 | X95 433Mhz | X95 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Renault | Megane IV | 01/2016-06/2020 | RFB 433MHz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Renault | Modus | 04/2004-12/2012 | 433Mhz | J77 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Renault | Oroch Pickup | 01/2015-12/2019 | 433Mhz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Renault | Scenic I | 01/2001-05/2003 | 433Mhz | J64 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Renault | Scenic II | 05/2003-06/2009 | 433Mhz | J95 | ● | ● | ● | 0 | 433Mhz | Continental | ● | ● |
| Renault | Scenic III | 01/2009-10/2016 | 433Mhz | J95 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Renault | Scenic IV | 01/2016-06/2020 | 433Mhz | JFA | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Renault | Scenic RX4 | 01/2001-06/2003 | JA 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Renault | Symbol/Thalia | 01/2013-12/2019 | L52 433MHz | L52 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Renault | Talisman | 06/2015-12/2019 | RFD 433Mhz | | ● | ● | ○ | 0/A | 433Mhz | Continental | ● | ● |
| Renault | Trafic | 01/2014-12/2019 | X82 433MHz | X82 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Renault | Twingo | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Twingo | 01/2007-12/2019 | X44 433MHz | X44 | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| Renault | Vel Satis | 09/2001-12/2009 | 433Mhz | X73 | ● | ● | ● | 0 | 433Mhz | Schrader | ● | ● |
| Renault | Wind | 06/2010-12/2016 | 433Mhz | X33 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Renault | Zoe | 09/2012-12/2019 | 433Mhz | X10 | ● | ● | ○ | 0 | 433Mhz | Continental | ● | ● |
| Retrofit | ORO W401 | 01/2018-06/2019 | 433Mhz | | ○ | ● | ○ | S | 433Mhz | ORO | ● | ● |
| Retrofit | ORO W410-A | 01/2018-06/2019 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | ORO | ● | ● |
| Retrofit | ORO W410/W403 | 01/2018-06/2019 | 433Mhz | | ○ | ● | ○ | S | 433Mhz | ORO | ● | ● |
| Retrofit | ORO W417-A | 01/2019-12/2019 | 433Mhz | | ○ | ● | ○ | A/S | 433Mhz | ORO | ● | ● |
| Retrofit | ORO W418-A | 01/2018-06/2019 | 433Mhz | | ○ | ● | ○ | A/S | 433Mhz | ORO | ● | ● |
| Rolls Royce | Black Badge | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Rolls Royce | Cabrio | 06/2009-12/2011 | 433MHz | RR02 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Rolls Royce | Cullinan | 03/2018-06/2020 | 433MHz | R31 | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Rolls Royce | Dawn | 04/2014-12/2015 | 433MHz | RR6 | ○ | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Rolls Royce | Dawn | 01/2016-06/2020 | 433MHz | RR6 | ○ | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Rolls Royce | Drophead Coupe | 01/2008-12/2017 | 433MHz | RR02 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 01/2010-06/2020 | 433MHz | RR04 | ○ | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 01/2009-12/2010 | 433Mhz | RR04 | ○ | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 01/2017-12/2019 | PR11 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Rolls Royce | Phantom | 01/2007-12/2011 | 433MHz | RR01 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 01/2012-12/2016 | 433MHz | RR02 | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 08/2013-06/2020 | 433Mhz | RR04 | ○ | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Saab | 9-3 | 01/2003-09/2006 | 433MHz | YS3F | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Saab | 9-3 | 10/2006-05/2009 | 433MHz | YS3F | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|----------|-----------------|----------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Saab | 9-3 | 06/2009-12/2012 | 433MHz | YS3F | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Saab | 9-3 | 01/2013-12/2014 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Saab | 9-3X | 01/2009-12/2011 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Saab | 9-4X | 01/2011-06/2014 | 433MHz | | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Saab | 9-5 | 07/2002-10/2006 | 433MHz | YE3E | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Saab | 9-5 | 11/2006-09/2009 | 433MHz | YE3E | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Saab | 9-5 | 10/2009-12/2012 | 433MHz | YS3G | ● | ● | ● | 0/A | 433Mhz | Schrader | ● | ● |
| Saab | 9-7X | 01/2007-12/2009 | 433MHz | | ○ | ● | ○ | S | 433Mhz | Schrader | ● | ● |
| Scion | TC | 01/2015-12/2018 | 433MHz | 745L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Seat | Alhambra | 05/2010-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Altea | 01/2010-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Arona | 03/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Ateca | 09/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Exeo | 01/2009-02/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Exeo | 06/2013-07/2015 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Seat | Ibiza | 01/2010-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Leon | 01/2010-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Mii | 06/2012-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Tarraco | 01/2018-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Toledo | 01/2011-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Citigo | 01/2011-04/2014 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Citigo | 05/2014-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Citigo | 01/2012-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Fabia | 01/2015-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Fabia | 10/2013-12/2014 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Fabia | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Kamiiq | 09/2019-12/2020 | 433MHz | | ● | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Karoq | 05/2017-12/2019 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Karoq | 01/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Kodiaq | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Kodiaq | 11/2016-06/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Octavia | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Octavia | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Octavia | 10/2012-12/2014 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Praktik | 01/2013-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Rapid | 05/2012-04/2015 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Rapid | 01/2013-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Rapid | 05/2015-06/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Roomster | 01/2013-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Roomster | 01/2006-12/2018 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Scala | 01/2019-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Superb | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Superb | 05/2015-12/2016 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Superb | 01/2017-06/2020 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Skoda | Superb | 03/2008-04/2015 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|--------------|-----------------|-------------|-------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Skoda | Yeti | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Yeti | 06/2009-12/2018 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Smart | Forfour | 01/2005-06/2020 | 433Mhz | A453 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Smart | Fortwo | 03/2014-06/2020 | 433MHz | A452 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Smart | Fortwo | 01/2007-02/2014 | 433MHz | A451 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Ssangyong | Actyon | 01/2014-12/2019 | QJ 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Ssangyong | Actyon | 07/2018-12/2019 | Q200 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ssangyong | C-CUV | 05/2015-12/2019 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ssangyong | Chairman | 06/2014-12/2019 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Ssangyong | Korando | 08/2013-12/2019 | C200 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Ssangyong | Korando | 01/2018-12/2019 | C300 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ssangyong | Kyron | 06/2014-09/2016 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Ssangyong | LUVi | 01/2015-12/2019 | X100 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ssangyong | Musso | 01/2016-12/2019 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Ssangyong | Nomad | 06/2014-12/2017 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Ssangyong | Rexton | 01/2014-12/2017 | Y300 433MHz | | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Ssangyong | Rexton | 01/2018-12/2019 | Y400 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ssangyong | Rodius | 01/2014-12/2019 | AJ 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Ssangyong | Tivoli | 05/2015-12/2019 | X100 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Ssangyong | Turismo | 01/2014-12/2019 | AJ 433MHz | | ○ | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Ssangyong | XLV | 06/2016-06/2019 | XK 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Subaru | Ascent | 01/2018-12/2020 | 433Mhz | HR3 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | BRZ | 01/2014-06/2020 | ZC 433Mhz | ZC | ● | ● | ○ | O | 433Mhz | Pacific | ● | ● |
| Subaru | C-Concept | 06/2014-06/2018 | 433Mhz | VL9 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Crosstrek | 01/2018-12/2019 | 433Mhz | HR3 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Forester | 01/2018-12/2020 | 433MHz | FM5/PF3 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Forester | 01/2014-12/2017 | 433MHz | FM5/PF3 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Impreza | 01/2014-12/2016 | 433Mhz | 55A/MF1/ZR1 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Impreza | 01/2017-06/2020 | 433Mhz | HR3 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Justy | 01/2014-06/2018 | 433Mhz | D71A | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Legacy | 01/2014-12/2017 | 433Mhz | EZ5 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Legacy | 01/2018-12/2019 | 433Mhz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Levorg | 06/2015-06/2020 | VM 433Mhz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Outback | 01/2018-12/2020 | 433Mhz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Outback | 01/2014-12/2017 | 433Mhz | EZ5 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Trezia | 01/2014-12/2019 | 433Mhz | 217A | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Tribeca | 01/2014-12/2016 | 433Mhz | 00X | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | Tribeca | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | WRX | 01/2019-06/2020 | 433Mhz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | WRX | 01/2014-12/2018 | XK 433Mhz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | XV | 01/2014-08/2017 | 433Mhz | MF1 | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | XV | 09/2017-12/2019 | 433Mhz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Subaru | XV Crosstrek | 12/2014-02/2018 | 433Mhz | | ● | ● | ○ | O | 433Mhz | Schrader | ● | ● |
| Suzuki | Alivio | 09/2018-12/2019 | 433Mhz | YLA | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | Alto | 01/2014-12/2014 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------|-----------------|-----------------------|---|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Suzuki | Alto | 06/2014-12/2019 | 433Mhz | YC5/YRA | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | Baleno | 01/2015-12/2019 | 433Mhz | YR | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | Carry Van | 04/2015-12/2018 | 433Mhz | YV7 | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | Celerio | 03/2014-12/2019 | 433Mhz | YLA | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | Celerio | 01/2015-06/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Suzuki | Cultus | 09/2014-09/2020 | 433Mhz | YLA | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | Grand Vitara | 06/2014-12/2019 | 433Mhz | YT4 | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | Ignis | 01/2016-12/2019 | 433MHz | YJ | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Suzuki | Jimny | 11/2018-12/2019 | 433Mhz | YW5 | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | Jimny | 06/2014-10/2018 | 433Mhz | YR7 | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | Kizashi | 06/2010-12/2019 | 433Mhz | YW1 | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | SX4 | 08/2013-12/2019 | 433Mhz | YY1, YY3 | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | SX4 S-Cross | 08/2013-12/2019 | 433Mhz | YAA | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | Splash | 09/2013-12/2019 | 433Mhz | YV1/YV4/ YV5 | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | Swift | 08/2013-12/2019 | 433Mhz | YP6/YP7/YS | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Suzuki | Swift Sport | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | C | 433MHz | Continental | ● | ● |
| Suzuki | Vitara | 01/2014-12/2019 | 433Mhz | YFA/YG4/ YH4 | ○ | ● | ○ | C | 433Mhz | Continental | ● | ● |
| Tesla | Model 3 | 01/2016-06/2020 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Tesla | Model S | 01/2013-09/2014 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Baolong | ● | ● |
| Tesla | Model S | 09/2014-08/2020 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Tesla | Model X | 10/2014-06/2020 | Continental 433Mhz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Tesla | Roadster | 01/2010-12/2012 | Baolong 433MHz | | ○ | ● | ○ | A | 433Mhz | Baolong | ● | ● |
| Tesla | Roadster | 01/2008-12/2010 | Huf 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Toyota | 86 | 01/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Alphard | 10/2014-12/2019 | 433Mhz | 480L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Auris | 01/2014-12/2019 | 433Mhz | 130A/130L/1 42L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Avensis | 01/2014-12/2019 | 433Mhz | 312N/445L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Avensis | 01/2005-12/2005 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Aygo | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Aygo | 01/2014-12/2015 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | C-HR | 01/2016-12/2019 | 433MHz | 560A | ● | ● | ○ | 0/A | 433Mhz | Pacific | ● | ● |
| Toyota | Camry | 01/2014-12/2015 | 433Mhz | 045L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Camry | 01/2016-12/2019 | 433MHz | 045L | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | Corolla | 01/2013-12/2018 | 433Mhz | 366A/140A/1 50A/681N/ 079L/140N/ 340N/252L/1 50L/466A | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Corolla | 01/2019-12/2019 | 433Mhz | 740A | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Dyna | 03/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | FJ Cruiser | 06/2014-12/2019 | 433MHz | 155L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Fortuner | 03/2014-12/2019 | 433MHz | 669L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | GT86 | 01/2014-12/2019 | 433Mhz | E88 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------|-----------------|---------------|-------------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | Hiace | 06/2014-12/2020 | 433Mhz | 550N | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Highlander | 01/2013-12/2019 | 433MHZ | 397L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Highlander | 01/2014-12/2019 | Russia 315MHz | | ● | ● | ○ | 0 | 315Mhz | Pacific | ● | ● |
| Toyota | Hilux | 06/2014-12/2019 | 433Mhz | 669L/640A | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | IQ | 06/2014-12/2019 | 433MHz | 630L/630X | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Kluger | 01/2014-12/2019 | 433MHZ | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Land Cruiser | 10/2015-12/2019 | 433MHZ | 215L/611L | ● | ● | ○ | 0 | 433MHZ | Pacific | ● | ● |
| Toyota | Land Cruiser | 09/2013-09/2015 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Land Cruiser | 01/2005-08/2013 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Land Cruiser 79 | 10/2015-12/2019 | 433MHZ | | ● | ● | ○ | 0 | 433MHZ | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 10/2017-12/2019 | 433MHZ | | ● | ● | ○ | 0 | 433MHZ | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 01/2014-09/2017 | 433MHz | 611L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Mirai | 01/2015-12/2019 | 433MHZ | 470A | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Previa | 01/2014-12/2019 | 433MHz | 085X/085L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Prius | 01/2019-12/2019 | 433MHZ | | ● | ● | ○ | 0 | 433MHZ | Pacific | ● | ● |
| Toyota | Prius | 01/2014-12/2018 | 433Mhz | 590L/030A/XW30/XW50/690A/277N | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Proace | 06/2014-12/2019 | 433Mhz | G9/K0 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Toyota | Proace | 01/2012-05/2014 | 433Mhz | G9 | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| Toyota | Proace II | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Proace Verso | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | RAV4 | 11/2005-12/2012 | 433Mhz | 120L/XA30 | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | RAV4 | 01/2013-12/2018 | 433Mhz XA40 | 410A/XA40/120L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | RAV4 | 01/2018-12/2019 | 433MHZ XA50 | | ● | ● | ○ | 0 | 433MHZ | Pacific | ● | ● |
| Toyota | Sequoia | 01/2015-12/2019 | 433MHz | 200L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Sienna | 06/2014-12/2019 | 433MHz | 500N/500L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Sienta | 01/2014-12/2019 | 433MHz | 433L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Tundra | 01/2014-12/2019 | 433MHz | 480A/180L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Urban Cruiser | 06/2014-12/2019 | 433MHz | 260L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Venza | 02/2015-03/2017 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Verso | 01/2013-12/2019 | 433Mhz | 770L/151L/595L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Verso-S | 05/2014-12/2017 | 433Mhz | 770L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Toyota | Yaris | 01/2014-12/2019 | 433Mhz | 020L/850L | ● | ● | ○ | 0 | 433Mhz | Pacific | ● | ● |
| Volkswagen | Amarok | 01/2014-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Amarok | 03/2018-06/2020 | 433Mhz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Amarok | 11/2009-02/2018 | 433MHZ | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Arteon | 06/2017-06/2020 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Beetle | 01/2016-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Beetle | 12/2012-12/2019 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | CC | 01/2018-12/2019 | MQB 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | CC | 06/2011-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|------------|-----------------|----------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volkswagen | CC | 06/2011-12/2017 | 433MHz | VC17 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | CC | 01/2009-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volkswagen | CC | 01/2009-12/2010 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Caddy | 06/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Caddy | 12/2003-12/2019 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Caravelle | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Caravelle | 01/2003-12/2018 | 433MHz | VN750 | ● | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Crafter | 07/2014-06/2020 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Crafter | 04/2006-06/2014 | 433Mhz | VN830 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Volkswagen | Crafter | 04/2006-06/2014 | 433Mhz | 2E/2F | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volkswagen | Cross Blue | 04/2016-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | EOS | 02/2006-06/2018 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | EOS | 01/2014-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Golf | 10/2008-02/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Golf | 03/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Golf | 01/2009-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Jetta | 07/2010-06/2020 | 433MHz | VW361 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Jetta | 01/2010-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Magotan | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Magotan | 01/2015-12/2016 | 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Volkswagen | Magotan | 01/2008-12/2016 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Magotan | 01/2007-12/2013 | 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Volkswagen | Multivan | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Multivan | 03/2008-06/2020 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | New Beetle | 08/2011-06/2020 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | New Beetle | 02/1998-07/2011 | 433MHz | VW314 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Volkswagen | New Beetle | 01/2006-12/2011 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | New Beetle | 01/2012-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Passat | 09/2014-06/2020 | 433MHz | B8 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 03/2005-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Passat | 09/2010-08/2014 | 433MHz | B6/VW471 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 01/2005-08/2010 | 433MHz | VW451 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volkswagen | Passat CC | 09/2014-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Passat CC | 03/2008-08/2014 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 06/2010-12/2019 | 433MHz | Vh67 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 06/2007-05/2010 | 433MHz | 3D/VW611 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 12/2001-05/2007 | 433MHz | VW611 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Polo | 09/2017-06/2020 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Polo | 01/2009-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Scirocco | 06/2008-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Scirocco | 01/2008-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Sharan | 01/2008-06/2020 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Sharan | 03/2010-06/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | T-Cross | 07/2019-06/2020 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | T-ROC | 11/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------|-----------------|--------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volkswagen | Teramont | 01/2017-12/2019 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2016-06/2020 | 433MHz | VW376/5N2 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2008-02/2010 | 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Volkswagen | Tiguan | 01/2008-02/2010 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Tiguan | 01/2011-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Tiguan | 05/2011-12/2015 | 433MHz | 5N | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan L | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 08/2014-06/2020 | 433Mhz | 7P5/7P6108 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2007-12/2009 | 433MHz | VW526 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 02/2002-12/2006 | 433MHz | 7L | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 08/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Touareg | 01/2010-07/2014 | 433MHz | VW526 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Touran | 01/2015-06/2020 | 433MHz | VW378 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Touran | 07/2010-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Touran L | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Touran (LCV) | 07/2010-06/2018 | 433MHz | VW368 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Transporter | 03/2018-06/2020 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Transporter | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Transporter | 01/2012-02/2018 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | Up! | 11/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Up! | 08/2011-12/2018 | VW120 433MHz | VW120 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Volkswagen | XL1 | 07/2013-05/2016 | 433MHz | | ● | ● | ○ | C | 433Mhz | Huf/Beru | ● | ● |
| Volvo | C30 | 01/2006-12/2010 | 433Mhz | Y279 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | C30 | 01/2011-12/2013 | 433Mhz | Y279 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | C30 Electric | 01/2010-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | C30 Electric | 01/2011-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | C70 | 01/2011-06/2014 | 433Mhz | V70064 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | C70 | 01/2008-12/2010 | 433Mhz | V70064 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | C70 | 01/2006-12/2007 | 433Mhz | V70064 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | S40 | 01/2011-06/2014 | 433Mhz | V40044 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | S40 | 01/2003-12/2010 | 433Mhz | V40044 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | S60 | 07/2014-06/2020 | 433MHz | Y283 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | S60 | 01/2018-06/2020 | 433MHz | V431 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Volvo | S60 | 02/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S60 | 03/2010-06/2014 | 433MHz | Y283/V634 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Volvo | S60 | 07/2000-02/2010 | 433Mhz | P24/V664 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Volvo | S70 | 07/2014-10/2020 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | S80 | 07/2014-01/2017 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | S80 | 03/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S80 | 01/2010-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | S80 | 01/2004-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | S90 | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S90 | 01/2016-06/2020 | 433Mhz | V541 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Volvo | V40 | 01/2015-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V40 | 01/2012-06/2020 | 433Mhz | Y555, Y556 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volvo | V50 | 01/2011-12/2016 | 433MHz | V5004-124 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | V50 | 01/2003-12/2010 | 433MHz | V5004-124 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | V60 | 11/2017-06/2020 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Volvo | V60 | 09/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V60 | 07/2014-12/2019 | 433Mhz 31341893 | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | V60 | 01/2008-06/2014 | 433MHz | Y352 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | V70 | 07/2014-01/2018 | 433MHz | Y285 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | V70 | 01/2008-06/2014 | 433MHz | Y285/V714 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | V70 | 01/2000-12/2007 | 433Mhz | Y285/V764 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Volvo | V90 | 01/2015-06/2020 | 433Mhz | V542 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Volvo | V90 | 01/2017-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC40 | 03/2018-06/2019 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Volvo | XC40 | 01/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 08/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 05/2008-12/2019 | 433MHz | Y413 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | XC70 | 07/2014-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | XC70 | 01/2010-06/2014 | 433MHz | Y381 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | XC70 | 01/2008-12/2009 | 433MHz | Y381 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Volvo | XC70 | 01/2003-12/2007 | 433MHz | Y381 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| Volvo | XC90 | 09/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC90 | 01/2015-12/2019 | 433MHz | V526 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Volvo | XC90 | 01/2002-06/2017 | 433MHz | Y289 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Volvo | XC90 (LCV) | 06/2015-06/2017 | 433MHz | V526 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Volvo | XC90 (LCV) | 06/2015-06/2017 | 433MHz | Y289 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| ZOTYE | Domy SR7 | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Orange | ● | ● |
| ZOTYE | Domy SR9 | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Orange | ● | ● |
| ZOTYE | Domy X5 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | ZOTYE | ● | ● |
| ZOTYE | Domy X7 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Zotye | ● | ● |
| ZOTYE | Meet5 | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | C | 433Mhz | TTE | ● | ● |
| ZOTYE | T300 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Orange | ● | ● |
| ZOTYE | T500 | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Zotye | ● | ● |
| ZOTYE | T600 | 01/2013-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |
| ZOTYE | T600 Coupe | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Orange | ● | ● |
| ZOTYE | T600 NEW | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Orange | ● | ● |
| ZOTYE | T700 | 01/2017-06/2019 | 433Mhz | | ● | ● | ○ | 0 | 433Mhz | DIAS | ● | ● |
| ZOTYE | T800 | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | DIAS | ● | ● |
| ZOTYE | Z360 | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Orange | ● | ● |
| ZOTYE | Z560 | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Orange | ● | ● |
| ZOTYE | Z700 | 01/2013-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433Mhz | Schrader | ● | ● |