



MX-Sensor_V6.00 Function List For KR Market (Note:For reference only)

NOTES:

- 1) ● This function is supported.
- 2) ○ This function is not supported.
- 3) Mark explaining:

Red: New.

Yellow: Modification like year range, feature, model code, OEM sensor information, relearn procedure and etc.

Special Declaration:

- 1) If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.
- 2) All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Abarth	500C	2010/01-2019/06	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Aston Martin	DB11	2016/01-2019/12	433Mhz	VH500	○	●	○	A	433Mhz	Schrader	●	●
Aston Martin	DBS	2007/09-2012/08	433Mhz	AM803	●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	DBS Superleggera	2018/01-2019/12	433Mhz	VH500	○	●	○	A	433Mhz	Schrader	●	●
Aston Martin	Rapide S	2010/01-2019/12	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Aston Martin	Vanquish	2010/01-2019/12	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A4	2008/08-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A5	2006/12-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A6	2018/01-2019/12		4G	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A6	2002/01-2017/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Audi	A7	2012/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A8	2017/01-2019/12			●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	A8	2010/11-2016/12			●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	Q5	2018/01-2019/12		8R	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	Q5	2008/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	Q7	2015/01-2019/12		4L/AU726	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Audi	Q7	2005/09-2014/12		4L/AU716	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Audi	R8	2015/04-2019/12			○	●	○	A	433Mhz	Huf/Beru	●	●
Audi	R8	2009/06-2015/03		AU714	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	RS5	2017/01-2019/12	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
Audi	RS5	2010/01-2016/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	S6	2018/01-2019/12			●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	S6	2002/01-2017/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Audi	S7	2012/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	S8	2017/11-2019/12			●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	S8	2009/11-2017/10		D4	●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	SQ5	2017/01-2019/12	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Audi	SQ5	2012/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	TTS	2017/01-2019/12	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
BMW	1 Series	2010/07-2019/12		F20/F21/F40	●	●	○	A	433Mhz	Continental	●	●
BMW	1 Series	2008/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	2 Series	2014/01-2019/12	433Mhz	F22/F23/F45/F46	●	●	○	A	433Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
BMW	3 Series	2005/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	3 Series Sedan	2014/03-2019/12	433MHz	F34	●	●	○	A	433Mhz	Continental	●	●
BMW	4 Series	2014/03-2019/12	F32/F33/F36 433MHz	F32/F33/F36	●	●	○	A	433Mhz	Continental	●	●
BMW	5 Series	2017/01-2019/12	433Mhz	G30/G31/G38	●	●	○	A	433Mhz	Schrader	●	●
BMW	5 Series	2014/03-2017/12		F10/F11	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	5 Series	2010/10-2014/02	433MHz	F10/F07	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	6 Series	2014/03-2018/12		F12/F13/F06	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	6 Series	2011/01-2014/12	433MHz	F06/F12/F13	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	7 Series	2015/06-2019/12	433Mhz	G11/G12	●	●	○	A	433Mhz	Schrader	●	●
BMW	7 Series	2010/10-2014/12	433MHz	F01/F02/F04	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	7 Series	2014/03-2015/05		F01/F02/F03 /F04	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	M2	2014/11-2019/12	433MHz	F87	●	●	○	A	433Mhz	Continental	●	●
BMW	M3	2014/01-2018/12	433Mhz	F80	●	●	○	A	433Mhz	Continental	●	●
BMW	M4	2015/01-2019/12	433Mhz	F82/F83	●	●	○	A	433Mhz	Continental	●	●
BMW	M5	2014/03-2017/12		F10	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	M6	2014/03-2018/12		F12	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	X1	2014/03-2015/07		E84	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	X1	2009/01-2013/12	Indirect	E84	○	○	○	A	N/A	N/A	Indirect	●
BMW	X1	2015/08-2019/12		F48	●	●	○	A	433Mhz	Continental	●	●
BMW	X3	2014/04-2017/12	433Mhz	F25	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	X3	2017/01-2019/12	G01/G08		●	●	○	A	433Mhz	Schrader	●	●
BMW	X4	2014/01-2019/12	433Mhz	F26	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	X4	2017/03-2019/12	433Mhz	G02	●	●	○	A	433Mhz	Schrader	●	●
BMW	X5	2013/05-2019/12	433Mhz	F15/F85	●	●	○	A	433Mhz	Continental	●	●
BMW	X6	2014/08-2019/12		F16/F86	●	●	○	A	433Mhz	Continental	●	●
BMW	Z4	2014/03-2018/12		E89	●	●	○	A	433Mhz	Huf/Beru	●	●
BMW	i3	2013/01-2019/12	433Mhz	I01/I12	●	●	○	A	433Mhz	Continental	●	●
Cadillac	ATS	2013/01-2013/12		A1SL/A1BL	●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	ATS	2014/01-2014/12		A1SL/A1BL	●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	ATS	2015/01-2015/12		A1SL/A1BL	●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	ATS	2016/01-2019/06		A1SL/A1BL	●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	ATS-V	2016/01-2016/12			○	●	○	S	433Mhz	Schrader	●	●
Cadillac	ATS-V	2015/01-2015/12			○	●	○	S	433Mhz	Schrader	●	●
Cadillac	ATS-V	2017/01-2019/12			○	●	○	S	433Mhz	Schrader	●	●
Cadillac	BLS	2006/01-2010/12			○	●	○	A	433Mhz	Schrader	●	●
Cadillac	CT6	2016/01-2018/12		01SL	●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	CTS	2013/06-2013/12		A1LL	○	●	○	C	433Mhz	Schrader	●	●
Cadillac	CTS	2016/01-2019/12			●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	CTS-V	2010/01-2015/12			●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	CTS-V	2016/01-2019/12			●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	Escalade	2007/01-2008/12		GMT926	●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	Escalade	2009/01-2011/12		GMT926	●	●	●	O/S	433Mhz	Schrader	●	●
Cadillac	Escalade	2012/01-2012/12		GMT900/ GMTK2XL	●	●	●	O/S	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Cadillac	Escalade	2013/01-2013/12		GMT900/GMTK2XL	●	●	●	0/S	433Mhz	Schrader	●	●
Cadillac	Escalade	2014/01-2014/12		GMT900/GMTK2XL/K2UL	●	●	●	0/S	433Mhz	Schrader	●	●
Cadillac	Escalade	2015/01-2019/12		GMT900/GMTK2XL/K2UL	●	●	●	0/S	433Mhz	Schrader	●	●
Cadillac	SRX	2013/01-2013/12		GMT166	●	●	●	0/S	433Mhz	Schrader	●	●
Cadillac	SRX	2010/01-2012/12	433MHz	GMT166	●	●	●	0/S	433Mhz	Schrader	●	●
Cadillac	SRX	2009/06-2009/12	433MHz	GMT166	●	●	●	0/S	433Mhz	Schrader	●	●
Cadillac	SRX	2016/01-2018/12	433MHz	C1UL	●	●	●	0/S	433Mhz	Schrader	●	●
Cadillac	SRX	2014/01-2018/12		GMT166	●	●	●	0/S	433Mhz	Schrader	●	●
Cadillac	XT5 Crossover	2016/01-2018/12			○	●	○	S	433Mhz	Schrader	●	●
Chevrolet	Alpheon	2011/01-2015/12	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Chevrolet	Aveo	2013/01-2018/12	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Bolt EV	2017/01-2019/06	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Camaro	2017/01-2019/06	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Camaro	2016/01-2016/12	Snap in 433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Captiva	2011/01-2018/12	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Colorado	2017/01-2018/12	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Cruze	2016/01-2019/12	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Cruze	2013/01-2015/12		D1SC/D1JC/D1WC/KL1J	●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Cruze	2012/01-2012/12		D1SC/D1JC/D1WC/KL1J	●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Equinox	2017/06-2019/06	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Impala	2016/01-2019/06	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Malibu	2011/01-2019/12	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Monte Carlo	2007/01-2007/12	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Orlando	2017/01-2018/12	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Spark	2013/01-2019/06	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Trax	2017/01-2019/06	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chevrolet	Volt	2016/01-2019/06	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Chrysler	200	2015/01-2016/12	433MHz		●	●	●	0/A	433Mhz	Continental	●	●
Chrysler	Grand Voyager	2011/01-2019/12	433MHz	RT	●	●	●	0/S	433Mhz	Schrader	●	●
Citroen	C4	2014/06-2019/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	DS3	2015/01-2019/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	DS4	2014/02-2019/12		B81	●	●	○	0/A	433Mhz	Schrader	●	●
Citroen	DS4	2010/12-2014/01		B75	●	●	○	0	433Mhz	Schrader	●	●
Citroen	DS5	2014/02-2019/12		X2/50	●	●	○	0	433Mhz	Schrader	●	●
Citroen	Space Tourer	2016/10-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Ferrari	458 Spider	2011/01-2015/12	433MHz	F142	●	●	○	0/A	433Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Ferrari	488 GTB	2015/01-2019/12	433Mhz	F142	○	●	○	A	433Mhz	Huf/Beru	●	●
Ferrari	488 Spider	2015/01-2019/06	433Mhz	F142	○	●	○	A	433Mhz	Huf/Beru	●	●
Ferrari	California	2008/10-2017/12		F149	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Ferrari	Enzo	2003/01-2006/12		F140	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Ferrari	F12 Berlinetta	2012/10-2017/12	433Mhz	F151/ F152	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Ferrari	F430	2007/07-2009/10		F131E	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Ferrari	FF	2011/01-2020/01		F151	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Ferrari	FXX	2005/01-2006/12		F140	○	●	○	A	433Mhz	Huf/Beru	●	●
Ferrari	GTC4 Lusso	2016/01-2018/12	433MHz		○	●	○	C	433Mhz	Huf/Beru	●	●
Ferrari	La Ferrari	2013/07-2019/06		F150	○	●	○	A	433Mhz	Huf/Beru	●	●
Ferrari	Portofino	2016/01-2019/12	433MHz		○	●	○	C	433Mhz	Huf/Beru	●	●
Fiat	500L	2012/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	500X	2014/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Ford	Escape	2015/01-2018/12		C520	●	●	●	0/S	433Mhz	Schrader	●	●
Ford	Escape	2012/05-2014/12		C520	●	●	●	S	433Mhz	Schrader	●	●
Ford	Explorer	2015/06-2019/12	433MHz		●	●	○	0/S	433Mhz	Schrader	●	●
Ford	Explorer	2011/01-2015/12		U502	●	●	●	S	433Mhz	Schrader	●	●
Ford	Kuga	2014/01-2019/12		C520	●	●	●	0/S/A	433Mhz	Schrader	●	●
Ford	Mondeo	2017/09-2019/12	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Ford	Mondeo	2015/01-2017/08	Snap in 433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Ford	Mustang	2015/01-2018/12	433MHz	S550	●	●	●	0/S	433Mhz	Schrader	●	●
Ford	Taurus	2016/01-2018/12	433MHz		●	●	●	0/S	433Mhz	Schrader	●	●
Honda	CR-V	2014/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Honda	Civic	2013/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Honda	HR-V	2014/09-2019/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Honda	Odyssey	2014/01-2017/12	315MHz		○	●	○	C	315Mhz	TRW	●	●
Honda	Odyssey	2017/01-2019/12	433MHz		●	●	○	0	433MHz	Continental	●	●
Hyundai	Accent	2015/01-2019/12	Hi-Line 433MHz	RB	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Accent	2017/01-2018/12	433MHz	YC	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Aslsan	2014/01-2018/12	433MHz		●	●	○	0	433Mhz	Continental	●	●
Hyundai	Avante	2012/01-2016/12	JK		●	●	○	0	433MHz	TRW	●	●
Hyundai	Avante	2016/01-2018/12	AD		●	●	○	0	433Mhz	Continental	●	●
Hyundai	Avante	2012/01-2016/12	MD		●	●	○	0	433MHz	TRW	●	●
Hyundai	Elantra	2014/08-2019/12	315MHz		●	●	○	0/A	315MHz	TRW	●	●
Hyundai	Elantra GT	2017/06-2019/12	PD 433MHz	PD	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Equus	2013/01-2016/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Hyundai	Equus	2014/01-2016/12	433MHz	HI	●	●	○	0/A	433MHz	Continental	●	●
Hyundai	Equus	2008/01-2013/12	433MHz		●	●	○	0	433MHz	TRW	●	●
Hyundai	Genesis	2014/01-2017/12	BH/DH 433Mhz	BH/DH	●	●	○	0/A	433Mhz	Continental	●	●
Hyundai	Genesis	2013/01-2016/12	Lo Line 315MHz		●	●	○	0	315Mhz	TRW	●	●
Hyundai	Genesis	2007/01-2013/12	433MHz	BH	●	●	○	0	433MHz	TRW	●	●
Hyundai	Genesis Coupe	2012/01-2019/06	433MHz		●	●	○	0	433Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Hyundai	Genesis G70	2017/10-2019/12	433Mhz	IK	●	●	○	0	433Mhz	Schrader	●	●
Hyundai	Genesis G80	2016/07-2019/12	433Mhz	DH	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Genesis G90	2016/07-2019/12	433MHz	HI	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Grand Starrex	2015/01-2018/12	433MHz		●	●	○	0	433MHz	Continental	●	●
Hyundai	Grandeur	2011/01-2017/12	HG	HG	●	●	○	0	433Mhz	TRW	●	●
Hyundai	Grandeur	2014/01-2017/12	Hybrid 433MHz		●	●	○	0	433MHz	TRW	●	●
Hyundai	Grandeur	2017/01-2018/12	433MHz	IG/IG HEV	●	●	○	0	433MHz	Continental	●	●
Hyundai	Ioniq	2016/01-2019/12	433MHz	AE	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Kona	2018/01-2019/12			●	●	○	0	433MHz	Continental	●	●
Hyundai	Maxcruz	2012/01-2018/12	433MHz		●	●	○	0	433Mhz	Continental	●	●
Hyundai	Santa Fe	2014/01-2018/12	433MHz	DM	●	●	○	0	433MHz	Continental	●	●
Hyundai	Santa Fe	2009/01-2012/05	CM 433Mhz	CM	●	●	○	0	433Mhz	Lear	●	●
Hyundai	Santa Fe	2013/01-2014/12	315MHz	NC	●	●	○	0	315Mhz	Continental	●	●
Hyundai	Santa Fe	2018/01-2018/12	433MHz	TM	●	●	○	0	433MHz	Schrader	●	●
Hyundai	Solati	2014/03-2019/06	433MHz		●	●	○	0	433MHz	Continental	●	●
Hyundai	Sonata	2014/01-2015/12	VDO_433MHz		●	●	○	0	433MHz	Continental	●	●
Hyundai	Sonata	2011/06-2013/12	433MHz	LF/LFA	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Sonata	2010/01-2013/12	433Mhz	YF	●	●	○	0	433Mhz	Continental	●	●
Hyundai	Sonata	2015/03-2019/12	SCH_433MHz	LF/LFA	●	●	○	0	433MHz	Schrader	●	●
Hyundai	Sonata Hybrid	2011/01-2014/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Hyundai	Sonata Hybrid	2016/01-2019/12	433MHz	YF/LF HEV	●	●	○	0	433MHz	Schrader	●	●
Hyundai	Sonata Hybrid	2015/01-2019/12	433MHz		●	●	○	0	433Mhz	Continental	●	●
Hyundai	Starex	2007/01-2015/12	433Mhz	A1	○	●	○	C	433MHz	Continental	●	●
Hyundai	Starex	2007/01-2007/12	315Mhz		○	●	○	C	315MHz	Continental	●	●
Hyundai	Tucson	2009/01-2013/12	433MHz	LM	●	●	○	0	433MHz	TRW	●	●
Hyundai	Tucson	2012/01-2015/12	Low line 433Mhz	EL	●	●	○	0	433MHz	TRW	●	●
Hyundai	Tucson	2013/11-2015/09	Hi line 433Mhz	EL	●	●	○	0	433MHz	TRW	●	●
Hyundai	Tucson	2015/01-2018/12	433Mhz		●	●	○	0	433Mhz	Schrader	●	●
Hyundai	Tucson	2016/01-2017/12	LM/TL 433Mhz	LM/TL	●	●	○	0	433Mhz	TRW	●	●
Hyundai	Tucson	2016/01-2019/12	433MHz	TL	●	●	○	0	433Mhz	Schrader	●	●
Hyundai	Veloster	2011/03-2018/12	FS 433Mhz	FS/JS	●	●	○	0	433Mhz	Schrader	●	●
Hyundai	Veracruz	2007/01-2012/12	CM 433Mhz	EN	●	●	○	0	433Mhz	Lear	●	●
Hyundai	Veracruz	2007/01-2013/12	433Mhz		●	●	○	0	433Mhz	Lear	●	●
Hyundai	i30	2016/08-2019/12	PD	PD	●	●	○	0	433MHz	Continental	●	●
Hyundai	i30	2013/01-2018/12	GD/SW/Turbo	GD/Gde/SW/Turbo	●	●	○	0/A	433Mhz	Continental	●	●
Hyundai	i40	2014/04-2019/12	VF	VF	●	●	○	0/A	433Mhz	TRW	●	●
Hyundai	i40	2011/01-2014/03	VF	VF	●	●	○	0	433Mhz	TRW	●	●
Infiniti	EX Series	2008/01-2014/03	433MHz	P53B/J50	●	●	○	0	433Mhz	Schrader	●	●
Infiniti	FX Series	2008/03-2014/12	433MHz	P53C/S51	●	●	○	0	433Mhz	Schrader	●	●
Infiniti	G Series	2008/06-2014/02	433MHz	CV36/G312/L53A	●	●	○	0	433Mhz	Schrader	●	●
Infiniti	M Series	2010/01-2013/12	Y51	M312/Y51	●	●	○	0	433Mhz	Pacific	●	●
Infiniti	Q30	2015/01-2019/12	433MHz	GD1A/H15	●	●	○	0/A	433Mhz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Infiniti	Q50	2015/01-2019/12	433MHZ	L53H/D53H/V37	●	●	○	0	433Mhz	Continental	●	●
Infiniti	Q60	2016/05-2019/12	433MHZ	CV37	●	●	○	0	433MHZ	Continental	●	●
Infiniti	Q70	2014/05-2018/09	433MHZ	L53E/Y51	●	●	○	0	433Mhz	Pacific	●	●
Infiniti	Q70	2018/10-2019/12	433MHZ		●	●	○	0	433Mhz	Continental	●	●
Infiniti	QX60	2014/01-2019/12	433MHZ	L50	●	●	○	0	433Mhz	Continental	●	●
Infiniti	QX70	2014/03-2019/12	433MHZ		●	●	○	0	433Mhz	Pacific	●	●
Infiniti	QX80	2014/01-2019/12	433MHZ	Z62	●	●	○	0	433Mhz	Pacific	●	●
Jaguar	E-Pace	2017/06-2019/12	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	F-Pace	2016/01-2019/12	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	F-Type	2017/01-2019/12	433MHZ		●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	I-Pace	2017/01-2019/12	433MHZ		○	●	○	A	433Mhz	Continental	●	●
Jaguar	XE	2015/12-2019/12		X760	●	●	○	0/A	433Mhz	Continental	●	●
Jaguar	XF	2015/06-2019/12		X260	●	●	○	0/A	433Mhz	Continental	●	●
Jeep	Commander	2006/01-2007/12	433MHZ	XK	●	●	●	0/A	433Mhz	Continental	●	●
Jeep	Commander	2008/01-2010/12		XK	●	●	●	0/A	433Mhz	Schrader	●	●
Jeep	Compass	2007/01-2007/12	315MHZ	MK49	●	●	●	0/A	315Mhz	Continental	●	●
Jeep	Compass	2008/01-2009/12	315MHZ	MK49	●	●	●	0/A	315Mhz	Continental	●	●
Jeep	Compass	2017/01-2018/12		551	○	●	○	A	433Mhz	Continental	●	●
Jeep	Grand Cherokee	2018/01-2019/12	433Mhz	WK	●	●	●	0/A	433Mhz	Continental	●	●
Jeep	Grand Cherokee	2012/01-2013/12		WK74	●	●	●	0	433Mhz	Schrader	●	●
Jeep	Grand Cherokee	2014/01-2019/12		WK74	●	●	●	0	433Mhz	Schrader	●	●
Jeep	Grand Cherokee	2016/01-2017/12	433Mhz	WK	●	●	●	0/A	433Mhz	Continental	●	●
Jeep	Grand Cherokee	2011/01-2011/12		WK74	●	●	●	0	433Mhz	Schrader	●	●
Jeep	Patriot	2009/01-2014/12	315MHZ	MK	●	●	●	0/A	315Mhz	Schrader	●	●
Jeep	Patriot	2007/01-2008/12	433Mhz	MK	●	●	●	0/A	433Mhz	Continental	●	●
Jeep	Renegade	2017/01-2018/12	433MHZ		●	●	○	0/A	433Mhz	Continental	●	●
Jeep	Renegade	2015/01-2016/12	433Mhz		●	●	●	0/A	433Mhz	Continental	●	●
Jeep	Wrangler	2010/09-2019/12	433MHZ	JK72	●	●	●	0/A	433Mhz	Schrader	●	●
Jeep	Wrangler	2014/01-2019/12		JL	●	●	●	0/A	433Mhz	Schrader	●	●
KIA	Bongo	2014/01-2018/12	433MHZ		●	●	○	0	433MHZ	Continental	●	●
KIA	Carens	2012/01-2019/12	RP	RP/UN	●	●	○	0/A	433Mhz	Continental	●	●
KIA	Carnival	2014/01-2018/12	Sedone	YP	●	●	○	C	433Mhz	Schrader	●	●
KIA	Carnival	2005/01-2013/12	315MHZ		●	●	○	0	315Mhz	Lear	●	●
KIA	Carnival	2019/01-2019/12		YP	●	●	○	C	433Mhz	Schrader	●	●
KIA	K3	2012/01-2018/12	433MHZ	YD	●	●	○	0	433MHZ	TRW	●	●
KIA	K3	2018/01-2019/12	433MHZ	BD	●	●	○	0	433MHZ	TRW	●	●
KIA	K5	2015/07-2019/12	JF 433Mhz	JF/JF HEV	●	●	○	0/A	433Mhz	Continental	●	●
KIA	K5	2013/01-2015/06	TF 433Mhz	TF/TF HEV	●	●	○	0	433Mhz	Continental	●	●
KIA	K5	2011/01-2012/12	TF 433Mhz	TF/TF HEV	●	●	○	0	433Mhz	Continental	●	●
KIA	K7	2016/01-2019/12	YG 433MHZ	YG	●	●	○	0	433MHZ	Continental	●	●
KIA	K7	2013/01-2016/12	VG 433MHZ	VG	●	●	○	0	433MHZ	Continental	●	●
KIA	K7	2008/01-2012/12	433MHZ	VG	●	●	○	0	433MHZ	Continental	●	●
KIA	K9	2011/01-2018/12	433MHZ	KH	●	●	○	0	433MHZ	Schrader	●	●
KIA	Mohave	2017/01-2018/12	433MHZ		●	●	○	0	433Mhz	Continental	●	●
KIA	Mohave	2009/01-2016/12	433MHZ		●	●	○	0	433Mhz	TRW	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
KIA	Mohave	2014/01-2016/12	HM 433MHZ	HM	●	●	○	0	433Mhz	TRW	●	●
KIA	Morning	2014/01-2019/06	433MHZ		●	●	○	0	433MHZ	Continental	●	●
KIA	Morning 3	2017/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
KIA	Niro	2016/01-2019/12	433MHZ	DE	●	●	○	0	433Mhz	Continental	●	●
KIA	Opirus	2006/01-2014/12	433MHZ		●	●	○	0	433Mhz	TRW	●	●
KIA	Pride	2012/01-2017/12	UB 433MHZ		●	●	○	0	433MHZ	TRW	●	●
KIA	Pride 3	2018/01-2018/12	YB 433MHZ		●	●	○	0	433MHZ	TRW	●	●
KIA	Pride 4	2017/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
KIA	Ray	2011/01-2018/12	433MHZ		●	●	○	0	433Mhz	Continental	●	●
KIA	Sorento	2018/01-2018/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
KIA	Sorento	2016/01-2017/12	433MHZ	UMA	●	●	○	0	433Mhz	Continental	●	●
KIA	Sorento	2011/01-2015/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
KIA	Sorento	2009/01-2010/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
KIA	Soul	2013/11-2016/12	433Mhz		●	●	○	0	433Mhz	Schrader	●	●
KIA	Soul	2008/06-2013/10	AM 433Mhz	AM	●	●	○	0	433Mhz	Continental	●	●
KIA	Sportage	2010/01-2013/12	Hi Line 433Mhz	SL	●	●	○	0	433Mhz	TRW	●	●
KIA	Sportage	2010/01-2013/12	Lo Line 433Mhz	SL	●	●	○	0	433Mhz	TRW	●	●
KIA	Sportage	2016/01-2019/12	QL/QLE 433Mhz	QL/QLE	●	●	○	0/A	433Mhz	Continental	●	●
KIA	Sportage	2014/01-2015/12	SL 433Mhz	SL	●	●	○	0/A	433Mhz	TRW	●	●
KIA	Sportage R	2014/01-2015/12	433Mhz		●	●	○	0	433MHZ	TRW	●	●
KIA	Stinger	2017/10-2019/12	433Mhz	CK	●	●	○	0	433Mhz	Schrader	●	●
KIA	Stinger	2017/01-2017/12	433Mhz		●	●	○	0	433Mhz	Schrader	●	●
KIA	Stonic	2017/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Lamborghini	Aventador	2012/01-2019/12	433Mhz	LB834	○	●	○	A	433Mhz	Huf/Beru	●	●
Lamborghini	Huracan	2014/01-2019/12	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
Lamborghini	One off	2017/01-2019/12	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
Lamborghini	Urus	2017/01-2019/12	433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
Land Rover	Discovery	2017/01-2019/12	433MHZ		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Discovery Sport	2015/09-2019/12	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	FreeLander	2005/01-2016/12	433Mhz	Fr132	●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover	2015/06-2019/12		D6, Ra5	●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover	2010/01-2012/12		L322	●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover Evoque	2015/10-2019/12			●	●	○	0/A	433Mhz	Continental	●	●
Land Rover	Range Rover Sport	2015/06-2019/12			●	●	○	0/A	433Mhz	Continental	●	●
Lexus	CT Series	2014/06-2019/12	433Mhz	080A	●	●	○	0	433Mhz	Pacific	●	●
Lexus	ES Series	2007/01-2012/05	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
Lexus	GS Series	2012/01-2019/12	433Mhz	920L	●	●	○	0	433Mhz	Pacific	●	●
Lexus	IS Series	2013/04-2019/12	433Mhz	030L/400A/720A/XE30	●	●	○	0	433Mhz	Pacific	●	●
Lexus	LC Series	2017/01-2019/12	433MHZ		●	●	○	0	433MHZ	Pacific	●	●
Lexus	LS Series	2017/10-2019/12	433Mhz		●	●	○	0	433Mhz	Pacific	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Lexus	LS Series	2012/10-2017/09	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
Lexus	NX Series	2014/03-2019/12	433Mhz	600A	●	●	○	0	433Mhz	Pacific	●	●
Lexus	RC Series	2014/01-2019/12	433Mhz	XC1/720A	●	●	○	0	433Mhz	Pacific	●	●
Lexus	RX Series	2015/11-2019/12	433Mhz	740A	●	●	○	0	433Mhz	Pacific	●	●
Lexus	RX Series	2014/06-2015/10	433Mhz	640L	●	●	○	0	433Mhz	Pacific	●	●
Lexus	RX Series	2015/12-2019/12	315MHZ		●	●	○	0	315MHZ	Pacific	●	●
Lincoln	Continental	2017/01-2019/12	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Lincoln	MKC	2015/06-2018/12	433MHz	2.0F SEL	●	●	●	O/S	433Mhz	Schrader	●	●
Lincoln	MKX	2015/01-2015/12	433MHz		●	●	●	S	433Mhz	Schrader	●	●
Lincoln	MKX	2016/01-2019/12	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Lincoln	MKZ	2015/09-2019/12	433MHz		○	●	○	S	433Mhz	Schrader	●	●
Lincoln	MKZ	2013/01-2016/12	433MHz		●	●	●	O/S	433Mhz	Schrader	●	●
Lotus	3 Eleven	2015/01-2017/05			○	●	○	A	433Mhz	Schrader	●	●
Lotus	Elise	2008/01-2018/12		Monza	○	●	○	A	433Mhz	Schrader	●	●
Lotus	Evora	2010/01-2018/12	433MHz		○	●	○	A	433Mhz	Schrader	●	●
Lotus	Exige	2008/01-2018/12		Monza	○	●	○	A	433Mhz	Schrader	●	●
Maserati	Ghibli	2013/01-2020/09		M156/M157	●	●	○	O/A	433Mhz	Schrader	●	●
Maserati	GrandCabrio	2017/01-2018/12	433MHz		○	●	○	C	433Mhz	Schrader	●	●
Maserati	Levante	2015/01-2018/12	433MHz		●	●	○	O/A	433Mhz	Schrader	●	●
Maserati	Quattroporte	2013/01-2018/12	433MHz		○	●	○	C	433Mhz	Schrader	●	●
Mercedes	A Class	2018/03-2019/12	433Mhz	W177	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Mercedes	A Class	2014/04-2018/02	433Mhz	W176	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	B Class	2011/11-2019/01	W246/W242	W246	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	C Class	2014/03-2019/07		W205	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	C Class	2007/04-2014/02		W204/W203	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	CLA Class	2012/12-2014/05		C117	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	CLA Class	2014/06-2019/04		C117	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	CLS Class	2018/01-2019/12	C257		●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	CLS Class	2012/01-2017/12	433MHz		●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	E Class	2009/07-2014/05		W212	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	E Class	2017/01-2019/12	W213/BR238 433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	G Class	2018/01-2019/12	433Mhz	G463/461	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	G Class	2007/04-2017/12		463	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	GLA Class	2018/01-2019/12	433MHz		●	●	○	0	433Mhz	Schrader	●	●
Mercedes	GLC Class	2015/01-2019/07		X253	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	GLK Class	2008/01-2015/09		X204	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	S Class	2013/07-2019/07		W222	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	S Class	2009/06-2013/06		W221	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	SL Class	2012/01-2019/12	433Mhz	W231	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	SLC Class	2016/01-2019/07	433MHz	R172	●	●	○	O/A	433Mhz	Schrader	●	●
Mercedes	SLK Class	2007/04-2019/05		R171, R172	●	●	○	O/A	433Mhz	Schrader	●	●
Mini	Clubman	2013/11-2019/12	433Mhz	F54	●	●	○	A	433Mhz	Continental	●	●
Mini	Clubman	2008/01-2013/12	Indirect	R55	○	○	○	A	N/A	N/A	Indirect	●
Mini	Convertible	2017/01-2019/12		R57	●	●	○	A	433Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Mini	Convertible	2014/01-2016/12		R57	●	●	○	A	433Mhz	Huf/Beru	●	●
Mini	Convertible	2010/01-2013/12	Indirect	R57	○	○	○	A	N/A	N/A	Indirect	●
Mini	Cooper	2014/03-2019/12	433MHz		●	●	○	A	433Mhz	Continental	●	●
Mini	Countryman	2014/07-2018/12	433Mhz	R60	●	●	○	A	433Mhz	Huf/Beru	●	●
Mini	Countryman	2010/01-2013/12	Indirect	R60	○	○	○	A	N/A	N/A	Indirect	●
Mini	Coupe	2014/01-2015/12		R58	●	●	○	A	433Mhz	Huf/Beru	●	●
Mini	Coupe	2012/01-2013/12	Indirect	R58	○	○	○	A	N/A	N/A	Indirect	●
Mini	Hatchback	2013/11-2018/12	433Mhz	F56	●	●	○	A	433Mhz	Continental	●	●
Mini	Paceman	2014/07-2018/06	433Mhz	R61	●	●	○	A	433Mhz	Huf/Beru	●	●
Mini	Paceman	2012/01-2013/12	Indirect	R61	○	○	○	A	N/A	N/A	Indirect	●
Mini	Roadster	2014/01-2015/12	433Mhz		●	●	○	A	433Mhz	Huf/Beru	●	●
Mini	Roadster	2012/01-2013/12	Indirect	R59	○	○	○	A	N/A	N/A	Indirect	●
Nissan	370Z	2014/07-2019/12	PAC_433MHz	RC53D(2)/Z34	●	●	○	O/A	433Mhz	Pacific	●	●
Nissan	Altima Sedan	2018/10-2019/12	433MHz	L33	●	●	○	0	433Mhz	Continental	●	●
Nissan	Altima Sedan	2012/07-2018/09	433MHz	L33	●	●	○	0	433Mhz	Continental	●	●
Nissan	Leaf Korea	2015/01-2019/12	433MHz		●	●	○	0	433Mhz	Continental	●	●
Nissan	Maxima	2016/01-2019/12	433MHz	A36	●	●	○	0	433Mhz	Continental	●	●
Nissan	Murano	2015/01-2019/12	433MHz	Z52	●	●	○	0	433Mhz	Continental	●	●
Peugeot	2008	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Peugeot	208	2012/05-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Peugeot	5008	2009/01-2013/09		T87	●	●	○	0	433Mhz	Schrader	●	●
Peugeot	508	2013/10-2019/12	433Mhz	W2	●	●	○	O/A	433Mhz	Schrader	●	●
Porsche	911	2015/01-2019/12			●	●	○	A	433Mhz	Huf/Beru	●	●
Porsche	911(991)	2011/12-2015/08		991	●	●	○	A	433Mhz	Huf/Beru	●	●
Porsche	918 Spyder	2013/01-2015/12	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Porsche	Boxster	2014/01-2016/02		981	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Porsche	Boxster	2009/01-2013/12		987	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Porsche	Cayenne S	2010/01-2014/05	433MHz	4. 8L	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Porsche	Macan	2014/01-2019/12	433MHz	PO416	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Porsche	Panamera	2013/07-2019/12	433MHz	970	●	●	○	O/A	433Mhz	Huf/Beru	●	●
Porsche	Panamera	2009/01-2014/02	433MHz		●	●	○	O/A	433Mhz	Huf/Beru	●	●
Renault Samsung	QM3	2016/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Renault Samsung	QM3	2013/01-2015/12	433Mhz		●	●	○	0	433Mhz	Schrader	●	●
Renault Samsung	QM5	2014/01-2016/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Renault Samsung	QM5	2007/01-2013/12	433MHz		●	●	○	0	433Mhz	Schrader	●	●
Renault Samsung	QM6	2017/01-2018/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Renault Samsung	SM3	2009/01-2018/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Renault Samsung	SM3 ZE	2015/01-2018/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Renault Samsung	SM5	2010/01-2018/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Renault Samsung	SM6	2015/01-2018/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Renault Samsung	SM7	2012/01-2018/12	433Mhz		●	●	○	0	433Mhz	Continental	●	●
Rolls Royce	Dawn	2016/01-2019/12	433Mhz	RR6	○	●	○	C	433Mhz	Huf/Beru	●	●
Rolls Royce	Phantom	2017/01-2019/12	PR11 433MHz		○	●	○	A	433Mhz	Schrader	●	●
Rolls Royce	Phantom	2012/01-2016/12		RR02	○	●	○	A	433Mhz	Huf/Beru	●	●
Rolls Royce	Wraith	2013/08-2019/12	433Mhz	RR04	○	●	○	C	433Mhz	Huf/Beru	●	●
Ssangyong	Actyon	2018/07-2019/12	Q200 433Mhz		○	●	○	A	433Mhz	Huf/Beru	●	●
Ssangyong	Actyon	2014/01-2019/12	QJ 433MHz		○	●	○	A	433Mhz	Schrader	●	●
Ssangyong	Chairman	2014/06-2019/12	433Mhz		●	●	○	A	433Mhz	Schrader	●	●
Ssangyong	Chairman	2008/01-2013/12	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Ssangyong	Korando	2013/08-2019/12	C200 433MHz		○	●	○	A	433Mhz	Schrader	●	●
Ssangyong	Korando	2008/01-2013/12	315MHz		○	●	○	A	315Mhz	Huf/Beru	●	●
Ssangyong	Kyron	2014/06-2016/09	433Mhz		○	●	○	A	433Mhz	Schrader	●	●
Ssangyong	Kyron	2008/01-2014/05	315MHz		○	●	○	A	315Mhz	Huf/Beru	●	●
Ssangyong	Musso	2017/01-2019/12	433Mhz		○	●	○	A	433Mhz	Schrader	●	●
Ssangyong	Rexton	2014/01-2017/12	Y300 433MHz		●	●	○	A	433Mhz	Schrader	●	●
Ssangyong	Rexton	2008/01-2013/12	315MHz		●	●	○	A	315Mhz	Huf/Beru	●	●
Ssangyong	Rodius	2008/01-2013/12	315MHz		○	●	○	A	315Mhz	Huf/Beru	●	●
Ssangyong	Rodius/Turismo	2014/01-2019/12	AJ 433MHz		○	●	○	A	433Mhz	Schrader	●	●
Ssangyong	Tivoli	2015/05-2019/12	X100 433MHz		○	●	○	A	433Mhz	Huf/Beru	●	●
Tesla	Model 3	2016/01-2019/12	433Mhz		○	●	○	A	433Mhz	Continental	●	●
Tesla	Model S	2014/10-2019/12			○	●	○	A	433Mhz	Continental	●	●
Tesla	Model X	2014/10-2019/12			○	●	○	A	433Mhz	Continental	●	●
Toyota	Avalon	2013/01-2018/12	433Mhz		●	●	○	0	433Mhz	Pacific	●	●
Toyota	Camry	2016/01-2019/12	433MHZ	045L	●	●	○	0/A	433MHZ	Pacific	●	●
Toyota	Camry	2014/01-2017/12	433MHZ	XV50	●	●	○	0	433MHZ	Pacific	●	●
Toyota	Camry Hybrid	2014/01-2017/12	433MHZ	XV50/XV70	●	●	○	0	433MHZ	Pacific	●	●
Toyota	FJ Cruiser	2014/06-2019/12	433MHZ	155L	●	●	○	0	433Mhz	Pacific	●	●
Toyota	GT86	2014/01-2019/12	433Mhz	E88	●	●	○	0	433Mhz	Pacific	●	●
Toyota	Land Cruiser Prado	2014/01-2017/09	433MHz	611L	●	●	○	0	433Mhz	Pacific	●	●
Toyota	Prius	2014/01-2019/12	433Mhz	590L/030A/XW30/XW50/690A/277N	●	●	○	0	433Mhz	Pacific	●	●
Toyota	RAV4	2013/01-2019/12	433Mhz	410A/XA40/120L	●	●	○	0	433Mhz	Pacific	●	●
Volkswagen	CC	2018/01-2019/12	MQB 433Mhz		●	●	○	0/A	433Mhz	Huf/Beru	●	●
Volkswagen	CC	2011/06-2017/12		VC17	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Volkswagen	Golf	2013/01-2019/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Volkswagen	Golf	2012/01-2012/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Volkswagen	Jetta	2010/01-2018/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	New Beetle	2012/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	New Beetle	2011/08-2019/12			●	●	○	A	433Mhz	Huf/Beru	●	●
Volkswagen	Polo	2009/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	Tiguan	2016/01-2019/12		VW376/5N2	●	●	○	0/A	433Mhz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Volkswagen	Tiguan	2011/05-2015/12		5N	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Volkswagen	Touareg	2014/08-2019/12	433Mhz	7P5/7P6108	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Volkswagen	Touareg	2010/01-2014/07		VW526	●	●	○	0/A	433Mhz	Huf/Beru	●	●
Volvo	C30	2011/01-2013/12	433Mhz	Y279	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	C30	2006/01-2010/12	433Mhz	Y279	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	C30 Electric	2011/01-2013/12			●	●	○	0/A	433Mhz	Continental	●	●
Volvo	C30 Electric	2010/01-2010/12			●	●	○	0/A	433Mhz	Continental	●	●
Volvo	C70	2011/01-2014/06	433Mhz	V70064	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	C70	2008/01-2010/12	433Mhz	V70064	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	C70	2006/01-2007/12	433Mhz	V70064	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	S40	2011/01-2014/06	433Mhz	V40044	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	S40	2004/01-2010/12	433Mhz	V40044	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	S60	2013/02-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	S60	2010/01-2013/01	315MHz		●	●	○	A	315Mhz	Schrader	●	●
Volvo	S60	2010/01-2013/01		Y283	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	S80	2013/03-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	S80	2006/01-2013/02	433MHz		●	●	○	0/A	433Mhz	Continental	●	●
Volvo	S80	2006/01-2013/02	315MHz		●	●	○	A	315Mhz	Schrader	●	●
Volvo	S90	2016/01-2019/12	433Mhz	V541	●	●	○	0/A	433Mhz	Schrader	●	●
Volvo	S90	2016/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V40	2012/01-2019/12	433Mhz	Y555, Y556	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	V60	2017/11-2019/12	433Mhz		●	●	○	0/A	433Mhz	Schrader	●	●
Volvo	V60	2014/07-2017/10	433Mhz		●	●	○	0/A	433Mhz	Continental	●	●
Volvo	V60	2010/09-2014/06		Y352	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	V70	2007/01-2016/12		Y285	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	V90	2015/01-2019/12	433Mhz	V542	●	●	○	0/A	433Mhz	Schrader	●	●
Volvo	XC60	2016/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	XC60	2008/05-2017/12		Y413	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	XC70	2014/07-2017/12			●	●	○	0/A	433Mhz	Continental	●	●
Volvo	XC70	2010/01-2014/06		Y381	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	XC70	2008/01-2009/12		Y381	●	●	○	0/A	433Mhz	Continental	●	●
Volvo	XC90	2016/09-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	XC90	2015/01-2019/12		V526	●	●	○	0/A	433Mhz	Schrader	●	●
Volvo	XC90	2005/01-2014/12		Y289	●	●	○	0/A	433Mhz	Schrader	●	●