



MX-Sensor_V6.53 Function List For AU Market (Note:For reference only)

NOTES:

● This function is supported. ○ This function is not supported. Mark explaining(Red:New, Yellow: Modify)

Special Declaration:

1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.

2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Abarth | 124 Spider | 2018/01-2022/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Abarth | 124 Spider | 2016/10-2017/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Abarth | 124 Spider | 2016/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 500 | 2008/01-2022/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Abarth | 500 | 2008/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 500C | 2010/01-2019/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 595 | 2014/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 595 C | 2015/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Abarth | 599 | 2014/03-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 695 Rivale | 2019/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Acura | NSX | 2016/06-2020/12 | 315MHz | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Alfa Romeo | 159 | 2005/07-2016/12 | 433MHz | 939 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Alfa Romeo | 4C | 2013/01-2021/12 | 433MHz | 960/961 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | 8C | 2007/01-2009/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alfa Romeo | Giulia | 2016/01-2017/12 | 433MHz 50547691 | 952 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulia | 2018/01-2021/12 | 433MHz 50547691 | 952 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulietta | 2010/01-2013/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | TRW | ● | ● |
| Alfa Romeo | Giulietta | 2010/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alfa Romeo | Giulietta | 2014/01-2017/12 | 433MHz | 940 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | Giulietta | 2018/01-2023/12 | 433MHz | 940 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | MiTo | 2008/01-2013/07 | 433MHz | 955 | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| Alfa Romeo | MiTo | 2013/08-2020/12 | 433MHz | 955 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | Quadrifoglio | 2018/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Quadrifoglio | 2016/01-2017/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Spider | 2006/06-2017/12 | 433MHz | 946 | ○ | ● | ○ | NA | 433MHz | TRW | ● | ● |
| Alfa Romeo | Stelvio | 2018/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Stelvio | 2019/01-2024/12 | 433MHz | 949 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Stelvio | 2017/01-2017/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Tonale | 2022/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | B3 | 2022/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Alpina | B3 | 2009/09-2014/03 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B3 | 1998/05-2006/01 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B3 | 2022/07-2024/06 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Alpina | B3 | 2022/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Alpina | B3 | 2022/07-2024/06 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | B3 | 2014/03-2019/06 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | B4 | 2014/03-2020/07 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | B5 | 2017/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | B7 | 2015/07-2022/07 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | B7 | 2015/07-2022/07 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Alpina | D3 | 2022/07-2024/06 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | D3 | 2009/09-2014/02 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D3 | 2022/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D3 | 2022/07-2024/06 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Alpina | D3 | 2022/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Alpina | D3 | 2014/01-2022/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | D4 | 2014/03-2020/07 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | D5 | 2017/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | XB7 | 2020/01-2022/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | XB7 | 2020/01-2022/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Alpina | XB7 | 2022/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Alpina | XB7 | 2022/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XD3 | 2017/08-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | XD3 | 2017/08-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Alpina | XD4 | 2018/01-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Aston Martin | Cygnets | 2011/01-2018/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| Aston Martin | DB11 | 2016/01-2023/12 | 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DB9 | 2009/01-2018/12 | 433MHz | AM803 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 2018/01-2023/12 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBS | 2007/01-2015/12 | 433MHz | V12 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS Superleggera | 2018/01-2022/12 | 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBX | 2020/04-2023/12 | 433MHz Huf | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Lagonda | 2015/01-2019/12 | 433MHz | COMET | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | One-77 | 2011/01-2012/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide | 2010/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide S | 2010/01-2019/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Valkyrie | 2018/01-2021/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vanquish | 2012/01-2020/12 | 433MHz | AM310 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vantage | 2005/07-2023/12 | 433MHz | AM305 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Virage | 2010/01-2020/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Zagato | 2011/01-2012/08 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A1 | 2010/06-2023/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | A3 | 2003/01-2012/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | A3 | 2012/06-2023/12 | 433MHz | 8L | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A3 | 2010/01-2022/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A4 | 2007/01-2015/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Audi | A4 | 2007/01-2012/12 | 315MHz Continental | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | A4 | 2001/01-2011/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 | 2012/01-2023/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 Allroad | 2015/01-2023/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 Allroad | 2008/01-2012/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | A5 | 2007/01-2012/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | A5 | 2006/09-2023/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A5 | 2006/12-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 | 2018/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 | 2014/03-2019/12 | 433MHz 7PP907275F | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 2011/01-2023/12 | 433MHz | 4G | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 2010/01-2017/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | A6 | 2000/01-2005/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 2009/11-2019/12 | 433MHz | 4G | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A7 | 2010/09-2023/12 | 433MHz 5Q0907275 | 4G | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A7 | 2012/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A8 | 2009/11-2017/10 | 433MHz | 4H/4L | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 2009/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A8 | 2002/10-2012/12 | 433MHz | 4E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 2010/01-2023/12 | 433MHz 5Q0907275 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A9 | 2019/01-2019/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q2 | 2015/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q2 | 2016/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q3 | 2011/06-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q3 | 2011/07-2023/12 | 433MHz | 8U | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q4 | 2019/09-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q5 | 2008/09-2023/12 | 433MHz | 8R | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q5 | 2008/01-2015/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | Q5 | 2008/01-2017/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q6 | 2018/01-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 2013/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q7 | 2005/09-2015/12 | 433MHz | 4L/AU716 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 2015/01-2023/12 | 433MHz MLB | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q8 | 2018/01-2023/12 | 433MHz | 4M | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q8 | 2018/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | R8 | 2009/06-2023/12 | 433MHz 7PP907275F | AU714 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 2015/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS Q3 | 2018/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS Q8 | 2019/12-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS3 | 2016/07-2023/12 | 433MHz | 8V | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS3 | 2013/01-2017/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS4 | 2006/04-2018/12 | 433MHz | 8E/B7 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 2006/04-2021/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Audi | RS4 | 2008/01-2015/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS5 | 2012/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 2007/01-2012/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | RS5 | 2010/01-2016/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS6 | 2013/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS6 | 2019/01-2023/12 | 433MHz 5Q0907275 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 2000/01-2007/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 2008/01-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6/RS6 Plus | 2013/01-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 2010/01-2021/06 | 433MHz 7PP907275F | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 2013/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS7 | 2018/03-2023/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S3 | 2003/01-2012/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | S4 | 2007/01-2015/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S4 | 2009/01-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S5 | 2007/01-2016/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S5 | 2012/01-2019/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 2000/01-2005/12 | 433MHz 4D0907275 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 2004/01-2009/12 | 433MHz 7PP907275F | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S7 | 2012/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S8 | 2009/11-2017/10 | 433MHz | D4 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ5 | 2012/01-2017/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ5 | 2014/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ7 | 2016/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ7 | 2016/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ8 | 2020/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | TT | 2014/03-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TT | 2014/02-2023/12 | 433MHz | AU334 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | TT | 2007/01-2014/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | TT | 2006/04-2014/02 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TT RS | 2016/11-2023/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | TTS | 2012/01-2022/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TTS | 2016/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | e-tron | 2018/01-2023/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 2008/01-2013/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 1 Series | 2010/09-2013/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 2014/01-2024/06 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 1 Series | 2019/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 2019/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 2019/11-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 2019/11-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 2014/03-2024/06 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------|-----------------|--------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | 2 Series | 2012/11-2014/02 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2010/10-2014/03 | 433MHz | F30/F31/F34 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2009/09-2013/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2014/03-2022/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series | 2019/03-2024/06 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 3 Series | 2019/03-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2019/03-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2019/03-2024/06 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 3 Series | 1998/01-2003/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 1999/01-2002/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 1999/03-2013/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 3 Series | 2005/01-2009/08 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 4 Series | 2013/07-2021/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 4 Series | 2020/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 4 Series | 2020/07-2024/06 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 4 Series | 2020/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 4 Series | 2020/07-2024/06 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 5 Series | 2003/05-2013/12 | 433MHz 36236798726 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2007/01-2013/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 5 Series | 2023/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2023/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2016/11-2024/06 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 5 Series | 2016/11-2024/06 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 5 Series | 2010/09-2014/02 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2014/03-2017/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 1999/01-2004/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 5 Series | 1998/08-2004/05 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 2003/01-2007/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 6 Series | 2014/04-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 2011/01-2014/03 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 2003/01-2012/12 | 433MHz | E63/E64 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series GT | 2017/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 6 Series GT | 2017/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 7 Series | 2022/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2022/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 1999/01-2001/12 | Indirect | E38 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 7 Series | 2015/06-2022/12 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 7 Series | 2015/06-2022/12 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 7 Series | 2014/03-2015/05 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | 7 Series | 2010/09-2014/02 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2006/01-2010/08 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2002/01-2005/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 8 Series | 2018/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 8 Series | 2018/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M2 | 2022/12-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M2 | 2022/12-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M2 | 2014/11-2021/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M3 | 2020/11-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M3 | 2008/01-2013/12 | 433MHz 36106856227 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M3 | 2007/01-2013/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M3 | 2014/01-2019/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M3 | 2020/11-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M3 | 1999/01-2006/12 | 433MHz 36112360420 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M3 | 2006/01-2007/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M4 | 2014/03-2021/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M4 | 2021/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M4 | 2021/07-2024/06 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M4 | 2020/01-2022/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 2014/04-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 2016/01-2022/12 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M5 | 2010/09-2014/03 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 2005/01-2010/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M5 | 1999/01-2003/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M6 | 2005/01-2011/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M6 | 2014/03-2018/12 | 433MHz | F12 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 2014/01-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 2011/06-2015/12 | 433MHz 36106856227 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M8 | 2019/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | Motorcycle | 2010/01-2019/12 | 433MHz | | ○ | ○ | ○ | | 433MHz | Schrader | Activate Only | ● |
| BMW | X1 | 2015/08-2023/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X1 | 2022/11-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X1 | 2022/11-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 2008/09-2014/02 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 2014/03-2016/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X2 | 2016/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X3 | 2017/01-2024/06 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X3 | 2017/01-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X3 | 2014/04-2017/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | X3 | 2003/01-2010/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X3 | 2003/03-2011/07 | 433MHz | E83 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 2010/11-2014/03 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X4 | 2018/04-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X4 | 2018/04-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X4 | 2014/01-2018/12 | 433MHz 36106790054 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X4 | 2013/05-2018/03 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 2023/04-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X5 | 2023/04-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 1999/10-2007/09 | 433MHz | E53 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 2004/01-2010/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X5 | 2010/10-2013/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 2018/08-2023/03 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X5 | 2018/08-2023/03 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X5 | 2015/01-2018/07 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X6 | 2019/08-2023/12 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X6 | 2023/01-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X6 | 2023/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 2007/12-2010/09 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 2008/01-2014/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X6 | 2010/10-2014/07 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 2014/08-2019/07 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X6 | 2019/08-2023/12 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X7 | 2018/12-2022/07 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X7 | 2018/12-2022/07 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X7 | 2022/08-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X7 | 2022/08-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | XM | 2022/12-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | XM | 2022/12-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 2009/01-2013/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | Z4 | 2006/01-2014/02 | 433MHz 36106790054 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 2003/01-2008/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | Z4 | 2014/03-2016/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 2018/11-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 2018/11-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i3 | 2013/01-2022/06 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | i3 | 2022/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i4 | 2021/01-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | i4 | 2021/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i5 | 2023/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | i5 | 2023/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i7 | 2022/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | i7 | 2022/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | i8 | 2013/01-2022/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | iX | 2021/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | iX | 2021/01-2023/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | iX1 | 2022/11-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | iX1 | 2022/11-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | iX3 | 2017/08-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | iX3 | 2017/08-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BYD | ATTO 3 | 2021/12-2024/06 | 433MHz SC3609200 | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| BYD | ATTO 3 | 2022/02-2024/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |
| BYD | Dolphin | 2022/12-2024/06 | 433MHz SC3609200B | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| BYD | Dolphin | 2021/08-2024/06 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| BYD | Han EV | 2020/01-2024/06 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| BYD | Han EV | 2022/04-2024/06 | 433MHz SC3609200B | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| BYD | Seal | 2022/07-2024/06 | 433MHz SA3HE3609200 B | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |
| BYD | Seal | 2022/07-2024/06 | 433MHz SC3609200 | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Bentley | Arnage | 2008/01-2011/09 | 433MHz 7PP907275F | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Bentayga | 2016/01-2023/12 | 433MHz 5Q0907275 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Bentayga | 2016/01-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Brooklands | 2008/01-2011/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental Flying Spur | 2005/03-2020/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 2018/04-2024/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 2005/06-2023/12 | 433MHz BY634 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 2003/09-2005/05 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GTC | 2018/01-2023/12 | 433MHz 5Q0907275 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 2011/01-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 2019/01-2024/06 | 433MHz 5Q0907275 | | ● | ● | ○ | O | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulliner | 2021/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 2001/01-2020/12 | 433MHz 7PP907275F | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 2017/01-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Cadillac | CT6 | 2019/01-2022/12 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 2009/01-2009/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2007/10-2008/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2007/01-2007/09 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2016/01-2021/12 | 315MHz 13598772 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2016/01-2019/12 | 433MHz 13598787 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Cadillac | CTS | 2014/01-2015/12 | 315MHz 13581558 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2014/01-2015/12 | 315MHz 20964159 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2014/01-2014/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2016/01-2019/12 | 315MHz 13598786 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2013/01-2013/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2012/01-2012/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2010/01-2011/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 2005/01-2006/12 | 315MHz 15268606 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 2006/01-2006/12 | 315MHz 25920615 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 2007/01-2007/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 2008/01-2008/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 2009/01-2013/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Deville | 2004/01-2004/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Deville | 2000/01-2003/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Deville | 2005/01-2007/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2012/01-2012/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2017/01-2020/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2009/01-2011/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2013/01-2013/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2014/01-2014/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2018/01-2019/12 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2015/01-2016/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2008/01-2008/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2007/01-2007/12 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | TRW | ● | ● |
| Cadillac | Escalade | 2007/01-2007/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 2007/01-2008/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 2004/01-2006/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 2014/01-2016/12 | 433MHz | GMT166 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 2013/01-2013/12 | 433MHz | GMT166 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 2010/01-2012/12 | 433MHz | GMT166 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 2009/01-2009/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 2015/01-2016/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 2004/01-2007/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 2009/01-2011/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 2008/01-2008/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 2009/01-2011/12 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------|-----------------|-----------------------------|-------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Cadillac | Seville | 2004/01-2006/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Seville | 2001/01-2003/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | XLR | 2004/01-2005/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | XLR | 2006/01-2009/12 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XLR-V | 2016/01-2019/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT3 | 2018/01-2019/12 | 315MHz | D2UL | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | XT4 | 2018/11-2022/12 | 433MHz | E2UL | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT4 | 2018/01-2019/12 | 315MHz | E2UL | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT6 | 2019/01-2022/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chery | OMODA 5 | 2022/07-2023/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 3 | 2021/01-2023/12 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 3 | 2016/05-2023/12 | 433MHz T113114011 | | ● | ● | ○ | 0 | 433MHz | Chery | ● | ● |
| Chery | Tiggo 7 | 2021/12-2024/06 | 433MHz 802000247AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 7 | 2019/06-2024/06 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chevrolet | Aveo | 2015/01-2020/06 | 433MHz | G1SC/G1JC/T 250/T300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2016/01-2016/12 | 433MHz Snap in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2017/01-2020/12 | 433MHz Snap in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2016/01-2019/12 | 433MHz 13598787 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2016/01-2016/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2016/01-2016/12 | 433MHz Clamp in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2021/01-2023/12 | 433MHz Clamp in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2020/01-2023/12 | 315MHz | | ● | ● | ● | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2017/01-2022/12 | 433MHz Clamp in 13598787 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2014/01-2015/12 | 315MHz 22854866 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2013/01-2013/12 | 315MHz 12768826 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2012/01-2012/12 | 315MHz 12768826 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2018/01-2019/12 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2020/01-2023/12 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 2011/01-2013/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 2022/01-2023/12 | 433MHz 23576928 | | ● | ● | ● | 0 | 433MHz | Baolong | ● | ● |
| Chevrolet | Captiva | 2020/01-2023/12 | 433MHz | | ● | ● | ● | 0 | 433MHz | Baolong | ● | ● |
| Chevrolet | Colorado | 2017/01-2019/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2013/01-2013/12 | 315MHz | C6 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2014/01-2019/12 | 433MHz | Y1BC | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-----------|-----------------|--------------------|---------------------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Corvette | 2020/01-2023/12 | 433MHz 13529771 | | ● | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2021/01-2023/12 | 315MHz 13538759 | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2022/01-2023/12 | 433MHz 13554170 | | ● | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2012/01-2012/12 | 315MHz | C6 | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 1997/01-2000/12 | 315MHz | C5 | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2001/01-2002/12 | 315MHz | C5 | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2003/01-2004/12 | 315MHz | C5 | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2005/01-2009/12 | 315MHz 25758220 | C6 | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2009/01-2009/12 | 315MHz 13598771 | C6 | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2010/01-2011/12 | 315MHz | C6 | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2010/01-2014/12 | 433MHz | C6 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 2013/01-2015/12 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 2008/10-2010/12 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 2011/01-2011/12 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 2012/01-2012/12 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 2016/01-2016/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 2017/01-2018/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 2015/01-2016/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 2013/01-2015/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 2015/01-2016/10 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 2013/10-2014/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 2010/07-2014/12 | 433MHz | K2XC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 2009/01-2013/09 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 2009/01-2011/12 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 2021/01-2023/12 | 433MHz 13530661 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 2017/01-2023/12 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 2021/01-2022/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 2016/11-2019/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 2015/01-2020/12 | 433MHz | K2XC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 2021/01-2023/12 | 315MHz 13538759 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|---------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Silverado | 2015/01-2016/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 2015/01-2015/12 | 433MHz | M1JC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 2013/01-2014/12 | 433MHz | M1JC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Uplander | 2004/01-2010/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chrysler | 200 | 2018/01-2020/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chrysler | 200 | 2014/01-2016/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 200 | 2017/01-2017/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 300 | 2018/01-2021/12 | 433MHz | LE48 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 2011/01-2013/12 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 2014/01-2017/12 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 SRT | 2010/01-2012/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 SRT | 2013/01-2017/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 SRT | 2018/01-2021/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 2005/06-2009/05 | 433MHz | LE48 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 300C | 2014/01-2015/12 | 433MHz 56029400AE | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 2014/01-2017/12 | 433MHz 56029400AD | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 2018/01-2019/12 | 433MHz 56029400AD | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 2018/01-2021/06 | 433MHz 18 inch | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 2009/06-2017/12 | 433MHz 18 inch | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Crossfire | 2003/10-2009/01 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | Grand Voyager | 2011/01-2017/12 | 433MHz | RT | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chrysler | Grand Voyager | 2016/01-2017/12 | 433MHz | RU | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Grand Voyager | 2018/01-2019/12 | 433MHz | RU | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chrysler | Grand Voyager | 2018/01-2020/03 | 433MHz | RT | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Grand Voyager | 2007/01-2010/12 | 433MHz | RT | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Chrysler | PT Cruiser | 2008/01-2008/12 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Sebring | 2006/01-2010/12 | 433MHz | JS | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Voyager | 2018/01-2019/12 | 433MHz | RT | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | Voyager | 2011/01-2017/12 | 433MHz | RT | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Chrysler | Voyager | 2002/01-2003/12 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Ypsilon | 2018/01-2019/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Chrysler | Ypsilon | 2011/01-2017/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Berlingo | 2008/01-2013/09 | 433MHz | B9 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Citroen | Berlingo | 2013/10-2018/06 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Citroen | Berlingo | 2018/07-2023/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | C3 | 2009/09-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C4 | 2014/10-2018/10 | 433MHz | B58 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | C4 | 2010/08-2024/06 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | C4 | 2008/08-2010/07 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Citroen | C4 | 2004/09-2008/07 | 433MHz | B5 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Citroen | C4 Aircross | 2012/04-2018/06 | 433MHz | | ● | ● | ○ | S | 433MHz | Continental | ● | ● |
| Citroen | C4 Cactus | 2014/05-2021/04 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | C4 Picasso | 2006/05-2013/02 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Citroen | C5 | 2000/12-2004/07 | 433MHz | X40 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C5 | 2004/08-2013/08 | 433MHz | X3/X40 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C5 | 2013/09-2020/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Citroen | C5 Aircross | 2017/09-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C6 | 2005/01-2013/12 | 433MHz | X6 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C8 | 2005/10-2015/12 | 433MHz | V3 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C8 | 2002/01-2005/09 | 433MHz | V3 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS3 | 2015/01-2022/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | DS3 | 2009/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS4 | 2010/12-2014/01 | 433MHz | B75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS4 | 2014/02-2020/07 | 433MHz | B81 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Citroen | DS5 | 2011/06-2014/01 | 433MHz | B81 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS5 | 2014/02-2018/11 | 433MHz | X2/50 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS7 | 2018/01-2024/06 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | Dispatch | 2006/10-2014/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Avenger | 2007/01-2014/12 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Avenger | 2006/01-2013/12 | 433MHz | JS41D | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Caliber | 2007/01-2007/12 | 315MHz | PM | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Caliber | 2008/01-2009/12 | 315MHz | PM | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Challenger | 2019/01-2022/12 | 433MHz | LC22 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 2018/01-2018/12 | 433MHz | LC22 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 2014/01-2017/12 | 433MHz | LC22 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 2011/01-2013/12 | 433MHz | LX48D/LD | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 2015/01-2015/12 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Dakota | 2007/01-2007/12 | 315MHz | ND | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Dodge | Dakota | 2008/01-2010/12 | 315MHz Snap in | ND | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Dodge | Dakota | 2008/01-2010/12 | 315MHz Clamp in | ND | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Dodge | Dart | 2012/10-2019/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Durango | 2011/01-2013/12 | 433MHz | WD | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 2011/01-2013/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 2008/01-2010/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Grand Caravan | 2014/01-2015/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 2017/11-2017/12 | 433MHz | JC49 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 2008/01-2011/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Journey | 2011/01-2013/12 | 433MHz | JC | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 2014/01-2017/10 | 433MHz | JC49 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 2018/01-2019/12 | 433MHz | JC49 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Dodge | Magnum | 2005/01-2008/12 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Nitro | 2009/01-2012/12 | 315MHz | KA | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Dodge | Nitro | 2007/06-2011/12 | 433MHz | KA | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 1500 | 2019/01-2024/12 | 433MHz DT | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 1500 | 2018/01-2023/12 | 433MHz | DS | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Dodge | Ram 1500 | 2010/01-2013/12 | 433MHz | D2 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 2500 | 2016/01-2017/12 | 433MHz | | ● | ● | ● | 0 | 433MHz | TRW | ● | ● |
| Dodge | Ram 2500 | 2019/01-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|----------|-----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Dodge | Ram 2500 | 2018/01-2018/12 | 433MHz | | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 | 2010/01-2013/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 3500 | 2014/01-2017/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 | 2019/01-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 DRW | 2019/01-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Dodge | Ram Series | 2018/01-2021/12 | 433MHz | DS/DJ | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Dodge | Ram Series | 2014/01-2017/12 | 433MHz | DS/DJ | ● | ● | ● | O | 433MHz | TRW | ● | ● |
| Dodge | SRT Viper | 2010/01-2017/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Viper | 2003/01-2011/12 | 433MHz | ZB | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Ferrari | 458 Spider | 2009/01-2020/12 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 488 | 2015/01-2021/12 | 433MHz | F142 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 575M Maranello | 2002/01-2006/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 599 GTB | 2004/01-2014/12 | 433MHz | F141 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 599 GTO | 2004/01-2012/12 | 433MHz | F141 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 612 Scaglietti | 2004/01-2012/12 | 433MHz | F137 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 812 Superfast | 2016/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | CTC4 Lusso T | 2017/01-2019/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Ferrari | California | 2008/10-2017/12 | 433MHz | F149 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Daytona SP3 | 2022/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Enzo | 2002/01-2006/12 | 433MHz | F140 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 2012/01-2022/12 | 433MHz | F151/ F152 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F12 tdf | 2015/01-2021/12 | 433MHz | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 2007/07-2009/10 | 433MHz | F131E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 2005/01-2007/06 | 433MHz | F131E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F8 Tributo | 2019/01-2023/12 | 433MHz | F151/ 282189 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | FF | 2011/01-2020/01 | 433MHz | F151 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | FXX | 2005/01-2006/12 | 433MHz | F140 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | GTC4 Lusso | 2016/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | La Ferrari | 2013/01-2020/12 | 433MHz | F150 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Monza SP1/SP2 | 2019/01-2021/12 | 433MHz | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Portofino | 2017/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Roma | 2020/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | SF90 | 2020/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Fiat | 124 Spider | 2015/08-2016/12 | 433MHz | NF/J12F | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Fiat | 124 Spider | 2017/01-2021/12 | 433MHz | NF/J12F | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Fiat | 500 | 2014/01-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500 | 2014/01-2022/12 | 433MHz | 312 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500C | 2014/01-2019/06 | 433MHz | 312 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500C | 2013/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500L | 2013/03-2016/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500L | 2012/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500X | 2014/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | Doblo | 2009/01-2021/12 | 433MHz | 223/263 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------------|-----------------|-----------------------|-----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Fiat | Ducato | 2014/06-2024/06 | 433MHz | X2/50 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Freemont | 2014/07-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Freemont | 2011/01-2014/06 | 433MHz | JF | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Panda | 2012/01-2023/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Punto | 2005/09-2018/12 | 433MHz | 199 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Fiat | Scudo | 2016/01-2023/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Scudo | 2006/01-2013/10 | 433MHz | G9 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Scudo | 2013/01-2019/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Fiat | Talento | 2016/01-2022/12 | 433MHz | FJL/X82 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ford | E-Series SD | 2022/01-2023/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | E-Series SD DRW | 2022/01-2023/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Ecosport | 2013/01-2019/06 | 433MHz EV6T1A180CB | CBW | ● | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Ecosport | 2013/06-2014/09 | 433MHz | B515 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Ecosport | 2017/11-2023/12 | 433MHz | CR6 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Edge | 2015/01-2015/12 | 433MHz | CD389/ CD539 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Edge | 2020/01-2023/12 | 433MHz | CD389/ CD539 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Edge | 2016/01-2019/12 | 433MHz | CD389/ CD539 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Endura | 2018/01-2020/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Endura | 2018/01-2018/12 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 2018/01-2019/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 2020/01-2023/12 | 315MHz | | ● | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Ford | Escape | 2013/01-2013/09 | 315MHz | C520 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 2013/10-2014/12 | 315MHz | C520 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 2012/01-2012/12 | 315MHz | U377 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 2020/01-2023/12 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 2015/01-2015/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 2016/01-2017/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Everest | 2018/01-2018/12 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Everest | 2016/06-2017/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Everest | 2015/06-2017/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Everest | 2009/06-2015/05 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Everest | 2006/01-2009/05 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Everest | 2018/01-2018/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Everest | 2019/01-2019/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Everest | 2020/01-2020/12 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Everest | 2019/01-2019/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Everest | 2021/01-2024/06 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 2018/01-2018/12 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 2013/01-2015/05 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 2011/01-2012/12 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 2011/01-2015/12 | 315MHz | U502 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 2014/03-2019/12 | 433MHz | P552 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 2021/01-2024/06 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | F-Series | 2021/01-2021/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series | 2015/01-2020/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series | 2015/01-2021/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Fiesta | 2014/05-2019/06 | 433MHz | CCN | ● | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Fiesta | 2017/01-2023/06 | 433MHz | CE1 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Fiesta | 2014/01-2019/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Focus | 2020/01-2024/06 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus | 2018/05-2019/12 | 433MHz | CGE | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Focus | 2011/01-2019/06 | 433MHz EV6T1A180DB | CEW/CB8 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Kuga | 2014/01-2019/12 | 433MHz | C520 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mondeo | 2019/06-2022/12 | 433MHz F2GZ1A189B | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Mondeo | 2017/09-2019/05 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Mondeo | 2014/10-2017/12 | 433MHz Snap in | CD391 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Mondeo | 2013/01-2015/06 | 433MHz Clamp in | CD345 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Ford | Mondeo | 2007/01-2012/12 | 433MHz Clamp in | CD345 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Ford | Mustang | 2020/01-2023/12 | 433MHz | S550 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 2015/08-2015/12 | 433MHz | S550 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 2015/01-2015/07 | 433MHz | S550 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 2016/01-2019/12 | 433MHz | S550 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang Mach-E | 2020/01-2024/06 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Mustang Mach-E | 2021/01-2024/06 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | PUMA | 2019/11-2024/06 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 2015/01-2015/12 | 433MHz Lo Line | P375 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 2015/01-2023/12 | 433MHz Hi Line | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 2016/01-2023/12 | 433MHz Lo Line | P375 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 2014/05-2014/12 | 433MHz | P375 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Territory | 2007/01-2010/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Territory | 2011/01-2015/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Territory | 2016/01-2016/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Territory | 2004/01-2006/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Tourneo Custom | 2013/09-2019/05 | 433MHz | V362 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Tourneo Custom | 2019/06-2023/12 | 433MHz | TTF | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 2010/01-2014/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 2017/01-2019/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 2016/01-2016/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 2015/01-2015/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 2013/06-2014/12 | 433MHz | V363 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 2023/01-2024/06 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 2020/01-2020/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 2023/01-2024/06 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 2019/01-2019/12 | 433MHz | V363 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Ford | Transit Custom | 2013/01-2019/12 | 315MHz | V363 | ○ | ● | ○ | S/A | 315MHz | Schrader | ● | ● |
| Ford | Transit Custom | 2022/01-2023/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit Custom | 2019/01-2021/12 | 433MHz Trailer | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Transit Custom | 2013/09-2019/05 | 433MHz | V363 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Van | 2023/01-2023/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit Van | 2013/01-2019/12 | 315MHz | V363 | ○ | ● | ○ | S/A | 315MHz | Schrader | ● | ● |
| Ford | Transit Van | 2019/01-2022/12 | 433MHz Trailer | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Foton | Cargo Van | 2018/01-2019/12 | 433MHz | | ● | ● | ○ | S | 433MHz | TTE | ● | ● |
| Foton | Sauvana | 2015/01-2022/12 | 433MHz | | ● | ● | ○ | S | 433MHz | TTE | ● | ● |
| Foton | Tunland | 2011/01-2022/12 | 433MHz | | ● | ● | ○ | S | 433MHz | TTE | ● | ● |
| Foton | View CS2 | 2014/01-2018/12 | 433MHz | | ● | ● | ○ | S | 433MHz | TTE | ● | ● |
| GMC | Acadia | 2018/09-2023/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 2016/11-2018/08 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Denali | 2018/01-2020/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Denali | 2017/01-2017/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Denali | 2014/01-2016/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Denali | 2020/01-2021/12 | 315MHz 13512346 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 2018/01-2023/12 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 2007/01-2007/12 | 315MHz Clamp in SCH | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 2007/01-2007/12 | 315MHz Clamp in TRW | | ● | ● | ● | O/S | 315MHz | TRW | ● | ● |
| GMC | Sierra | 2007/01-2008/12 | 315MHz Snap in SCH | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 2010/01-2011/12 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 2014/01-2014/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 2015/01-2016/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 2009/01-2013/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 2017/01-2021/12 | 315MHz | XL7 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Geely | Coolray | 2018/09-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | EMGRAND | 2016/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | GC 6 | 2015/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | X7 | 2017/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| GreatWall | CANNON | 2019/09-2024/06 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | CANNON | 2021/06-2024/06 | 433MHz Clamp in | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| GreatWall | CANNON | 2019/09-2022/12 | 433MHz Snap in | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | ORA Flash Cat | 2023/01-2024/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| GreatWall | ORA Good Cat | 2023/01-2024/06 | 433MHz 3641100XKR02 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|---------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| GreatWall | ORA Good Cat | 2023/01-2024/06 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | ORA Good Cat | 2023/01-2024/06 | 433MHz 3641100AKR02 A | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| GreatWall | ORA Good Cat | 2023/01-2024/06 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Steed Pick Up | 2014/01-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | TanKe 300 | 2023/01-2024/06 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | TanKe 300 | 2023/01-2024/06 | 433MHz 3641101AKN01 A | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| GreatWall | TanKe 300 | 2020/12-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | V200 | 2011/01-2016/12 | 433MHz 3641110AK80X A | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | V240 | 2009/01-2016/12 | 433MHz 3641110AK80X A | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C20R | 2014/01-2018/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C30 | 2014/01-2017/12 | 433MHz 3641110AK80X A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 5 | 2018/01-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 5 | 2011/01-2016/12 | 433MHz 3641110AK80X A | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 5 | 2016/01-2024/06 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 6 | 2014/04-2018/11 | 433MHz 3641100XSZ08 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 6 | 2014/01-2015/12 | 433MHz 3641110K80 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 6 | 2012/01-2015/12 | 433MHz 3641110AK80X A | | ● | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 7 | 2018/06-2024/06 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 7 | 2018/06-2024/06 | 433MHz 3641100XKU00 B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | X200 | 2011/01-2016/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| GreatWall | X240 | 2009/01-2016/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| HSV | Clubsport R8 | 2014/01-2019/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| HSV | G | 2014/01-2016/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| HSV | GTC | 2014/01-2018/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------------------|-----------------|-----------------------------|----------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| HSV | GTS | 2017/01-2019/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| HSV | GTSR | 2017/01-2019/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| HSV | Grange | 2014/01-2017/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| HSV | Grange | 2011/01-2013/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| HSV | Maloo R8 LSA | 2014/01-2019/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| HSV | Senator Signature | 2016/01-2019/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| HSV | Senator Signature | 2010/01-2012/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| HSV | SportsCat | 2018/01-2020/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Haval | Dargo | 2020/08-2024/06 | 433MHz 3641100XKR02 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Dargo | 2020/08-2024/06 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Dargo | 2020/08-2024/06 | 433MHz 3641101BKN01 A | | ● | ● | ○ | O/A | 433MHz | SAT | ● | ● |
| Haval | Dargo II | 2023/03-2024/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Haval | F7 | 2018/11-2023/12 | 433MHz 3641100BKRO2 A | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Haval | H1 | 2014/01-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H2 | 2014/01-2023/12 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 | 2011/01-2015/12 | 433MHz 3641100XKZ16 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 | 2016/01-2019/12 | 433MHz 3641100XKZ16 B | CC6461RM | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Haval | H6 | 2016/01-2021/12 | 433MHz 3641100XKZ16 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 Coupe | 2015/01-2017/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 Coupe | 2017/06-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 II | 2019/07-2022/12 | 433MHz 3641100AKZ16 A | CC6461RM CC6472RM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Haval | H6 II | 2020/01-2021/01 | 433MHz 3641100AKZ16 A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Haval | H6 II | 2017/01-2021/12 | 433MHz 3641100XKR02 A | CC6472RM CC6464RM | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 III | 2020/08-2024/06 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 III | 2020/08-2024/06 | 433MHz 3641100XKR02 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|---------|-----------------|-----------------------------|-----------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Haval | H6 III | 2020/08-2024/06 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 PHEV | 2022/01-2024/06 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H7 | 2023/01-2023/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Haval | H7 | 2016/01-2022/12 | 433MHz 3641100XKU00 B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H8 | 2013/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H9 | 2019/08-2024/06 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H9 | 2019/08-2024/06 | 433MHz 3641100XKR02 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H9 | 2014/01-2019/12 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Jolion | 2020/08-2023/12 | 433MHz 3641100BKR02 A | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Haval | Jolion | 2020/08-2023/12 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Jolion | 2020/08-2023/12 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | Jolion | 2020/08-2023/12 | 433MHz 3641100AKR02 A | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Holden | Acadia | 2018/01-2020/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | Astra H | 2004/01-2010/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | Astra J | 2009/01-2011/09 | 433MHz | GM P3400 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Holden | Astra J | 2011/10-2014/05 | 433MHz | GM P3400/ GM A3300 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Holden | Astra J | 2014/06-2014/12 | 433MHz | GM P3400 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Holden | Astra J | 2015/01-2015/09 | 433MHz | GM P3400 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | Astra K | 2015/10-2020/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | Barina | 2011/01-2015/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | Barina | 2016/01-2018/12 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Holden | Caprice | 2014/01-2017/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Holden | Caprice | 2014/01-2017/12 | 315MHz 13581558 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Holden | Caprice | 2011/01-2013/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Holden | Captiva | 2012/01-2015/12 | 433MHz | C100 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | Captiva | 2006/06-2008/12 | 433MHz | C100 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | Captiva | 2009/01-2011/12 | 433MHz | C100 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | Captiva | 2016/01-2019/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | Cascada | 2013/01-2014/05 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Holden | Cascada | 2014/06-2019/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Holden | Colorado | 2015/01-2015/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Colorado | 2014/01-2014/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Colorado | 2013/01-2017/12 | 433MHz | GMI700 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Holden | Colorado | 2011/07-2012/12 | 433MHz | GMI700 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Holden | Colorado | 2011/01-2013/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Holden | Colorado | 2016/01-2016/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Colorado | 2017/01-2019/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Colorado | 2017/01-2021/12 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Holden | Colorado | 2018/01-2021/12 | 315MHz 13516164 | | ● | ● | ○ | O | 315MHz | Schrader | ● | ● |
| Holden | Commodore | 2018/01-2020/12 | 433MHz | ZB | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Holden | Commodore | 2013/01-2017/12 | 315MHz | VF | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Commodore | 2010/01-2013/12 | 433MHz | VE | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Holden | Corvette | 2019/01-2019/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Holden | Equinox | 2017/01-2021/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Holden | Equinox | 2017/06-2020/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Equinox | 2016/01-2016/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Equinox | 2017/01-2017/05 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Equinox | 2013/01-2015/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Equinox | 2011/01-2012/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Equinox | 2010/01-2010/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Equinox | 2009/01-2009/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Equinox | 2008/01-2008/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Equinox | 2007/01-2007/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Insignia | 2017/06-2022/12 | 433MHz | | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Holden | Spark | 2013/01-2014/12 | 433MHz | M1JC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Holden | Spark | 2016/01-2016/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Holden | Spark | 2015/01-2015/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Holden | Spark | 2009/07-2012/12 | 433MHz | M1JC | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Holden | Spark | 2017/01-2019/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Holden | Statesman | 2014/01-2017/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Holden | Statesman | 2013/01-2013/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Holden | Trailblazer | 2006/01-2008/12 | 433MHz | GMT360 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Holden | Trailblazer | 2001/01-2005/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Holden | Trailblazer | 2006/01-2006/12 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Holden | Trailblazer | 2016/01-2019/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Trailblazer | 2013/01-2014/12 | 433MHz 20925925 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Holden | Trailblazer | 2012/01-2013/12 | 433MHz 20922901 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Holden | Trailblazer | 2009/01-2009/12 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Holden | Trailblazer | 2007/01-2009/12 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Holden | Trailblazer | 2017/01-2020/12 | 433MHz 13598773 | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Holden | Trax | 2016/01-2016/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Holden | Trax | 2013/01-2014/12 | 433MHz | G1UC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Holden | Trax | 2015/01-2015/12 | 433MHz | G1UC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | Trax | 2015/01-2015/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Holden | Trax | 2013/01-2014/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Holden | Trax | 2012/01-2012/12 | 433MHz | G1UC | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Holden | Trax | 2016/01-2019/12 | 433MHz | G1UC | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Holden | UTE | 2014/01-2015/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | UTE | 2011/01-2013/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Holden | UTE | 2016/01-2018/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | Volt | 2010/01-2010/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Holden | Volt | 2011/01-2012/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Holden | Volt | 2013/01-2014/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Holden | Volt | 2015/01-2015/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Holden | WM Caprice | 2007/01-2012/12 | 433MHz | WM | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Honda | Accord | 2013/01-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Accord | 2008/01-2012/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Honda | CR-V | 2014/01-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | CR-V | 2012/01-2014/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Honda | CR-V | 2007/01-2011/12 | 315MHz Alloy/Steel | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Honda | CR-Z | 2010/01-2021/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | CR-Z | 2010/01-2017/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | City | 2014/01-2023/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Civic | 2012/01-2014/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Civic | 2016/01-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | HR-V | 2014/01-2020/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | HR-V | 2014/09-2024/06 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Insight | 2009/06-2021/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Jazz | 2014/01-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Jazz | 2014/01-2024/06 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Legend | 2015/01-2021/12 | 315MHz | Hybrid | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | NSX | 2016/01-2021/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | NSX | 2016/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Odyssey | 2017/01-2020/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Odyssey | 2021/01-2024/06 | 433MHz 42753T3RA02 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Odyssey | 2014/01-2017/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hummer | H3 | 2005/01-2006/12 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Hummer | H3 | 2007/01-2012/12 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Hyundai | Accent | 2014/01-2020/06 | 433MHz Lo Line | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 2011/04-2021/12 | 433MHz Hi Line | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 2011/01-2014/12 | 315MHz | RB | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Accent | 2006/01-2007/12 | 315MHz 529333E000 | MC | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Accent | 2005/01-2010/12 | 315MHz | MC | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Custin | 2022/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Baolong | ● | ● |
| Hyundai | Elantra | 2007/01-2010/12 | 315MHz | HD | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Elantra | 2010/01-2012/12 | 315MHz | FD | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Elantra | 2010/01-2013/10 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Elantra | 2020/07-2023/12 | 433MHz 52940L1100 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 2015/01-2020/12 | 433MHz | AD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 2014/01-2018/12 | 433MHz | MD/UD | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Elantra | 2013/10-2019/12 | 315MHz Lo Line | | ● | ● | ○ | O/A | 315MHz | TRW | ● | ● |
| Hyundai | Elantra N | 2022/01-2023/12 | 433MHz 52940L8200 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Equus | 2013/03-2016/06 | 315MHz Hi Line | VI | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Genesis | 2013/01-2019/12 | 433MHz | DH | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis | 2008/09-2014/12 | 315MHz Conti | BH | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Genesis | 2008/01-2014/12 | 315MHz TRW | BH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Genesis | 2007/01-2014/12 | 433MHz | BH | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Genesis G70 | 2018/01-2023/12 | 433MHz | IK | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G70 | 2017/01-2017/12 | 433MHz | IK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G80 | 2021/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 | 2016/07-2019/12 | 433MHz | DH | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 | 2021/07-2023/12 | 433MHz 52940T6000 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 | 2020/01-2022/12 | 433MHz | DH | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 EV | 2022/11-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV60 | 2021/12-2024/06 | 433MHz 52933D2100 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV60 | 2021/12-2024/06 | 433MHz 52940CG100 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis GV70 | 2020/12-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV70 | 2021/01-2024/06 | 433MHz 52940T6000 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV70 EV | 2022/11-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV80 | 2021/07-2024/06 | 433MHz 52940T6000 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV80 | 2020/01-2024/06 | 433MHz 52933D4100 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis Sedan | 2009/01-2014/12 | 315MHz | BH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Grandeur GN7 | 2023/01-2024/12 | 433MHz | | ● | ● | ○ | C | 433MHz | Continental | ● | ● |
| Hyundai | H-1 | 2014/01-2023/12 | 433MHz | HR | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq | 2016/01-2023/12 | 433MHz | AE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 5 | 2020/01-2021/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 5 | 2022/01-2024/06 | 433MHz 52940L1100 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 5 | 2022/01-2024/06 | 433MHz 52940L8200 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Ioniq 6 | 2021/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Kona | 2017/01-2023/12 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Continental | ● | ● |
| Hyundai | Nexo | 2018/04-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Nexo | 2020/01-2022/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Nexo | 2023/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Palisade | 2018/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 2013/04-2017/12 | 433MHz 529333N100 | DM/DMI | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 2018/03-2023/12 | 433MHz | TM/TMA | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 2021/01-2023/12 | 433MHz | TMA | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 2009/06-2012/12 | 315MHz | CM | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Santa Fe | 2006/01-2008/12 | 433MHz | CM | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Hyundai | Sonata | 2020/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 2011/01-2016/12 | 433MHz 529333N100 | YFC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 2014/04-2019/12 | 433MHz Hi Line | LF/LFA | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata | 2011/01-2016/12 | 315MHz 529333N000 | YFC | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Sonata | 2010/01-2010/12 | 315MHz | YF | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Sonata | 2009/12-2014/05 | 315MHz 529332M000 | YF | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Starex | 2021/01-2023/12 | 433MHz 52940CG100 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Starex | 2007/01-2021/03 | 433MHz | TQ | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Staria | 2021/03-2024/06 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 2014/06-2015/12 | 315MHz | ix | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 2007/01-2010/12 | 315MHz 529333E000 | | ○ | ● | ○ | A | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 2010/01-2013/07 | 315MHz | LM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 2014/09-2015/12 | 315MHz | LM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 2015/01-2015/12 | 433MHz | TL/TLE | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 2015/05-2020/12 | 433MHz Hi Line | TL | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 2021/01-2024/06 | 433MHz 52940BV100 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 2021/01-2021/09 | 433MHz Hi Line | TL | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Veloster | 2011/03-2019/06 | 433MHz | FS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Veloster | 2019/01-2020/12 | 433MHz 529332V100 | FS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Veloster | 2019/01-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Veloster | 2011/01-2019/12 | 315MHz | FS | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Hyundai | Venue | 2022/01-2023/12 | 433MHz 52933D4100 | QXI | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Venue | 2019/01-2022/12 | 433MHz 52933D4100 | QX/QXI | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | i10 | 2013/11-2020/06 | 433MHz 52933B2100 | IA | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | i10 | 2016/01-2019/12 | 433MHz | PA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i20 | 2008/01-2014/05 | 433MHz 529331J000 | PB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i20 | 2014/10-2020/12 | 433MHz | GB | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i20 | 2021/01-2022/12 | 433MHz 52933F2000 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | i20 | 2021/01-2023/12 | 433MHz 52933C1100 | GB | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------|-----------------|----------------------|---------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | i20 N | 2021/01-2023/07 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Hyundai | i20 N | 2021/01-2024/06 | 433MHz 52933D4100 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 2016/08-2024/06 | 433MHz | PD/Pde | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 2021/01-2021/12 | 433MHz | CN7 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 2017/01-2020/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Hyundai | i30 | 2014/03-2019/12 | 433MHz | GD | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 2007/01-2016/12 | 433MHz | FD/Fde | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 2016/08-2024/06 | 433MHz 52933562C6 | PD/Pde | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Hyundai | i30 Fastback | 2017/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | i30 N | 2018/01-2023/12 | 433MHz 52933F2000 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | i30 N | 2018/01-2023/12 | 433MHz 52940L8200 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Hyundai | i40 | 2017/01-2019/12 | 433MHz | IF | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Hyundai | i40 | 2014/04-2020/12 | 433MHz | VF | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Hyundai | i40 | 2011/01-2014/03 | 433MHz | VF | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| Hyundai | i40 | 2011/01-2014/03 | 433MHz Second | VF | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| Hyundai | iLoad | 2007/01-2022/12 | 433MHz | FQ | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Hyundai | iMax | 2014/01-2022/12 | 433MHz 529334H100 | TQ | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Hyundai | iMax | 2018/01-2019/12 | 433MHz 52933A5100 | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Hyundai | ix35 | 2017/01-2019/12 | 433MHz | EL | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 2014/03-2016/12 | 433MHz | EL | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| Infiniti | EX Series | 2007/01-2010/03 | 315MHz | J50 | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Infiniti | EX Series | 2010/04-2018/09 | 315MHz | J50 | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Infiniti | FX Series | 2007/07-2010/08 | 315MHz 40700JK01B | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Infiniti | FX Series | 2007/07-2010/08 | 315MHz | S51 | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Infiniti | FX Series | 2010/09-2019/09 | 315MHz | S51 | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Infiniti | FX Series | 2011/04-2014/04 | 433MHz 407001LLOD | | ● | ● | ○ | O | 433MHz | Pacific | ● | ● |
| Infiniti | G Series | 2011/07-2014/12 | 433MHz 407001AYOA | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Infiniti | G Series | 2010/04-2015/12 | 315MHz | V36 | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Infiniti | G Series | 2007/01-2010/03 | 315MHz | V36 | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Infiniti | M Series | 2008/01-2010/12 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Infiniti | M Series | 2009/12-2016/04 | 433MHz | M312/Y51 | ● | ● | ○ | O | 433MHz | Pacific | ● | ● |
| Infiniti | M Series | 2006/01-2010/12 | 315MHz | Y50 | ● | ● | ○ | O | 315MHz | Schrader | ● | ● |
| Infiniti | M Series | 2011/01-2013/12 | 315MHz | Y51 | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Infiniti | Q30 | 2015/01-2023/12 | 433MHz | GD1A/H15 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Infiniti | Q30 | 2015/01-2019/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| Infiniti | Q50 | 2013/01-2022/07 | 315MHz | V37 | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Infiniti | Q50 | 2013/01-2024/06 | 433MHz | L53H/D53H/V37 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Infiniti | Q60 | 2017/01-2024/06 | 315MHz 407004GA0B | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Infiniti | Q60 | 2013/01-2017/12 | 315MHz | CV36/HV36 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | Q60 | 2013/07-2016/06 | 433MHz | L53A/CV36 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | Q60 | 2016/05-2022/12 | 433MHz | CV37 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | Q70 | 2013/01-2019/12 | 315MHz | Y51 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | Q70 | 2013/01-2019/12 | 433MHz 407005ZH0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | Q70 | 2014/01-2015/11 | 433MHz | M312/Y51 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | Q70 | 2017/01-2019/12 | 433MHz 407003JA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX30 | 2016/03-2020/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Infiniti | QX50 | 2018/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX70 | 2014/01-2019/06 | 315MHz | S51 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX70 | 2013/10-2014/04 | 433MHz 407001LLOD | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX70 | 2013/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX70 | 2014/01-2020/06 | 433MHz 407006WY0B | P53C/S51 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX80 | 2022/07-2024/06 | 315MHz 407006GPOA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX80 | 2017/01-2023/12 | 315MHz 407005UV0A | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX80 | 2014/01-2016/12 | 315MHz | Z62 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX80 | 2013/01-2022/12 | 433MHz | Z62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX80 | 2010/01-2016/09 | 433MHz | JA60 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Isuzu | D-Max | 2020/09-2024/06 | 433MHz 8974993680 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Isuzu | D-Max | 2007/01-2020/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Isuzu | MU-X | 2016/11-2024/06 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| Jaguar | E-Pace | 2022/01-2023/12 | 433MHz M8E21A159AA | X540 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | E-Pace | 2017/01-2018/12 | 433MHz | X540 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | E-Pace | 2019/01-2022/12 | 433MHz | X540 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 2019/01-2022/12 | 433MHz | X761 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 2022/01-2023/12 | 433MHz M8E21A159AA | X761 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 2015/01-2018/12 | 433MHz | X761 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2016/05-2018/12 | 433MHz FW931A159AB | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2019/01-2021/06 | 433MHz FW931A159AB | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2019/01-2023/12 | 433MHz GX631A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2012/11-2016/04 | 433MHz FW931A159AB | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2012/11-2016/04 | 433MHz AH521A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2012/11-2016/04 | 315MHz AH521A159CA | X152 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jaguar | F-Type | 2021/01-2023/12 | 433MHz M8E21A159AA | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2016/05-2018/12 | 433MHz GX631A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jaguar | I-Pace | 2017/01-2018/12 | 433MHz | X590 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 2019/01-2023/12 | 433MHz GX631A159AA | X590 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 2021/01-2023/12 | 433MHz M8E21A159AA | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | S-Type | 1998/10-2011/08 | 433MHz | X200 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | S-Type | 1998/10-2011/08 | 315MHz | X200 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | Super V8 | 2005/01-2009/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Jaguar | X-Type | 2001/01-2009/12 | 433MHz | X400 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | X-Type | 2001/01-2009/12 | 315MHz | X400 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XE | 2015/04-2018/12 | 433MHz FW931A159AB | X760 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 2015/01-2018/12 | 433MHz GX631A159AA | X760 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 2022/01-2023/12 | 433MHz M8E21A159AA | X760 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 2019/01-2022/12 | 433MHz GX631A159AA | X760 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 2015/09-2018/12 | 433MHz | X260 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 2009/04-2015/08 | 315MHz | X250 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XF | 2019/01-2022/12 | 433MHz GX631A159AA | X260 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 2007/01-2015/08 | 433MHz | X250 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 2022/01-2023/12 | 433MHz M8E21A159AA | X260 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 2010/01-2020/04 | 433MHz FW931A159AB | X351 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 2010/01-2020/04 | 433MHz AH521A159AA | X351 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 2010/01-2020/04 | 433MHz GX631A159AA | X351 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 2002/12-2009/12 | 433MHz | X350 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 2010/01-2015/12 | 433MHz | X150 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 2006/01-2009/12 | 433MHz | X150 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 2006/01-2009/12 | 315MHz | X150 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XK | 2010/01-2015/12 | 315MHz | X150 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XKR | 2006/01-2014/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Cherokee | 2015/12-2017/12 | 433MHz | KL | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 2019/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 2019/01-2022/12 | 315MHz | | ● | ● | ○ | A | 315MHz | TRW | ● | ● |
| Jeep | Cherokee | 2018/01-2023/12 | 433MHz | KL | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 2015/01-2017/12 | 315MHz | | ● | ● | ● | O/A | 315MHz | TRW | ● | ● |
| Jeep | Cherokee | 2013/10-2015/11 | 433MHz | KL | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 2005/01-2013/12 | 433MHz 56029359AC | KK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Cherokee | 2018/01-2018/12 | 315MHz | | ● | ● | ○ | A | 315MHz | TRW | ● | ● |
| Jeep | Commander | 2008/01-2011/12 | 433MHz | XK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Commander | 2006/01-2007/12 | 315MHz | XK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Commander | 2006/01-2007/12 | 433MHz | XK | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 2018/01-2018/12 | 433MHz | MP/MX | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jeep | Compass | 2019/01-2024/12 | 433MHz | MP/MX | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 2018/01-2018/12 | 315MHz | MK49 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jeep | Compass | 2017/01-2017/12 | 433MHz | 551 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 2014/01-2017/12 | 315MHz Continental | MK49 | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Compass | 2012/01-2016/12 | 315MHz | MK49 | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Compass | 2012/01-2015/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Compass | 2010/01-2011/12 | 315MHz | MK49 | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Compass | 2007/01-2011/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Compass | 2017/01-2017/12 | 433MHz | MP/MX | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 2019/01-2022/12 | 433MHz | 551 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 2019/01-2019/12 | 315MHz | MK49 | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Jeep | Compass | 2018/01-2018/12 | 433MHz | 551 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Gladiator | 2021/07-2024/12 | 433MHz Conti | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Gladiator | 2019/11-2022/12 | 433MHz MRXAG4WA5 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 2004/05-2005/12 | 315MHz | WK | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 2005/01-2006/05 | 433MHz | | ● | ● | ● | O | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 2006/01-2007/12 | 315MHz | WK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 2006/06-2010/12 | 433MHz | WH | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 2008/01-2011/12 | 315MHz | WK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 2011/01-2011/12 | 433MHz | WK74 | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 2012/01-2015/12 | 433MHz | WK74 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 2016/01-2017/12 | 433MHz | WK | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 2010/07-2010/12 | 433MHz | WK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 2018/01-2022/12 | 433MHz 68252493AB | WK | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 2021/01-2023/12 | 433MHz Conti | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 2001/01-2004/12 | 433MHz | WK/WJ | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Jeep | Grand Wagoneer | 2022/01-2023/12 | 433MHz 68339096AB | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Liberty | 2005/01-2006/12 | 315MHz | KJ | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Jeep | Liberty | 2010/01-2012/12 | 315MHz | KK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Liberty | 2006/01-2012/12 | 433MHz | KK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Liberty | 2007/01-2009/12 | 315MHz | KJ | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Liberty | 2002/01-2004/12 | 433MHz | KJ | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Patriot | 2012/01-2017/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Patriot | 2011/01-2016/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Patriot | 2018/01-2019/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Jeep | Patriot | 2007/01-2010/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Patriot | 2007/01-2008/12 | 315MHz | | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Patriot | 2014/12-2017/12 | 433MHz | MK74 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Patriot | 2009/01-2014/12 | 315MHz | MK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Renegade | 2019/01-2020/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Jeep | Renegade | 2019/01-2020/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 2018/01-2018/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Jeep | Renegade | 2018/01-2018/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jeep | Renegade | 2015/01-2016/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 2015/01-2017/12 | 315MHz | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Renegade | 2017/01-2017/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Wagoneer | 2022/01-2022/12 | 433MHz 68339096AB | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Wagoneer | 2023/01-2023/12 | 433MHz | WS | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Wrangler | 2021/01-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2018/01-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2008/06-2010/12 | 433MHz | JK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2010/01-2012/12 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2019/01-2019/12 | 433MHz | J3 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2010/01-2013/12 | 433MHz | JK72 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2013/01-2014/12 | 433MHz | JK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2014/01-2017/12 | 433MHz | JL | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2010/01-2012/12 | 315MHz | JK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2019/01-2020/12 | 433MHz | JL | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2021/07-2024/12 | 433MHz Conti | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Wrangler | 2007/01-2009/12 | 315MHz | JK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| KIA | Bongo | 2020/01-2023/12 | 433MHz | | ● | ● | ○ | C | 433MHz | Continental | ● | ● |
| KIA | Bongo | 2014/01-2016/12 | 433MHz | | ● | ● | ○ | C | 433MHz | Continental | ● | ● |
| KIA | Carens | 2019/01-2019/12 | 433MHz | RP | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| KIA | Carens | 2012/01-2020/12 | 433MHz | RP/UN | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Carnival | 2016/01-2018/12 | 433MHz | YP/VQ | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| KIA | Carnival | 2020/01-2024/06 | 433MHz | KA4 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| KIA | Carnival | 2019/01-2020/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| KIA | Carnival | 2005/01-2014/12 | 315MHz | YP | ● | ● | ○ | O | 315MHz | Lear | ● | ● |
| KIA | Ceed | 2018/05-2019/12 | 433MHz | CD | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| KIA | Ceed | 2012/03-2018/06 | 433MHz | JD | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| KIA | Ceed | 2020/01-2020/12 | 433MHz | CD | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| KIA | Cerato | 2017/01-2018/12 | 315MHz | YD | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| KIA | Cerato | 2022/01-2023/12 | 433MHz | BD | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| KIA | Cerato | 2019/01-2021/12 | 433MHz | BD | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| KIA | Cerato | 2019/01-2019/12 | 315MHz | YD | ● | ● | ○ | C | 315MHz | TRW | ● | ● |
| KIA | Cerato | 2016/01-2018/12 | 433MHz 52933A7100 | YD | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| KIA | Cerato | 2012/01-2014/12 | 315MHz | YD | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| KIA | Cerato | 2015/01-2016/12 | 433MHz | BD | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| KIA | EV6 | 2021/03-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| KIA | EV9 | 2023/07-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| KIA | K3 | 2022/01-2023/12 | 433MHz | BD | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| KIA | K3 | 2021/07-2021/12 | 433MHz | BD | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| KIA | K3 | 2012/01-2018/12 | 433MHz TRW | YDC/YD | ● | ● | ○ | O | 433MHz | TRW | ● | ● |
| KIA | Magentis | 2005/12-2012/12 | 315MHz | | ● | ● | ○ | O | 315MHz | Lear | ● | ● |
| KIA | Niro | 2017/01-2023/12 | 433MHz | DE | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| KIA | Optima | 2014/03-2019/12 | 433MHz | JF | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Optima | 2015/09-2022/12 | 433MHz | JF/JFA | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Optima | 2013/09-2015/12 | 315MHz | TF/QF | ● | ● | ○ | O | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| KIA | Optima | 2010/07-2013/09 | 315MHz | TF/QF | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| KIA | Picanto | 2017/01-2022/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| KIA | Picanto | 2011/01-2017/12 | 433MHz 529333N100 | TA | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| KIA | Pro Ceed | 2023/01-2023/12 | 433MHz | CD | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| KIA | Pro Ceed | 2012/03-2018/06 | 433MHz | JD | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| KIA | Pro Ceed | 2018/05-2019/12 | 433MHz | CD | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| KIA | Pro Ceed | 2022/01-2022/12 | 433MHz | CD | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| KIA | Pro Ceed | 2020/01-2021/06 | 433MHz | CD | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| KIA | Quoris | 2012/06-2019/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| KIA | Rio | 2011/06-2017/12 | 315MHz | UB | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| KIA | Rio | 2014/03-2019/12 | 433MHz | UB | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| KIA | Rio | 2016/12-2020/06 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| KIA | Rio | 2017/01-2021/12 | 433MHz | QB | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Rio | 2017/01-2023/12 | 433MHz | SC | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| KIA | Rondo | 2014/03-2019/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Seltos | 2019/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| KIA | Sorento | 2015/01-2017/07 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| KIA | Sorento | 2014/06-2015/12 | 315MHz | XM/UM | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| KIA | Sorento | 2009/01-2014/05 | 315MHz | XM | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| KIA | Sorento | 2014/03-2019/12 | 433MHz | UM | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| KIA | Sorento | 2017/08-2018/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| KIA | Sorento | 2020/01-2023/12 | 433MHz | MQ4 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| KIA | Soul | 2009/01-2013/10 | 315MHz | AM | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| KIA | Soul | 2013/08-2018/12 | 433MHz | PS | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| KIA | Soul | 2019/01-2019/12 | 433MHz | PS | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| KIA | Soul EV | 2013/01-2018/12 | 433MHz | PS EV | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| KIA | Soul EV | 2019/01-2019/12 | 433MHz | PS EV | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| KIA | Sportage | 2014/06-2015/12 | 315MHz | SL | ● | ● | ○ | O/A | 315MHz | TRW | ● | ● |
| KIA | Sportage | 2015/11-2021/06 | 433MHz | QL/QLE | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Sportage | 2005/01-2007/12 | 315MHz Lo Line | KM | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| KIA | Sportage | 2008/01-2008/12 | 315MHz Lo Line | KM | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| KIA | Sportage | 2009/01-2010/12 | 315MHz Lo Line | KM/SL | ● | ● | ○ | O | 315MHz | TRW | ● | ● |
| KIA | Sportage | 2010/01-2014/05 | 315MHz | SL | ● | ● | ○ | O/A | 315MHz | TRW | ● | ● |
| KIA | Sportage | 2021/01-2024/06 | 433MHz 52940L1100 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| KIA | Stinger | 2018/01-2023/12 | 433MHz | CK | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| KIA | Stinger | 2017/06-2017/12 | 433MHz | CK | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| LYNK_CO | 01 | 2023/01-2023/12 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| LYNK_CO | 09 | 2023/01-2024/06 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Lamborghini | Aventador | 2011/01-2023/12 | 433MHz | LB834 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Gallardo | 2007/01-2014/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Huracan | 2014/01-2024/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Murcielago | 2002/01-2015/12 | 433MHz | LB824 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | One Off | 2016/01-2020/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|-----------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lamborghini | Reventon | 2007/01-2010/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Sian | 2020/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Urus | 2018/01-2024/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Defender | 1997/01-2019/12 | 433MHz BH521A159AA | L316 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 2020/01-2023/12 | 433MHz FW931A159AB | L663 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 2020/01-2023/12 | 433MHz GX631A159AA | L663 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 2020/01-2023/12 | 433MHz M8E21A159AA | L663 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2009/12-2016/12 | 315MHz AH521A159CA | L319 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | Discovery | 2009/12-2016/12 | 433MHz AH521A159AA | L319 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2009/12-2016/12 | 433MHz GX631A159AA | L319 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2017/01-2018/12 | 433MHz GX631A159AA | L462 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2019/01-2022/12 | 433MHz GX631A159AA | L462 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2021/01-2023/12 | 433MHz M8E21A159AA | L462 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2004/06-2009/11 | 315MHz | L319 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | Discovery | 2002/01-2004/05 | 433MHz | L318 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Discovery | 2009/12-2016/12 | 433MHz FW931A159AB | L319 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2009/01-2016/12 | 315MHz BH521A159CA | L319 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | Discovery | 2009/12-2016/12 | 433MHz BH521A159AA | L319 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2004/06-2009/11 | 433MHz | L319 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 2021/01-2023/12 | 433MHz M8E21A159AA | L550 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 2019/01-2022/12 | 433MHz GX631A159AA | L550 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 2019/01-2022/12 | 433MHz BH521A159AA | L550 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 2014/06-2018/12 | 433MHz GX631A159AA | L550 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 2014/01-2018/12 | 433MHz BH521A159AA | L550 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | FreeLander | 2006/01-2014/12 | 433MHz FW931A159AB | L359 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | FreeLander | 2006/01-2014/12 | 315MHz 4H231A159CA | L359 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | FreeLander | 2006/01-2014/12 | 433MHz BH521A159AA | L359 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | FreeLander | 2006/01-2014/12 | 433MHz GX631A159AA | L359 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Land Rover | FreeLander | 2006/01-2014/12 | 315MHz BH521A159CA | L359 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Land Rover | FreeLander | 2006/01-2014/12 | 315MHz AH521A159CA | L359 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Range Rover | 2010/01-2012/12 | 433MHz BH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2002/01-2004/12 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Range Rover | 2005/01-2009/12 | 315MHz | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2005/01-2009/12 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2010/01-2012/12 | 433MHz AH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2010/01-2012/12 | 433MHz GX631A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2010/01-2012/12 | 315MHz AH521A159CA | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2013/01-2015/12 | 433MHz AH521A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2013/01-2015/12 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2013/01-2015/12 | 315MHz AH521A159CA | L405 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2010/01-2012/12 | 315MHz BH521A159CA | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2022/01-2023/12 | 433MHz M8E21A159AA | L460 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2022/01-2023/12 | 433MHz GX631A159AA | L460 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2020/02-2021/12 | 433MHz M8E21A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2019/01-2021/12 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2016/01-2018/12 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2016/01-2018/01 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2013/01-2015/12 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2021/07-2023/12 | 433MHz M8E21A159AA | L551 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2011/07-2015/06 | 433MHz AH521A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2011/07-2015/06 | 315MHz AH521A159CA | L538 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2011/07-2015/06 | 315MHz BH521A159CA | L538 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2011/07-2015/06 | 433MHz BH521A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2015/07-2017/12 | 433MHz FW931A159AB | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2015/07-2018/12 | 315MHz BH521A159CA | L538 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2015/07-2018/12 | 433MHz BH521A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2015/07-2018/12 | 433MHz GX631A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2019/01-2023/12 | 433MHz GX631A159AA | L551 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2016/01-2018/12 | 433MHz FW931A159AB | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-------------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Range Rover Sport | 2012/10-2013/06 | 433MHz | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2012/10-2013/06 | 433MHz AH521A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2012/10-2013/06 | 433MHz FW931A159AB | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2012/10-2013/06 | 315MHz AH521A159CA | L320 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2012/10-2013/06 | 315MHz | L320 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2021/01-2022/09 | 433MHz M8E21A159AA | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2010/01-2012/09 | 433MHz GX631A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2010/01-2012/09 | 315MHz | L320 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2010/01-2012/09 | 315MHz AH521A159CA | L320 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2010/01-2012/09 | 433MHz AH521A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2022/10-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2010/01-2012/09 | 433MHz FW931A159AB | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2019/01-2022/09 | 433MHz FW931A159AB | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2019/01-2022/09 | 433MHz GX631A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2010/01-2012/09 | 433MHz | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2016/01-2018/12 | 433MHz GX631A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2013/07-2015/12 | 433MHz FW931A159AB | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2013/07-2015/12 | 433MHz GX631A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2005/01-2009/12 | 315MHz | L320 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2005/01-2009/12 | 433MHz | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2013/07-2015/12 | 315MHz AH521A159CA | L494 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2013/07-2015/12 | 433MHz AH521A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2012/10-2013/06 | 433MHz GX631A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 2021/01-2023/12 | 433MHz M8E21A159AA | L560 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 2019/01-2023/12 | 433MHz GX631A159AA | L560 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 2017/01-2018/12 | 433MHz | L560 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2002/01-2004/12 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-------------------|-----------------|-----------------------|-----------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Range Rover Vogue | 2005/01-2009/12 | 315MHz | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2005/01-2009/12 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2010/01-2012/12 | 315MHz BH521A159CA | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2010/01-2012/12 | 315MHz AH521A159CA | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2010/01-2012/12 | 433MHz BH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2013/01-2015/12 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2016/01-2018/01 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2013/01-2015/12 | 433MHz AH521A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2013/01-2015/12 | 315MHz AH521A159CA | L405 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2022/01-2023/12 | 433MHz M8E21A159AA | L460 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2013/01-2015/12 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2022/01-2023/12 | 433MHz GX631A159AA | L460 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2020/02-2021/12 | 433MHz M8E21A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2019/01-2021/12 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2016/01-2018/12 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2010/01-2012/12 | 433MHz GX631A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2010/01-2012/12 | 433MHz AH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Lexus | CT Series | 2013/12-2022/12 | 433MHz | 080A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 2018/06-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 2006/01-2012/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 2012/06-2021/01 | 433MHz C210 | 980L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GS Series | 2012/01-2022/12 | 433MHz | 920L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GS Series | 2005/01-2012/03 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GS Series | 2005/01-2011/12 | 433MHz | GS32 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GX Series | 2013/09-2019/08 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | IS Series | 2013/04-2023/12 | 433MHz C210 | 030L/400A/7 20A/ XE30 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | IS Series | 2006/01-2021/01 | 433MHz | XE20 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LC Series | 2017/01-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LM Series | 2020/01-2021/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 2012/10-2017/09 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 2006/08-2012/09 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 2017/10-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LX Series | 2015/10-2021/12 | 433MHz C215 | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------------|-----------------|------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lexus | LX Series | 2012/06-2022/12 | 433MHz C210 | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | NX Series | 2014/01-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RC Series | 2014/09-2023/01 | 433MHz | XC1/720A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RX Series | 2014/01-2021/12 | 433MHz C210 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RX Series | 2016/06-2024/06 | 433MHz C215 | 740A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | SC Series | 2006/08-2010/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | SC Series | 2006/08-2010/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | UX Series | 2018/01-2024/06 | 433MHz C215 | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lotus | 3-Eleven | 2014/01-2019/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Elise | 2008/01-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Evora | 2009/06-2021/12 | 433MHz | Eagle | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Exige | 2000/09-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| MAXUS | D90 | 2017/08-2019/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | D90 | 2019/06-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | D90 PRO | 2020/04-2022/12 | 433MHz C00030048 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | D90 PRO | 2016/06-2020/12 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | E-Deliver 9 | 2020/01-2023/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| MAXUS | G10 | 2014/01-2024/06 | 433MHz GC91B50 | LTR | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | G10 | 2014/01-2024/06 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | G10 | 2014/01-2024/06 | 433MHz GC91B50 | PCR | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | G20 | 2019/04-2022/12 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | G20 | 2019/04-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | MIFA9 | 2023/01-2023/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| MAXUS | MIFA9 | 2022/06-2022/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| MAXUS | T60 | 2017/01-2024/06 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T60 | 2017/01-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T70 | 2017/01-2023/12 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T70 | 2017/01-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T90 | 2021/01-2024/06 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T90 | 2021/03-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | V80 | 2015/01-2022/12 | 433MHz TP3040001 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| MAXUS | V80 | 2015/01-2022/12 | 433MHz C00104713 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | V80 | 2023/01-2024/06 | 433MHz C00406825 | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| MAXUS | V90 | 2020/01-2024/06 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MG | GS | 2016/09-2020/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | HS | 2020/07-2023/12 | 433MHz 10718213 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------------|-----------------|-----------------------------|---------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| MG | HS | 2019/01-2021/12 | 433MHz 10290600 | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| MG | MG3 | 2013/09-2023/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | MG4 | 2022/09-2024/06 | 433MHz | | ○ | ● | ○ | C | 433MHz | Dias | ● | ● |
| MG | MG6 | 2012/01-2019/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | ZS | 2017/01-2024/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| MG | ZS | 2017/01-2023/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Mahindra | Black Mhawk Pickup | 2019/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Genio | 2014/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Pick-Up Dual Cab | 2014/06-2023/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mahindra | Scorpio | 2015/01-2023/12 | 433MHz 1805BA0131N | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Mahindra | Scorpio | 2017/12-2023/12 | 433MHz 1805BAA00791 N | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Mahindra | Scorpio | 2014/06-2023/12 | 433MHz | U202 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Scorpio-N | 2022/09-2023/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Mahindra | XUV500 | 2011/10-2023/12 | 433MHz 1805BA0131N | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mahindra | XUV500 | 2013/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | XUV500 | 2014/01-2023/12 | 433MHz 1805BAA00791 N | | ○ | ● | ○ | S | 433MHz | Huf/Beru | ● | ● |
| Maserati | 4200 GT/Coupe | 2002/01-2007/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Alfieri | 2019/01-2019/12 | 433MHz | M165 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Coupe | 2001/01-2007/12 | 433MHz | M138 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Ghibli | 2023/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Maserati | Ghibli | 2018/01-2022/12 | 433MHz | M156/ M157 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Ghibli | 2013/01-2017/12 | 433MHz | M156/ M157 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | GranCabrio | 2015/07-2017/12 | 433MHz Schrader | M147 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | GranCabrio | 2010/01-2020/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 2019/01-2021/12 | 433MHz | M156/ M157 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | GranTurismo | 2017/01-2018/12 | 433MHz | M156/ M157 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | GranTurismo | 2014/01-2022/01 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | GranTurismo | 2011/01-2016/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 2010/09-2013/12 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Grecale | 2022/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Maserati | Levante | 2015/04-2018/12 | 433MHz | WM | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Levante | 2020/01-2023/12 | 433MHz | M161 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Maserati | Levante | 2019/01-2023/12 | 433MHz | M156D | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Maserati | Levante | 2019/01-2022/12 | 433MHz | WM | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Levante | 2018/01-2018/12 | 433MHz | M156D | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Maserati | Levante | 2016/01-2019/12 | 433MHz | M161 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | MC20 | 2020/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Maserati | Quattroporte | 2013/01-2017/12 | 433MHz | M156 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Quattroporte | 2011/01-2013/12 | 433MHz | M139 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 2010/01-2010/12 | 433MHz | M139 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 2003/04-2009/12 | 433MHz | M139 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 2018/01-2022/12 | 433MHz | M156 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Spyder | 2001/07-2008/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maybach | Landulet | 2015/01-2019/12 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Maybach | Landulet | 2008/10-2014/12 | 433MHz | Ma009-127 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 57 | 2002/02-2013/12 | 433MHz | Ma007 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 62 | 2002/02-2013/12 | 433MHz | Ma007 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | S Series | 2021/01-2024/06 | 433MHz | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maybach | S Series | 2015/01-2021/12 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Maybach | S Series | 2021/01-2024/06 | 315MHz A0009058513 | 223 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Maybach | S Series | 2021/01-2024/06 | 315MHz | 223 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Maybach | S Series | 2021/01-2024/06 | 433MHz A0009058413 | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mazda | BT Pickup | 2006/01-2011/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Mazda | BT Pickup | 2020/01-2022/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mazda | BT Pickup | 2011/05-2019/12 | 433MHz | J26E | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mazda | BT-50 | 2021/01-2023/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mazda | BT-50 | 2011/10-2018/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mazda | BT-50 | 2006/08-2009/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mazda | BT-50 | 2018/10-2020/12 | 433MHz F2GT1A180DB | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mazda | CX-3 | 2018/03-2020/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-3 | 2021/01-2023/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-3 | 2015/01-2018/02 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-30 | 2020/01-2021/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-4 | 2016/01-2019/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-5 | 2011/11-2023/12 | 433MHz | J53C/J72A | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-5 | 2012/01-2017/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-5 | 2017/01-2020/12 | 315MHz Direct | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-5 | 2021/01-2023/12 | 315MHz BDGF37140 | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-60 | 2022/03-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-7 | 2010/01-2010/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-7 | 2011/01-2012/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-7 | 2006/01-2009/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-8 | 2021/01-2021/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-8 | 2017/01-2020/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-9 | 2020/01-2023/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-9 | 2007/01-2012/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-9 | 2013/01-2015/12 | 433MHz | J50C | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-9 | 2018/01-2020/12 | 315MHz | J50C | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-9 | 2016/01-2017/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-90 | 2023/01-2023/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|---------------------|--------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mazda | MX-30 | 2020/05-2023/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 | 2010/03-2015/04 | 315MHz | NC/J04C/J12A | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 | 2006/01-2010/02 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 | 2010/05-2018/12 | Indirect | ND | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | MX-5 | 2021/01-2023/12 | 315MHz | ND | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 | 2018/01-2020/12 | 315MHz | ND | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 2 | 2021/01-2021/12 | 315MHz | DJ | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 2 | 2019/01-2020/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 2 | 2011/01-2014/05 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 2 | 2014/06-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 2 | 2015/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 3 | 2019/01-2021/12 | 315MHz ALL new | BP | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 2020/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 2019/01-2023/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 2014/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 3 | 2011/01-2013/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 2010/01-2010/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 5 | 2016/01-2017/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 5 | 2011/01-2015/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 2008/01-2008/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 2011/01-2013/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 2021/01-2023/12 | 315MHz | GL | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 2017/01-2020/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 2014/01-2018/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 6 | 2009/01-2010/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| McLaren | 500 Series | 2015/01-2022/12 | 433MHz RDE011 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 2014/01-2023/12 | 433MHz F11001648001 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 2014/03-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 700 Series | 2017/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Artura | 2021/01-2024/06 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| McLaren | Elva | 2020/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | GT | 2019/01-2024/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | MP4-12C | 2011/01-2014/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | P1 | 2013/01-2020/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Senna | 2020/01-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Senna | 2017/01-2019/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Speedtail | 2019/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Sports Series | 2015/01-2022/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Super Series | 2011/03-2021/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 2018/06-2024/06 | 433MHz | 177 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 2018/06-2024/06 | 315MHz A0009054204 | 177 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 2014/04-2018/05 | 433MHz | 176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | A Class | 2012/01-2014/03 | 433MHz | 176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Mercedes | AMG | 2013/01-2018/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2023/06-2024/06 | 315MHz A0009058513 | 192 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2023/06-2024/06 | 433MHz A0009058706 | 192 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2023/06-2024/06 | 433MHz A0009058413 | 192 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2014/01-2023/12 | 433MHz | C190 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2018/11-2023/12 | 315MHz | 290 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2018/11-2023/12 | 433MHz | 290 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | B Class | 2019/02-2024/06 | 315MHz | 247 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | B Class | 2019/02-2024/06 | 433MHz A0009054104 | 247 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | B Class | 2011/11-2019/01 | 433MHz | 246 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 2022/09-2024/06 | 433MHz A0009058413 | 206 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 2014/03-2018/05 | 433MHz | W205 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 2014/09-2018/05 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 2018/06-2021/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 2021/06-2024/06 | 433MHz | 206 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 2007/01-2014/08 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CL Class | 2010/01-2015/12 | 433MHz | 216 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CL Class | 2000/01-2007/12 | 315MHz A0008223406 | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | CL Class | 2006/10-2010/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | CLA Class | 2019/05-2024/06 | 433MHz | 118 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CLA Class | 2012/12-2014/05 | 433MHz | 117 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLA Class | 2014/06-2019/04 | 433MHz | 117 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLA Class | 2019/05-2024/06 | 315MHz A0009054204 | 118 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | CLC Class | 2008/01-2018/06 | 433MHz | 216 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLE Class | 2022/01-2024/06 | 433MHz | 236 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | CLK Class | 2006/01-2011/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | CLK Class | 2002/01-2012/12 | 433MHz | 209 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 2018/01-2024/06 | 315MHz | 257 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 2018/01-2019/12 | 433MHz | C218 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 2011/01-2017/12 | 433MHz A0009050030 | 218 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 2006/01-2011/12 | 315MHz | 219 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | CLS Class | 2004/09-2011/12 | 433MHz A0025408017 | 219 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | CLS Class | 2018/01-2024/06 | 433MHz | 257 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 2009/07-2017/12 | 433MHz | 218 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Citan | 2012/01-2023/12 | 433MHz | 415 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 2023/10-2024/06 | 315MHz A0009058513 | 214 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | E Class | 2014/06-2018/12 | 433MHz | W212 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 2009/07-2014/05 | 433MHz | W212/C207 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 2005/06-2011/10 | 433MHz | W211 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | E Class | 1999/01-2005/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | E Class | 2023/10-2024/06 | 433MHz A0009058413 | 214 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 2006/01-2010/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | E Class | 2016/01-2023/12 | 315MHz | 213 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | E Class | 2016/01-2023/12 | 433MHz | W213/BR238 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | EQA | 2020/01-2024/06 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | EQA | 2020/01-2024/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQB | 2022/01-2024/06 | 315MHz | | ● | ● | ○ | O | 315MHz | Huf/Beru | ● | ● |
| Mercedes | EQB | 2021/01-2024/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQC | 2019/01-2024/06 | 433MHz | 293 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | EQC | 2019/01-2024/06 | 315MHz | 293 | ● | ● | ○ | O | 315MHz | Schrader | ● | ● |
| Mercedes | EQE | 2022/09-2024/06 | 315MHz A0009058513 | 295 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | EQE | 2022/01-2024/06 | 433MHz | 295 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQE | 2022/09-2024/06 | 433MHz A0009058413 | 295 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQE | 2022/01-2024/06 | 315MHz | 295 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | EQS | 2021/01-2024/06 | 315MHz | 297 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | EQS | 2022/09-2024/06 | 315MHz A0009058513 | 297 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | EQS | 2021/01-2024/06 | 433MHz | 297 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQS | 2022/09-2024/06 | 433MHz A0009058413 | 297 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 2018/06-2024/06 | 315MHz | 463 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | G Class | 2007/04-2018/05 | 433MHz | G463/461 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 2018/06-2024/06 | 433MHz | 463 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GL Class | 2006/01-2010/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | GL Class | 2006/04-2009/09 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | GL Class | 2009/06-2012/12 | 433MHz | X164 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GL Class | 2013/01-2019/06 | 433MHz | X166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLA Class | 2020/01-2024/06 | 433MHz | H247 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLA Class | 2013/12-2020/06 | 433MHz | X156 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLA Class | 2020/01-2024/06 | 315MHz A0009054204 | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | GLB Class | 2019/01-2024/06 | 433MHz | 247 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLB Class | 2019/01-2024/06 | 315MHz | 247 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | GLB Class | 2019/01-2019/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLC Class | 2015/01-2019/07 | 433MHz | X253 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 2016/09-2022/12 | 433MHz | C253 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 2022/01-2024/06 | 315MHz | 254 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 2022/09-2024/06 | 433MHz A0009058413 | 254 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 2022/06-2024/06 | 433MHz | 254 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 2022/09-2024/06 | 315MHz A0009058513 | 254 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 2018/01-2023/12 | 315MHz | W167 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | GLE Class | 2018/10-2023/12 | 433MHz | V167 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLE Class | 2019/01-2019/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | GLE Class | 2023/06-2024/06 | 315MHz A0009058513 | 236 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 2023/06-2024/06 | 433MHz A0009058413 | 236 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 2015/04-2019/11 | 433MHz | X166/C292 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLK Class | 2008/01-2015/09 | 433MHz | X204 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLS Class | 2020/01-2024/06 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | GLS Class | 2019/07-2024/06 | 433MHz | X167 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLS Class | 2015/01-2019/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLS Class | 2019/01-2019/12 | 433MHz 36106798872 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GT | 2014/01-2022/12 | 433MHz | GT | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | M Class | 2005/01-2011/05 | 433MHz | W164 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | M Class | 2005/01-2009/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | M Class | 2010/01-2014/12 | 433MHz | W166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | ML Class | 2011/06-2019/12 | 433MHz | W166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Marco Polo | 2014/01-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | R Class | 2010/01-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | R Class | 2006/01-2009/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | S Class | 2022/09-2024/06 | 315MHz A0009058513 | 223 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | S Class | 2018/01-2020/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 1999/07-2005/09 | 433MHz | W220 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | S Class | 2000/01-2006/12 | 315MHz A0008223406 | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | S Class | 2005/10-2009/05 | 433MHz | W221 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | S Class | 2009/06-2013/06 | 433MHz | W221 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 2005/12-2013/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | S Class | 2022/09-2024/06 | 433MHz A0009058413 | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 2022/01-2024/06 | 315MHz | 223 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | S Class | 2021/06-2024/06 | 433MHz | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 2013/07-2020/12 | 433MHz | W222/C217 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 2000/01-2005/04 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SL Class | 2005/05-2012/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | SL Class | 2005/05-2012/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | SL Class | 2021/09-2024/06 | 315MHz A0009058513 | 232 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | SL Class | 2021/09-2024/06 | 433MHz A0009058413 | 232 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 2021/09-2024/06 | 315MHz | 232 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | SL Class | 2021/09-2024/06 | 433MHz | 232 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 2000/01-2005/04 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | SL Class | 2012/07-2019/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLC Class | 2016/01-2020/06 | 433MHz | R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLK Class | 2004/01-2021/12 | 433MHz | R171, R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLR Class | 2008/01-2009/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | SLR Class | 2000/01-2007/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLR Class | 2008/01-2010/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|----------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | SLR McLaren | 2008/01-2009/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | SLR McLaren | 2004/01-2011/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLS Class | 2010/01-2019/06 | 433MHz | 197 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 2018/01-2024/06 | 433MHz A0009054104 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | Sprinter | 2018/01-2020/12 | 433MHz A0009050030 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 2010/01-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 2007/01-2014/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | Sprinter | 2006/06-2011/10 | 433MHz | W906 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | Sprinter Combi | 2011/11-2018/09 | 433MHz | 906 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | V Class | 2014/01-2024/06 | 433MHz | W447 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Valente | 2015/01-2023/12 | 433MHz | VS20 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Valente | 2003/01-2014/12 | 433MHz | 447 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | Viano | 2003/07-2014/05 | 433MHz A0025409517 | W639 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | Vito | 2003/05-2014/06 | 433MHz | W639 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | Vito | 2014/07-2024/06 | 433MHz | W447 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | X Class | 2017/01-2020/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Pacific | ● | ● |
| Mini | Clubman | 2015/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Clubman | 2014/07-2014/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubman | 2007/08-2016/12 | 433MHz 36236781847 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubman | 2007/01-2013/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Clubvan | 2012/07-2015/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Convertible | 2015/01-2023/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Convertible | 2014/07-2015/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Convertible | 2009/01-2014/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 2014/07-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 2009/01-2014/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 2015/07-2024/06 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Coupe | 2014/07-2015/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Coupe | 2011/07-2014/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Mini | 2006/03-2024/06 | 433MHz Continental | F55/F56/R56 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Mini | 2014/01-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Mini | 2009/01-2015/12 | 433MHz OYGTSSRE4D | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Paceman | 2014/07-2018/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Paceman | 2009/01-2014/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Roadster | 2011/01-2014/12 | 433MHz 36106856227 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Roadster | 2014/05-2015/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mitsubishi | ASX | 2022/01-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | ASX | 2013/04-2019/02 | 315MHz 4250B668 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | ASX | 2013/04-2019/02 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mitsubishi | ASX | 2014/01-2021/12 | 433MHz | GA0 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | ASX | 2019/03-2023/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | ASX | 2013/07-2023/12 | 315MHz 4250D585 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross | 2021/11-2023/12 | 315MHz 4250G326 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross | 2022/06-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross | 2017/01-2023/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross PHEV | 2023/04-2024/06 | 433MHz 4250G325 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Express | 2020/01-2021/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Orange | ● | ● |
| Mitsubishi | L200 | 2014/08-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Lancer | 2014/01-2022/12 | 433MHz | CY0 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Lancer | 2006/12-2020/12 | 315MHz 4250B975 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Lancer | 2006/12-2020/12 | 315MHz 4250B668 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Lancer Sportback | 2014/01-2020/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 2013/07-2023/12 | 315MHz 4250D585 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 2013/01-2023/12 | 433MHz | A00 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 2013/01-2022/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 2021/08-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 2021/04-2023/12 | 315MHz 4250G326 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 2021/02-2023/12 | 315MHz 4250G122 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 2014/01-2022/12 | 433MHz | CWO/GFO | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 2006/12-2022/12 | 315MHz 4250B975 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 2006/12-2022/12 | 315MHz 4250B668 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 2017/05-2021/03 | 315MHz 4250D585 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 2018/03-2021/12 | 433MHz 4250C275 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 2019/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mitsubishi | Outlander PHEV | 2019/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mitsubishi | Pajero | 2014/01-2015/12 | 315MHz 4250B668 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Pajero | 2014/01-2015/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Pajero | 2016/01-2019/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Pajero | 2014/01-2022/12 | 433MHz | V80 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Pajero Sport | 2014/03-2022/10 | 433MHz | V80 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Pajero Sport | 2014/01-2015/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Pajero Sport | 2014/01-2015/12 | 315MHz 4250B668 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Pajero Sport | 2016/01-2019/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Pajero Sport | 2022/11-2024/06 | 433MHz 4250G325 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Strada | 2014/08-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|---------|-----------------|----------------------|--------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mitsubishi | Triton | 2014/08-2023/12 | 433MHz 4250C275 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Triton | 2014/03-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Triton | 2015/01-2019/12 | 315MHz 4250B668 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Triton | 2015/01-2019/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | i-MiEV | 2010/01-2019/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| NIO | EC7 | 2022/12-2024/06 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Nissan | 350Z | 2007/01-2010/12 | 315MHz 40700JA00C | Z33 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | 350Z | 2007/01-2010/12 | 315MHz 40700JA01C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | 350Z | 2002/06-2006/12 | 315MHz | Z33 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | 350Z | 2007/01-2010/12 | 315MHz | Z33 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | 370Z | 2018/01-2019/12 | 433MHz 407003VU0A | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | 370Z | 2021/08-2022/09 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | 370Z | 2013/07-2021/06 | 433MHz 407006WY0B | RC53D(2)/Z34 | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Nissan | 370Z | 2009/01-2020/06 | 315MHz | Z34 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | 370Z | 2008/10-2010/03 | 315MHz 40700JK00C | Z34 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | 370Z | 2014/03-2019/12 | 433MHz 40700JY00B | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Nissan | Almera | 2013/01-2023/12 | 433MHz | LB1A/G11/B10 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Altima | 2012/05-2019/09 | 433MHz 407003JA0B | L33 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Altima | 2014/03-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Ariya | 2022/01-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Cube | 2011/01-2019/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Elgrand | 2010/01-2024/06 | 315MHz | E52 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | GT-R | 2020/05-2022/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | GT-R | 2016/01-2021/12 | 433MHz 407003VU0A | D52E | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | GT-R | 2014/03-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | GT-R | 2013/11-2022/08 | 433MHz 4070062B0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | GT-R | 2011/06-2023/12 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | GT-R | 2009/09-2010/10 | 315MHz 40700JA00C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | GT-R | 2008/12-2009/08 | 315MHz 40700JA01C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | GT-R | 2022/09-2024/06 | 315MHz 407006GP0A | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | GT-R | 2007/09-2013/12 | 433MHz | R35 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | GT-R | 2007/01-2022/12 | 315MHz | R35 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | GT-R | 2022/09-2023/12 | 433MHz 407006GP1A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Juke | 2020/01-2024/06 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|------------|-----------------|----------------------|---------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Juke | 2010/01-2017/12 | 315MHz 407001AA0C | F15 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Juke | 2010/01-2020/12 | 315MHz 407001LA0E | F15 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Juke | 2010/01-2022/12 | 433MHz | F15/P12C | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Juke | 2012/07-2015/07 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Juke | 2014/03-2019/12 | 433MHz 407005ZH0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Leaf | 2022/04-2024/06 | 433MHz | ZE1 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 2015/01-2019/12 | 433MHz 407003AR1A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 2017/01-2023/12 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 2010/01-2012/12 | 315MHz | ZE0 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Leaf | 2013/01-2019/12 | 315MHz | ZE0 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Leaf | 2010/10-2019/12 | 433MHz | ZE0/B12G | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Leaf | 2004/03-2010/10 | 433MHz | ZE0/B12G | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Maxima | 2012/08-2015/03 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Maxima | 2012/01-2014/12 | 315MHz | A35 | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Maxima | 2008/05-2010/08 | 315MHz 40700JA01B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Maxima | 2007/01-2012/12 | 315MHz 407001AA0B | A35 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Maxima | 2007/01-2007/12 | 315MHz Alloy | A34 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Maxima | 2003/01-2006/12 | 315MHz | A34 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Micra | 2010/03-2019/12 | 433MHz | B02A/K13 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Murano | 2014/06-2021/06 | 433MHz | Z51/Z52/P42 M | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Murano | 2008/01-2015/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Murano | 2004/01-2014/09 | 433MHz | Z51/P42D | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Navara | 2017/01-2024/06 | 433MHz | Y62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Navara | 2016/06-2021/12 | 433MHz 40700EZ00A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Navara | 2004/10-2016/12 | 433MHz | D22/D23/D40 /H61B/H60A | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Note | 2013/01-2020/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 2021/01-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 2015/11-2021/05 | 433MHz | R52/P61B | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 2013/01-2015/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 2010/09-2012/08 | 315MHz 407001AA0D | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 2012/01-2012/12 | 315MHz 407003AN0B | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Pathfinder | 2007/01-2013/12 | 315MHz | R51 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 2004/01-2006/12 | 315MHz | R51 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 2006/09-2010/08 | 315MHz 40700JA01B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 2008/05-2009/05 | 315MHz 40700JA02B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|------------|-----------------|----------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Pathfinder | 2019/01-2021/12 | 433MHz 407009DJ0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Patrol | 2019/01-2021/12 | 433MHz | T62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Patrol | 2008/01-2016/08 | 433MHz | Y61 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Patrol | 2010/01-2020/06 | 315MHz | E52 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Patrol | 2014/03-2020/12 | 433MHz | Y62 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Patrol | 2017/05-2021/08 | 315MHz 407005UV0A | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Primera | 2002/01-2007/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Pulsar | 2014/01-2019/12 | 433MHz | C13M/C13/B1 2L | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pulsar | 2016/01-2018/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pulsar | 2014/01-2019/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Qashqai | 2019/06-2021/12 | 433MHz | J10/J11/P32 S | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 2019/06-2022/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 2021/01-2024/06 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 2018/06-2019/05 | 433MHz | J10/J11/P32 S | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 2016/01-2019/05 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 2014/01-2018/05 | 433MHz | J10/J11/P32 S | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 2013/01-2013/12 | 433MHz | J10/J11/P32 S | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 2021/01-2024/06 | 433MHz 40700E1B6A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sunny | 2020/01-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Titan | 2017/01-2024/06 | 433MHz 40700EZ00A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | X-Trail | 2022/01-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Trail | 2013/01-2019/12 | 433MHz | T32/P32R | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Trail | 2016/09-2021/12 | 433MHz | T32 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Trail | 2021/01-2021/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Z | 2022/01-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Z | 2022/06-2023/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Z | 2022/09-2023/12 | 433MHz 407006GP1A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Opel/Vauxhall | Astra J | 2011/10-2014/05 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 2006/05-2014/05 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 2014/06-2014/11 | 433MHz | GM S4400 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 2020/01-2024/06 | Indirect | F/Mk5 | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Grandland | 2017/01-2024/06 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Insignia | 2008/01-2014/04 | 433MHz | GM G3700 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira | 2011/07-2015/01 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 1007 | 2004/01-2011/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 107 | 2005/03-2014/07 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 108 | 2014/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 2008 | 2013/02-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 207 | 2005/11-2013/09 | 433MHz | A7 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Peugeot | 207 | 2013/10-2016/12 | 433MHz | A7 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 208 | 2012/01-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 3008 | 2008/11-2013/08 | 433MHz | T84 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 3008 | 2013/09-2019/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Peugeot | 3008 | 2016/06-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 307 | 2001/01-2007/02 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 307 | 2007/03-2008/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 308 | 2020/01-2024/06 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | 308 | 2013/06-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 308 | 2007/05-2013/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 4008 | 2012/04-2018/01 | 433MHz | | ● | ● | ○ | S | 433MHz | Continental | ● | ● |
| Peugeot | 407 | 2003/01-2012/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 408 | 2012/07-2019/03 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 5008 | 2013/09-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 5008 | 2017/01-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 5008 | 2009/09-2013/08 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 508 | 2017/07-2024/06 | Indirect | R83 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 508 | 2013/10-2022/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Peugeot | 508 | 2010/09-2013/09 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 607 | 2004/10-2012/12 | 433MHz | Z8 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 607 | 1999/09-2004/09 | 433MHz | 6042/Z8 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 807 | 2004/10-2016/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 807 | 2002/02-2004/09 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Boxer | 2013/12-2022/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Peugeot | Boxer | 2006/02-2013/11 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Boxer | 2006/01-2013/11 | 433MHz 1612474480 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Expert | 2006/10-2013/12 | 433MHz | G9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Expert | 2016/03-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Expert | 2014/01-2016/02 | 433MHz | G9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Partner | 2018/07-2024/06 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | Partner | 2014/06-2018/06 | 433MHz | B9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Partner | 2008/01-2014/05 | 433MHz | B9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | RCZ | 2013/10-2017/06 | 433MHz | T75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | RCZ | 2009/12-2013/09 | 433MHz | T75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Porsche | 718 (982) | 2016/01-2024/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 2010/01-2016/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (991) | 2017/01-2020/12 | 433MHz | 991 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (991) | 2011/01-2016/12 | 433MHz | 991 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (992) | 2017/01-2024/06 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (997) | 2004/01-2008/06 | 433MHz OYGTSSRE4B | 997 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (997) | 2008/04-2015/08 | 433MHz | 997 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 918 Spyder | 2013/01-2015/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 960 | 2015/09-2019/06 | 433MHz | 714 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 2009/01-2013/12 | 433MHz | 987 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 2004/01-2008/12 | 433MHz | 987 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|----------------------|-----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Porsche | Boxster | 2012/01-2016/12 | 433MHz | 981 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Carrera GT | 2003/01-2011/12 | 433MHz | GT | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 2011/01-2014/07 | 433MHz | 92A | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 2014/11-2017/08 | 433MHz | 92A | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 2017/09-2023/12 | 433MHz | 9YA | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 2006/12-2010/12 | 433MHz | 9PA | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 2002/01-2006/12 | 433MHz | 9PA | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 2010/01-2014/05 | 433MHz | 4. 8L | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 2013/04-2016/12 | 433MHz | 981 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 2016/10-2024/12 | 433MHz | 982/982C/CT 4-2 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 2014/01-2023/12 | 433MHz | P0416/95B | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Mission E | 2019/01-2020/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 2009/01-2014/02 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 2017/09-2023/12 | 433MHz | 970/971 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 2013/09-2017/08 | 433MHz | 970 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 2019/01-2023/12 | 433MHz 9J1907275 | | ● | ● | ○ | 0 | 433MHz | Huf/Beru | ● | ● |
| Renault | AUSTRAL | 2023/01-2024/06 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Alaskan | 2018/01-2019/12 | 433MHz | U60A | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Alaskan Pickup | 2016/11-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Alpine A110 | 2021/01-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Captur | 2013/01-2019/12 | 433MHz | J87 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Captur | 2022/03-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Clio III | 2004/04-2014/05 | 433MHz | X85 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Clio IV | 2014/06-2019/12 | 433MHz | X85/X98 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Clio IV | 2016/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Fluence | 2009/01-2021/06 | 433MHz | L38 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Fluence | 2015/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Kadjar | 2015/01-2023/12 | 433MHz 407004CB0A | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Renault | Kadjar | 2021/05-2023/12 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Kangoo | 2022/02-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Kangoo | 2007/10-2022/01 | 433MHz | X61 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Koleos | 2016/08-2024/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Renault | Koleos | 2017/01-2023/12 | 433MHz 407004CB0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Koleos | 2016/01-2019/12 | 433MHz 407001628R | H45 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Koleos | 2013/01-2016/07 | 433MHz 407003VU0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Koleos | 2008/02-2015/12 | 433MHz 407001628R | H45 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Laguna II | 2000/12-2010/03 | 433MHz | X74 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Laguna III | 2007/01-2016/12 | 433MHz | X91 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Latitude | 2016/01-2019/12 | 433MHz | L43 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Latitude | 2010/09-2015/12 | 433MHz | L43 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Master | 2009/11-2022/12 | 433MHz | X62 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|------------------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Renault | Megane | 2020/01-2024/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane I | 1997/01-2005/03 | 433MHz | B32/X95/X64 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Megane II | 2002/01-2009/12 | 433MHz | B32/X84 | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane III | 2008/10-2019/12 | 433MHz | X95 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane IV | 2016/01-2023/12 | 433MHz 407004CB0A | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Renault | Scenic II | 2003/01-2009/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Scenic III | 2009/01-2015/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Trafic | 2014/01-2021/12 | 433MHz | X82 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Trafic | 2022/03-2024/06 | 433MHz 407004CB0B | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Zoe | 2012/09-2019/06 | 433MHz | X10 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Zoe | 2019/07-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Zoe | 2021/01-2023/12 | 433MHz 407006UA0A | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Rivian | EDV | 2022/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| Rivian | R1S | 2022/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| Rivian | R1T | 2022/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| Rolls Royce | Cullinan | 2018/01-2024/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Dawn | 2016/01-2023/12 | 433MHz | RR6 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 2011/01-2019/12 | 433MHz | RR04 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 2020/01-2024/06 | 433MHz 36106877937 | RR21 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 2020/08-2024/06 | 433MHz 36106887147 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Phantom | 2007/01-2022/12 | 433MHz 36106798872 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 2017/01-2024/06 | 433MHz MRXAG5SP4 | RR11/RR02 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Phantom | 2012/01-2017/12 | 433MHz | RR01 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 2003/02-2018/12 | 433MHz OYGTSSRE4TC | RR01 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom Drophead Coupe | 2007/01-2018/12 | 433MHz | RR02 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Spectre | 2023/08-2024/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Spectre | 2023/08-2024/06 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 2013/01-2022/12 | 433MHz | RR5 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 2013/05-2023/12 | 433MHz 36106874830 | RR5 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Saab | 9-3 | 2006/10-2009/05 | 433MHz | YS3F | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 2003/01-2006/09 | 433MHz | YS3F | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 2013/01-2015/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 2009/06-2012/12 | 433MHz | YS3F | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3X | 2007/07-2014/04 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-4X | 2011/01-2014/06 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 2009/10-2013/12 | 433MHz | YS3G | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 2006/11-2009/09 | 433MHz | YE3E | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 2002/07-2006/10 | 433MHz | YE3E | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-7X | 2007/01-2011/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|--------------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Seat | Arona | 2017/03-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Ateca | 2016/09-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Ibiza | 2010/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Leon | 2010/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Tarraco | 2018/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Fabia | 2015/01-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Fabia | 2013/10-2014/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Fabia | 2013/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Karoq | 2017/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Kodiaq | 2016/11-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Kodiaq | 2016/01-2023/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Octavia | 2015/01-2023/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Octavia | 2013/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Octavia | 2012/10-2014/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Praktik | 2013/01-2015/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Rapid | 2012/01-2016/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Rapid | 2017/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Rapid | 2012/01-2015/04 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Rapid | 2015/05-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Roomster | 2013/01-2020/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Roomster | 2006/01-2018/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Scala | 2019/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Superb | 2017/01-2023/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Superb | 2013/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Superb | 2008/03-2015/04 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Yeti | 2014/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Yeti | 2009/06-2018/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Smart | Forfour | 2005/01-2023/12 | 433MHz | A453 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | Fortwo | 2014/03-2023/12 | 433MHz | A453 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | Fortwo | 2007/01-2019/12 | 433MHz | A451 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Ssangyong | Actyon | 2018/07-2019/12 | 433MHz Q200 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Actyon | 2012/08-2021/12 | 433MHz QJ | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Actyon Sport | 2012/10-2019/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Chairman | 2014/01-2019/12 | 433MHz 4199034000 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Korando | 2019/05-2024/06 | 433MHz 4199037000 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Korando | 2018/01-2023/12 | 433MHz C300 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Korando | 2010/11-2023/12 | 433MHz C200 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | LUVi | 2015/01-2019/12 | 433MHz X100 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Musso | 2023/01-2024/06 | 433MHz 4199036100 | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Ssangyong | Musso | 2018/06-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Musso | 2016/01-2018/05 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Nomad | 2013/07-2019/10 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Rexton | 2017/03-2023/12 | 433MHz Y400 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Rexton | 2012/07-2017/12 | 433MHz Y300 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|--------------|-----------------|----------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ssangyong | Rodius | 2005/05-2021/12 | 433MHz AJ | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Stavic | 2014/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Tivoli | 2015/01-2020/06 | 433MHz X100 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Tivoli | 2016/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Turismo | 2014/01-2022/12 | 433MHz AJ | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Subaru | BRZ | 2011/11-2020/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Subaru | BRZ | 2014/01-2021/06 | 433MHz ZC | ZC | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Subaru | Crosstrek | 2023/01-2024/06 | 433MHz | HR3 | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Forester | 2014/01-2017/12 | 433MHz | FM5/PF3 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Forester | 2018/01-2024/06 | 433MHz | FM5/PF3 | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Impreza | 2016/09-2024/06 | 433MHz | HR3 | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Impreza | 2013/07-2022/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Impreza | 2014/01-2017/09 | 433MHz | 55A/MF1/ZR1 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Legacy | 2018/01-2019/12 | 433MHz | EZ5 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Legacy | 2014/01-2017/12 | 433MHz | EZ5 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Levorg | 2021/03-2022/12 | 433MHz | VN | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Levorg | 2015/01-2021/06 | 433MHz VM | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Libery | 2014/01-2017/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Libery | 2018/01-2021/12 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Outback | 2018/01-2019/12 | 433MHz | EZ5 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Outback | 2018/01-2024/06 | 433MHz | BS/BT | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Outback | 2014/01-2017/12 | 433MHz | EZ5 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Solterra | 2023/01-2024/06 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Subaru | Solterra | 2022/06-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Subaru | Tribeca | 2017/01-2020/12 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | WRX | 2014/01-2018/12 | 433MHz XK | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | WRX | 2022/01-2023/12 | 433MHz MRXSHR3 | | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | WRX | 2019/01-2021/12 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | XV | 2012/01-2017/12 | 433MHz | MF1 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | XV | 2018/01-2023/12 | 433MHz | GT | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | XV | 2018/01-2019/12 | 433MHz | HR3 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Suzuki | APV | 2014/06-2024/06 | 433MHz | YC5/YRA | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Suzuki | Across | 2020/01-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Suzuki | Alto | 2014/01-2015/06 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Suzuki | Alto | 2014/06-2017/12 | 433MHz | YC5 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Baleno | 2016/01-2024/06 | 433MHz | YR | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Celerio | 2014/01-2024/06 | 433MHz | YLA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Celerio | 2014/01-2024/06 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Suzuki | Grand Vitara | 2005/01-2014/12 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Suzuki | Grand Vitara | 2014/01-2024/06 | 433MHz | YT4 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Ignis | 2016/01-2021/01 | 433MHz | YJ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Ignis | 2021/02-2024/06 | 433MHz | MF | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Jimny | 2021/02-2024/06 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Continental | ● | ● |
| Suzuki | Jimny | 2014/01-2021/01 | 433MHz | YR7/YW5 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Kizashi | 2009/01-2019/12 | 433MHz | YW1 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-----------------|-----------------|-------------------------|-----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Suzuki | Kizashi | 2009/01-2019/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Suzuki | S-Cross | 2013/01-2021/08 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | S-Cross | 2021/09-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | SX4 | 2006/01-2014/12 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Suzuki | SX4 | 2013/01-2023/12 | 433MHz | YY1, YY3 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | SX4 S-Cross | 2021/09-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | SX4 S-Cross | 2013/01-2021/08 | 433MHz | YAA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Splash | 2013/09-2019/12 | 433MHz | YV1/YV4/ YV5 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Swift | 2021/02-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Swift | 2013/08-2021/01 | 433MHz | YP6/YP7/YS | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Swift Sport | 2017/01-2020/01 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Swift Sport | 2020/02-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Vitara | 2021/02-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Vitara | 2013/09-2021/01 | 433MHz | YFA/YG4/ YH4 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Tata | Xenon XT | 2016/01-2021/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Tesla | Model 3 | 2016/01-2020/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model 3 | 2018/01-2021/12 | 433MHz (10748 1200B) | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 2012/01-2014/09 | 433MHz | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |
| Tesla | Model S | 2014/09-2020/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 2021/01-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 2023/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model X | 2014/10-2023/12 | 433MHz Continental | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model X | 2016/01-2019/12 | 433MHz Baolong | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |
| Tesla | Roadster | 2008/01-2010/12 | 433MHz Huf | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Tesla | Roadster | 2010/01-2012/12 | 433MHz Baolong | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |
| Toyota | 86 | 2012/04-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Aurion (H_Line) | 2014/01-2020/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Aurion (L_Line) | 2016/05-2021/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Avalon | 2018/06-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Avensis | 2008/10-2019/12 | 433MHz C210 | 312N/445L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | C-HR | 2016/01-2024/06 | 433MHz | 560A | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | C-HR | 2018/02-2021/05 | 433MHz E100 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | C-HR | 2017/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 2016/05-2021/01 | 433MHz C210 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 2018/08-2021/01 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 2016/10-2021/01 | 433MHz 60010 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 2016/01-2024/06 | 433MHz C215 | 045L | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 2006/01-2011/09 | 315MHz Japan/USA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 2014/01-2021/12 | 433MHz C210 | 045L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Camry Hybrid | 2014/01-2017/09 | 433MHz | XV50/XV70 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Coaster | 2008/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------------|-----------------|----------------|-------------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | Corolla | 2013/01-2021/12 | 433MHz C210 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Corolla | 2019/01-2024/06 | 433MHz C215 | 740A | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | Corolla | 2019/04-2024/06 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla | 2019/08-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Corolla | 2016/10-2019/03 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Corolla | 2019/01-2021/01 | 433MHz E100 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Corolla | 2017/01-2017/08 | 433MHz Pacific | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Corolla Cross | 2019/01-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | FJ Cruiser | 2016/08-2021/01 | 433MHz 30071 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | FJ Cruiser | 2014/06-2023/12 | 433MHz | 155L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Fortuner | 2016/08-2021/01 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Fortuner | 2005/12-2023/12 | 433MHz | 669L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | GR Supra | 2019/01-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Huf/Beru | ● | ● |
| Toyota | Granvia | 2019/01-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Hiace | 2004/08-2022/12 | 433MHz | 550N | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Highlander | 2014/01-2019/11 | 433MHz | 397L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Hilux | 2015/01-2022/12 | 433MHz | 669L/640A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Innova | 2015/11-2021/01 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Kluger | 2020/01-2022/10 | 433MHz | XU70 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Kluger | 2016/11-2019/11 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Kluger | 2007/01-2011/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 2014/01-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 2005/01-2013/08 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 2017/01-2021/01 | 433MHz C215 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 2015/10-2023/12 | 433MHz | 215L/611L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 2013/08-2021/01 | 433MHz C210 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 2009/01-2017/08 | 433MHz | 611L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 2017/09-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 2016/08-2017/08 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 2013/08-2017/08 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Previa | 2016/05-2020/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Previa | 2007/01-2020/12 | 433MHz | 085X/085L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius | 2019/01-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius | 2014/05-2019/12 | 433MHz | 590L/030A/XW30/XW50/690A/277N | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius | 2003/08-2012/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius C | 2015/11-2021/01 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius C | 2014/03-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 2018/01-2024/06 | 433MHz | XA50 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 2012/01-2023/12 | 433MHz | 410A/XA40/120L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 2005/11-2011/12 | 433MHz | 120L/XA30 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|---------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | Rukus | 2014/01-2019/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tarago | 2016/05-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Tarago | 2016/05-2020/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Urban Cruiser | 2007/06-2020/12 | 433MHz | 260L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Vellfire | 2020/01-2021/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris | 2016/07-2021/01 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris | 2011/01-2023/12 | 433MHz C210 | 020L/850L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris Cross | 2021/07-2023/12 | 433MHz | XPB1F | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | bZ4X | 2022/03-2024/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Volkswagen | Amarok | 2014/03-2023/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Arteon | 2017/01-2023/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | CC | 2018/01-2023/06 | 433MHz MQB | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | CC | 2011/06-2020/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Caddy | 2020/11-2023/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Caddy | 2014/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | California | 2019/11-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volkswagen | Caravelle | 2019/11-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Caravelle | 2015/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Crafter | 2018/03-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Volkswagen | Crafter | 2014/07-2018/02 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Crafter | 2006/04-2014/06 | 433MHz | VN830 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Crafter | 2006/01-2016/12 | 433MHz Continental | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | EOS | 2014/01-2015/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Golf | 2012/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Golf | 2009/01-2023/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Jetta | 2013/01-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Multivan | 2015/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Multivan | 2004/03-2015/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Multivan | 2019/10-2024/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volkswagen | New Beetle | 2011/08-2020/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 2014/09-2023/12 | 433MHz | B8 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 2012/01-2021/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Passat | 2010/01-2015/12 | 433MHz | B6/VW471 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 2005/01-2011/12 | 433MHz | VW451 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volkswagen | Passat CC | 2014/09-2019/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat CC | 2008/03-2016/12 | 433MHz 3AA907275 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 2010/06-2019/12 | 433MHz | Vh67 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 2001/12-2007/05 | 433MHz | VW611 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Polo | 2009/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Polo | 2017/09-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Santana | 2014/09-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Scirocco | 2008/06-2018/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Scirocco | 2008/01-2019/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | T-ROC | 2017/11-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | T5 | 2014/03-2019/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volkswagen | Tiguan | 2012/01-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 2016/01-2023/12 | 433MHz | VW376/5N2 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 2007/01-2011/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 2014/08-2023/12 | 433MHz | 7P5/7P6108 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 2012/01-2014/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 2002/02-2007/12 | 433MHz | 7L | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touran | 2015/01-2023/12 | 433MHz | VW378 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Transporter | 2015/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Transporter | 2014/03-2023/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Up! | 2011/08-2018/12 | 433MHz | VW120 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volvo | C30 | 2006/01-2014/03 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C30 | 2006/01-2010/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C30 | 2011/01-2014/03 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C30 Electric | 2011/01-2013/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C40 | 2022/01-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | C70 | 2008/01-2010/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 2006/01-2014/12 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 2006/01-2007/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 2011/01-2014/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | EX30 | 2023/06-2024/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Volvo | S40 | 2011/01-2014/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S40 | 2003/01-2014/12 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S40 | 2003/01-2010/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 2019/01-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S60 | 2019/04-2023/12 | 433MHz 31362304 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | S60 | 2010/01-2020/12 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 2010/01-2019/12 | 433MHz 31302096 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 2001/01-2010/12 | 315MHz 31200923 | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Volvo | S60 | 2000/07-2010/02 | 433MHz 31329981 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volvo | S80 | 2013/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S80 | 2010/01-2016/12 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 2007/01-2009/12 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 2006/01-2017/01 | 433MHz 31341893 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 1999/01-2007/12 | 315MHz 31200923 | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Volvo | S90 | 2016/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S90 | 2016/05-2023/12 | 433MHz 31362304 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | V40 | 2015/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volvo | V40 | 2012/01-2021/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V40 Cross Country | 2012/01-2017/12 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 2016/01-2018/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V50 | 2011/01-2016/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 2004/01-2014/12 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 2003/01-2010/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 | 2011/01-2019/12 | 433MHz 31341893 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 | 2019/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V60 | 2017/11-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | V60 | 2008/01-2014/06 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 Cross Country | 2015/01-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V70 | 2007/01-2016/12 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V90 | 2016/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V90 | 2015/01-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC40 | 2017/01-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC40 | 2018/01-2019/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC60 | 2017/01-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 2008/01-2017/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 2010/01-2014/06 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 2008/01-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 2008/01-2009/12 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC90 | 2016/01-2024/06 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC90 | 2015/01-2022/12 | 433MHz 31362304 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 | 2003/01-2016/12 | 315MHz 31200923 | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Volvo | XC90 | 2002/01-2018/05 | 433MHz 31329981 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |